GOLDEN LEAF AUTOMOTIVE

INVOICE 62897

GOLDEN LEAF AUTOMOTIVE

170 ZENWAY BLVD UNIT#2 WOODBRIDGE, ONTARIO L4H 2Y7 TELEPHONE 905/850-3433

BILL TO: COUNTER SALES UNUSED PART EXCHANGE/RETURN WITHIN 30 DAYS W/ORIGINAL INV.

TELEPHONE: / -

INVOICE DATE 2017-08-25

PAGE: 1

SHIP TO: DONNA LEWIS 78 VICTORIA ST SAINT JOHN NB E2K-1L4 506-663-8740,

*** INVOICE ***

| CUSTOMER | | SHIP VIA | | F.O.B | TERMS | PO NUMBER | SALES | DATE | OUR ORDER # |
|----------|------|----------|---------------------------------------|----------|--|-----------|-----------|------------|-------------|
| CSALE | | BEST | | ORIGIN | PREPAID | E-MAIL | M | 2017-08-24 | 51067 |
| ORDER | SHIP | | B.O. | ITEM | THEM DESCRIPTION | | PRICE | EVE PRICE | |
| ORDER | | | | MAKE | ITEM DESCRIPTION | | | DIS% | EXT.PRICE |
| 1 | 1 | | 0 | 1039W | FRONT INNER FENDER RH 67-68 | | \$ 155.00 | \$ 155.00 | |
| 1 | 1 | | U | CAMARO | FROIT INNER FEIDER KH 07-08 | | 0 % | \$ 133.00 | |
| 1 | 1 | | 0 | 1039X | FRONT INNER FENDER LH 67-68 | | | \$ 155.00 | \$ 155.00 |
| | | | | CAMARO | TROWT INVERTEDER EIT 07-00 | | 0 % | φ 133.00 | |
| 1 | 1 | | 0 | 1039K | FENDER LH 67 STD W / EXT | | \$ 332.00 | \$ 332.00 | |
| | 1 | | | CAMARO | LINDER EITOV STD W / EXT | | | 0 % | ψ 332.00 |
| 1 | 1 | | 0 | 1039J | FENDER RH 67 STD W / EXT | | \$ 332.00 | \$ 332.00 | |
| | | | Ů | CAMARO | | | 0 % | Ψ 332.00 | |
| 1 | 1 | | 0 | 1004 | 67-69 ROOF PANEL | | \$ 309.00 | \$ 309.00 | |
| | | | | CAMARO | | | 0 % | ψ 307.00 | |
| 1 | 1 | l | 0 | 1004A | 67-68 ROOF BRACE KITS14 PCS | | \$ 329.00 | \$ 329.00 | |
| | | | , , , , , , , , , , , , , , , , , , , | CAMARO | | | 0 % | \$ 527.00 | |
| 2 | 2 | | 0 | M1037A | DOOR WINDOW HANDLE BLACK67-81 CAMARO,67-76 CHEVY PU | | \$ 10.00 | \$ 20.00 | |
| | | | | CAMARO | | | 0 % | | |
| 1 | 1 | | 0 | 1104C | ROCKER PANEL RH 67-72 | | \$ 32.00 | \$ 32.00 | |
| | | | | CHEVY PU | | | 0 % | | |
| 1 | 1 | | 0 | M1273 | EYEBROW MOLDING LH 67-68 GMC | | \$ 37.00 | \$ 37.00 | |
| | - | | | CHEVY PU | | | 0 % | \$ 57.00 | |
| 2 | 2 | | 0 | 1151A | 47-72 ROUND CHROME 5" RIBBED MIRROR | | \$ 20.00 | \$ 40.00 | |
| | | | | CHEVY PU | | | 0 % | Ψ 10.00 | |
| 1 | 1 | L | 0 | 1153P | 67-72 EXTERIOR MIRROR ARM RHSTAINLESS | | \$ 44.00 | \$ 44.00 | |
| | | | | CHEVY PU | | | 0 % | \$. 1.00 | |
| 1 | 1 | | 0 | 1153M | 67-72 EXTERIOR MIRROR ARM LHSTAINLESS | | \$ 44.00 | \$ 44.00 | |
| | | | | CHEVY PU | | | 0 % | | |
| | | | | | | | | | CONTINUE |