| VENDOR | SHIP DATE  | SHIP VIA | F.O.B | ONSHIP ETA |
|--------|------------|----------|-------|------------|
| DII    | 2017-10-11 | CEVA     | ORGIN | 2017-10-12 |

## **CONTAINER 71011 DETAILS**

| PO# ITEM | ITEM                | DESCRIPTION                           | VPART NO.     | SHIP QTY     | LOCATION   | FOB      | EXT<br>COST |
|----------|---------------------|---------------------------------------|---------------|--------------|--|----------|-------------|
|          | II ENI              | DESCRIPTION                           | MAKE          |              |  |          |             |
| 3309     | 3309 <b>1000B</b>   | 67-69 CONVT. TOP BOLT &               |               | 1            | C52  | \$16.35  | \$16.37     |
| 3307     |                     | PIVOT KIT68-72 CHEVELLE               | CAMARO        | 1            |  |          |             |
|          | 3309 <b>1000C</b>   | 67-69ANTENNA MAST*FIXED               |               | 1            | B74  | \$7.56   | \$7.63      |
| 3309     |                     | WHIP STYLE** REPLACEMENT - MAST ONLY* | CAMARO        |              |  |          |             |
|          |                     |                                       | - Critin into | +            |  |          |             |
| 3314     | <b>1006M</b>        | 77-81 FRONT DISC BRAKE<br>BRACKET PR  | CAMARO        | 2            | D83  | \$41.86  | \$41.86     |
|          |                     |                                       | CAMARO        |              | <del>                                     </del> |          |             |
| 3309     | 1039W               | FRONT INNER FENDER RH 67-68           | CAMARO        | 8            | J171   | \$372.80 | \$471.12    |
| 3311     | 3311 <b>1041HC</b>  | 75-81 OUTER WHEELHOUSE                |               | 1            | G157   | \$50.83  | \$55.48     |
| 3311     |                     | LHFIREBIRD / TRANS AM                 | FIREBIRD      |              |  |          |             |
| 3288     | 1041J               | WHEELHOUSE OUTER LH 70-81             | CAMARO        | <b>-</b>   1 | G147   | \$27.72  | \$34.21     |
|          | 3311 <b>1041J</b> C | 75-81 OUTER WHEELHOUSE                | CAMARO        | 1            | G157   | \$50.79  | \$55.47     |
| 3311     |                     | RHFIREBIRD / TRANS AM                 | FIREBIRD      |              |  |          |             |
|          |                     | 67-76 HEATER BLOWER                   | TINEBINE      | 3            | A143   | \$66.54  | \$67.14     |
| 3311     | 3311 <b>1041W</b>   | MOTORW / O AC NOVA 64-74,             |               |              |  |          |             |
|          |                     | CHEVELLE 64-72                        | CAMARO        |              |  |          |             |
| 2216     | 3316 <b>1047B</b>   | FRONT APRON 68 RS                     | 3938601       | 2            | C23  | \$51.90  | \$62.20     |
| 3310     |                     | FRONT APRON 08 KS                     | CAMARO        |              |  |          |             |
| 2211     | 3311 <b>1047L</b>   | RADIATOR SUPPORT 67-                  |               | 10           | C14  | \$512.10 | \$565.10    |
| 3311     |                     | 69CAMARO AND FIREBIRD                 | CAMARO        |              |  |          |             |
| 3316     | 1048N               | FRONT BUMPER OUTER                    |               | 2            | G132   | \$12.70  | \$12.28     |
| 3310     | 3310 <b>1040</b> 1  | BRACKET LH 67                         | CAMARO        |              | 0132   | ψ12.70   | Ψ12.20      |
| 3302     | 3302 <b>1048QB</b>  | 69 FRONT BUMPER BRACKET<br>4PCS SET   |               | 3            | A55  | \$135.00 | \$151.26    |
|          | 10.002              |                                       | FIREBIRD      |              |  | Ψ133.00  | Ψ151.20     |
| 3309     | 1048X               | TRUNK FLOOR DROP OFF RH 69            | CAMARO        | 5            | G153   | \$68.10  | \$77.05     |
| 3309     | 1048Y               | TRUNK FLOOR DROP OFF LH 69            |               | 5            | G153   | \$69.00  | \$76.20     |
| 3307     | 10701               | TROURTEOOR DROI OFF LH 09             | CAMARO        |              | 0133   | Ψ07.00   | φ10.20      |
| 3306     | 3306 <b>1049B</b>   | REAR BUMPER 67-68                     | 3886603       | 4            | F95  | \$266.08 | \$272.88    |
|          |                     |                                       | CAMARO        |              |  |          |             |

PAGE:1