| VENDOR | SHIP DATE | SHIP VIA | F.O.B | ONSHIP ETA |
|--------|------------|----------|-------|------------|
| DII | 2017-09-26 | 1 | ORGIN | 2017-09-26 |

CONTAINER 3318 DETAILS

| PO# | ITEM | DESCRIPTION | VPART NO. MAKE | SHIP QTY | LOCATION | FOB | EXT COST |
|------|-------|--|-------------------|----------|----------|---------|-------------|
| 3318 | LH07 | 55-58 TURN SIGNAL LEVER | CHEVROLET | 1 | | \$0.00 | \$0.00 |
| 3318 | LH08 | 55 TURN SIGNAL SWITCH | CHEVROLET | 1 | | \$0.00 | \$0.00 |
| 3318 | LH09 | 56 TURN SIGNAL SWITCH | CHEVROLET | 1 | | \$0.00 | \$0.00 |
| 3318 | LH09A | 57-58 TURN SIGNAL SWITCH | CHEVROLET | 1 | | \$0.00 | \$0.00 |
| 3318 | LH13 | 60-61 HEADLAMP BUCKET | CHEVY PU | 1 | C53 | \$21.98 | \$21.98 |
| 3318 | LH20 | 58-66 HEADLAMP MOUNTING BUCKETW / RING 8PCS / SET 58- 72 GMC | IMPALA | 2 | A134 | \$79.10 | \$79.10 |
| 3318 | LH30 | 64-70 HEADLAMP MOUNTING BUCKET 4PCSW / RING 66-70 GTO | CHEVELLE | 2 | A26 | \$81.14 | \$81.14 |
| 3318 | LH41 | 64-66 WINDSHIELD WIPER SWITCH2 SPEED 63 / 64 NOVA, | GTO | 1 | B11 | \$27.30 | \$27.30 |
| 3318 | LH47 | 67-68 WINDSHIELD WIPER SWITCH 2SPD | CAMARO | 1 | B11 | \$18.48 | \$18.48 |
| 3318 | LP01 | PARK LAMP ASSY RH=LH YLW 12V 47-53 | CHEVY PU | 2 | A13 | \$29.92 | \$29.92 |
| 3318 | LP04 | PARK LAMP ASSY RH / LH CLR 12V 47-53 | CHEVY PU | 3 | A13 | \$46.20 | \$46.20 |
| 3318 | LP05 | PARK LAMP BEZEL 62-66 | CHEVY PU | 4 | A13 | \$23.20 | \$23.20 |
| 3318 | LP05B | 58-59 PARK LAMP BEZEL CHROME | CHEVY PU | 1 | A14 | \$21.84 | \$21.84 |
| 3318 | LP09 | 55-57 PARK LAMP ASSY AMBER 12V | CHEVY PU | 8 | A14 | \$82.24 | \$82.24 |
| 3318 | LP10 | 58-59 PARK LAMP ASSY CLEAR | CHEVY PU | 2 | A14 | \$60.48 | \$60.48 |

PAGE:129