VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-26	1	ORGIN	2017-09-26

CONTAINER 3318 DETAILS

PO# ITEM	ITEM	DESCRIPTION	VPART NO.	SHIP QTY	LOCATION	FOB	EXT COST
	II EWI	DESCRIPTION	MAKE				
3318 1103BG	DOOR SHELL RH 72 CUSTOMW /		1		\$0.00	\$0.00	
3316	3318 1103 D G	O DOOR HANDLE,LOCK HOLES	CHEVY PU	1		\$0.00	\$0.00
3318	3318 1103BH	DOOR SHELL LH 72 CUSTOMW /		1		\$0.00	\$0.00
3310 1103BH	O DOOR HANDLE,LOCK HOLES	CHEVY PU	1		\$0.00	\$0.00	
3318	1103CB	55-59 DOOR INNER PANEL RH	CHEVY PU	1	C123	\$32.85	\$32.85
			CHEVITO				
3318	1103CC	55-59 DOOR BRACKET PR	CHEVY PU	4	C122	\$34.84	\$34.84
3318	3318 1103CD	55-59 DOOR WINDOW FRAME W		1	B101	\$57.61	\$57.61
3316	1103CD	/ GLASS RHCHROME	CHEVY PU	1	D101	\$57.01	\$37.01
2210	3318 1103CE	55-59 DOOR WINDOW FRAME W		2	B101	\$117.20	\$117.20
3316		/ GLASS LHCHROME	CHEVY PU		D101	\$117.20	φ117.20
3318	3318 1103CF	55-59 DOOR WINDOW FRAME W		1	B103	\$45.98	\$45.98
3310		/ GLASS RHPAINTED	CHEVY PU	1	D103	φ 4 5.90	ψ+3.70
3318	1103D	DOOR SHELL LH 55-59	CHEVY PU	- 4	N11	\$780.00	\$780.00
			CHEVITO	2			
3318	1103DA	55-59 WINDOW FRAME LH	CHEVY PU		B94	\$29.24	\$29.24
3318	1103DD	64-66 DOOR SHELL LH	CHEVY PU		041	\$532.92	\$532.92
	3318 1103DE	55-59 DOOR UPPER GUIDE	CHEVITO	1			
3318		RAILFOR REGULATOR	CHEVY PU		A124	\$21.16	\$21.16
	3318 1103DK	55-59 EXTERIOR WINDSHIELD	CHEVIIO	1			
3318		SUNVISOR	CHEVY PU		E102	\$84.00	\$84.00
	3318 1103DL	-	CHEVIIO	1			
3318		47-53 WINDSHIELD SUNVISOR BRACKETRH	CHEVY PU		B92	\$8.82	\$8.82
		54-55 WINDSHIELD SUNVISOR	CHEVIIU	+			
3318	1103DN	BRACKETRH 1ST SERIES	CHEVY PU	1	B92	\$8.82	\$8.82
		47-59 WINDSHIELD SUNVISOR	CHEVIIU				
3318	3318 1103DW	PASBLACK	CHEVY PU	4	B92	\$53.76	\$53.76
	THODEICH	DAGE 7		<u> </u>			

PAGE:7