VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-26	1	ORGIN	2017-09-26

CONTAINER 3317 DETAILS

PO# IT	ITEM	DESCRIPTION	VPART NO.	SHIP OTV	LOCATION	FOB	EXT COST
	IIEM	DESCRIPTION	MAKE				
3317 1067RX	67-69 ROCKER PANEL INNER		2	E91	\$45.58	\$45.58	
3317	3317 1007KA	RHCPE W / O QUARTER SECTION	CAMARO	2	1571	\$ 4 5.58	Ф43.36
3317	3317 1067S	67-69 ROCKER PANEL INNER		5	E94	\$182.60	\$182.60
3317	10075	LH** COUPE **	CAMARO		1274	\$102.00	φ102.00
3317	3317 1067SX	67-69 ROCKER PANEL INNER			E91	\$54.06	\$54.06
3317	1007511	LHCPE W / O QUARTER SECTION	CAMARO		1271	Ψ54.00	Ψ.500
3317	1067U	67-69 COMPLETE ROCKER		_ 1	S31	\$147.06	\$147.06
	100.0	PANEL LH CONV	CAMARO		551	Ψ147.00	Ψ1-7.00
3317	1067W	69 TAIL PANEL BRACE	CAMARO	1	C32	\$13.32	\$13.32
3317	1067X	67-69 TORSION BAR CHASSIS	CAMARO	1	E114	\$97.39	\$97.39
3317	1067Y	INNER TAIL LAMP PANEL67-68	CAMARO	4	C32	\$110.96	\$110.96
3317	1068	HOOD 67-69 COWL INDUCTED	CAMARO	2	D71	\$210.00	\$210.00
3317	1068B	HOOD LATCH ASSY 68	CAMARO	1	A94	\$24.58	\$24.58
3317	1068D	STEEL DASH PANEL 68	CAMARO	1	C22	\$29.35	\$29.35
3317	1068F	HOOD LATCH ASSY 67-68 RS		2	A94	\$50.54	\$50.54
3317	10001	HOOD LATCH ASST 07-08 KS	CAMARO		A94	\$30.34	\$30.34
3317	1068K	BATTERY TRAY 67 / 9		9	F153	\$59.67	\$59.67
	CAMARO,66 CHEVELL	CAMARO			·		
3317	1068LA	70-81 BATTERY TRAY	FIREBIRD	2	F153	\$15.52	\$15.52
3317	1068R	68-69 FLOOR PAN FRAME RAIL		1	E101	\$52.85	\$52.85
		RH	CAMARO		E101	ψυ2.6υ	ψυ2.6υ
3317 1068RXW T		68-69 FLOOR PAN FRAME RAIL					
	RH6" WIDER WHEELHOUSE *WTP *	CAMARO	2	E101	\$181.60	\$181.60	
	-		DACE 17				

PAGE:17