VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-26	1	ORGIN	2017-09-26

CONTAINER 3312 DETAILS

PO# ITEM	DESCRIPTION	VPART NO.	CHID OTV	LOCATION	FOB	EXT	
	IIEWI	DESCRIPTION	MAKE		LOCATION	LOR	COST
2212	3639B	64-66 REAR BUMPER GUARD			CO2	¢24.40	¢24.40
3312 3639B	BRACKET PR	MUSTANG	4	G92	\$34.40	\$34.40	
2212	3312 3643NC	70 TAIL LAMP HOUSING TO		4	A37	\$57.52	\$57.52
3312	3043INC	BODY SEALRH=LH	MUSTANG				
3312	3643WA	69 TAIL LAMP LENSALL BODY		8	A45	\$206.48	\$206.48
3312	3043 WA	STYLE	MUSTANG				
3312	3647LDWT	, 67-70 ROCKER PANEL OUTER		8	E91	\$543.68	\$543.68
3312	3047LD W 1	RH*WTP*	MUSTANG				
3312	3647MDWT	67-70 ROCKER PANEL OUTER		10	E91	\$679.60	\$679.60
3312	504/1VID VV I	LH* WTP *	MUSTANG				
3312	3649E	TRUNK FLOOR RH 65-70	MUSTANG	10	G116	\$110.00	\$110.00
3312	3649F	TRUNK FLOOR LH 65-70	MUSTANG	10	G116	\$110.00	\$110.00
3312	3649PWT	65-68 SEAT SUPPORT		4	G95	\$99.16	\$99.16
3312	3312 3049PW1	PLATFORMRH *WTP *	MUSTANG	4			
3312	3312 3649QWT	65-68 SEAT SUPPORT		4	G95	\$98.36	\$98.36
3312		PLATFORMLH *WTP *	MUSTANG	-			
3312	3652WT	65-66 TORQUE BOX RH CONVT		4	A97	\$149.56	\$149.56
3312	3312 3032W1	*WTP*67-68 AS WELL	MUSTANG	4			
3312	3661	67-68 TRAP DOOR BEHIND REAR			G143	\$187.96	\$187.96
3312	3001	SEAT FB	MUSTANG				
3312	3312 EM4755	71-72 "SS" REAR BUMPER		4		\$96.12	\$96.12
3312		EMBLEM	CHEVELLE			\$90.12	\$70.12
3312	G1130	67-72 DOOR GLASS RH=LH		4	N131 / G2	\$75.36	\$75.36
3314	G1130	CLEAR	CHEVY PU	4			
3312	LH10	47-54 HEADLAMP BUCKET RH /		20	C84	\$406.80	\$406.80
3312	LIIIV	LH	CHEVY PU	20			
3312 LP53	I D52	60-72 DOME LAMP ASSY WHITE		6	A15	\$47.88	\$47.88
	LF33	BASE	CHEVY PU	0			

PAGE:4