VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-11-30	CEVA	ORGIN	2017-12-06

## **CONTAINER 71205 DETAILS**

PO# ITEM	ITEM	DESCRIPTION	VPART NO.	SHIP OTY	LOCATION	FOB	EXT COST
			MAKE				
3337	1068B	HOOD LATCH ASSY 68	CAMARO	2	A94	\$49.64	\$50.40
2220	3339 <b>1072D</b>	69 WIPER MOTOR		3	T01.55	Ø120.15	ф120.co
3339		TRANSMISSION ARM	CAMARO		F157	\$138.15	\$138.69
3339	1101	REAR BUMPER BRACKET SET		- 5	G101	¢176.25	¢101.45
3339	1101	0F 4 47-55	CHEVY PU		GIVI	\$176.35	\$184.45
3337	1102BK	55-59 FRONT LOWER DOOR		2	B94	\$27.76	\$38.26
3331	333/ 1102BK	PILLAR LH	CHEVY PU		Б94	\$37.76	\$38.26
2227	3337 <b>1102CJ</b>	55-59 DOOR HINGE PILLAR		4	B45	\$67.96	\$68.84
3331		POCKET RHLOWER INNER	CHEVY PU	4	D45	\$07.96	φυο.84
3337	3337 <b>1102CK</b>	55-59 DOOR HINGE PILLAR		4	B45	\$69.80	\$70.68
3331		POCKET LHLOWER INNER	CHEVY PU		D43	\$U9.8U	\$70.08
3339	1102XB	47-51 DOOR LATCH STRIKER PR	CHEVY PU	2	B92	\$19.62	\$19.82
3339	339 <b>1103E</b>	DOOR RELAY RH 47-54	CHEVY PU	2	B94	\$22.68	\$23.02
			CHEVIPU			·	
3339	1103F	DOOR RELAY LH 47-54	CHEVY PU	1	B94	\$11.34	\$11.51
3337	1106K	55-59 FIREWALL	CHEVY PU	1	F64	\$133.31	\$143.32
3337	1107C	55-59 COMPLETE FLOOR PAN	CHEVY PU	2	N81	\$652.28	\$701.70
2220	11100	FRONT BUMPER 47-54		4	F02	#220 22	ф22.4.40
3339	1110G		CHEVY PU		F93	\$320.32	\$334.40
3339	1115G	HEAD LAMP BEZEL 67-68PR	CHEVY PU	- 2	C42	\$44.84	\$45.54
		47.72 DECTANCINAD DI ACY	CHEVIIU	2	F164	\$10.72	\$10.94
3339	1151D	47-72 RECTANGULAR BLACK MIRROR	CHEVY PU				
			CHEVITU				
3339	3339 <b>1153B</b>	47-55 EXTERIOR MIRROR ARM BLACK RH	CHEVY PU	_ 2	F174	\$17.82	\$18.02
		DL/ ICIT IGI	DACE-2				

PAGE:2