VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-19	CEVA	ORGIN	2017-09-19

## **CONTAINER 70919 DETAILS**

PO# ITEM	ITEM	DESCRIPTION	VPART NO.	——————————————————————————————————————	LOCATION	FOB	EXT COST
	112	22001111011	MAKE	3222 422			
3297 <b>1069M</b>	77-81 TRANS AM W / SHAKER			D21	\$396.20	\$396.20	
	3297 1009111	HOLE	FIREBIRD		D21	Ψ370.20	ψ370.20
3294	3294 <b>1069U</b>	70-81 HOOD HINGE LHCAMARO		2	A104	\$59.22	\$59.22
3271		/ FIREBIRD / TRANS AM	CAMARO				
	3300 <b>1075</b>	FILLER PANEL (BEHIND REAR		5	F137	\$123.90	\$123.90
3300		WINDOW)67-69 CAMARO & FIREBIRD COUPE	CAMARO				
2200	1076ET	67 DOOR GLASS RH CP / CONVT CLEAR	TP	1	N131 / G6	\$22.56	\$22.56
3300	10/0E1		CAMARO				
3300	1076FT	67 DOOR GLASS LH CP / CONVT	TP	1	N131 / G6	\$22.48	\$22.48
3300	10/0F1	CLEAR	CAMARO	<b></b>			
3289	1076Н	67-69 DOOR GLASS STABILZER GUIDE		2	A85	\$17.40	\$17.40
3209	10/011		CAMARO				
3289	1076L	67-69 QUARTER VENT WINDOW		_ 2	B103	\$183.36	\$183.36
3209	1070L	RH CPE	CAMARO				
3305	1077A	OUTER DOOR HANDLE RH 73-81		5	A32	\$11.05	\$11.05
3303	107714	*CHROME*	CAMARO				
3305	3305 <b>1077B</b>	OUTER DOOR HANDLE LH 73-81		15	A32	\$33.15	\$33.15
	10771	*CHROME*	CAMARO				
3303	1090AWT	FRONT INNER FENDER RH 47-			J181	\$182.13	\$182.13
	3303 1090AW1	54CHEVY / GMC * WTP *	CHEVY PU	3	3101	φ102.13	Ψ102.13
3303	1090BWT	FRONT INNER FENDER LH 47-		4	J181	\$242.84	\$242.84
	10701111	54CHEVY / GMC * WTP *	CHEVY PU	,	0101	Ψ2π2.0π	Ψ2π2.0π
	3303 1097	60-66 REAR INNER			J181	\$65.14	\$65.14
3303		WHEELHOUSE RH=LHFLEETSIDE	CHEVY PU	2			
		RH=LHFLEETSIDE	CHEVITO				
3303	1099D	FENDER LH 1967	CHEVY PU	1	N62	\$95.13	\$95.13
2202	1000114	73-80 INNER FENDER RH	TP	1	1151	017.10	¢17.10
3303	1099НА		CHEVY PU		J171	\$17.19	\$17.19
2202	10001112	72 00 INNIED EENINED I II	TP	1	J171	\$17.19	\$17.19
3303	3303 1099НВ	73-80 INNER FENDER LH	CHEVY PU				

PAGE:3