VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-10-20	CEVA	ORGIN	2017-10-26

CONTAINER 171024 DETAILS

PO#	ITEM	DESCRIPTION	VPART NO. MAKE	SHIP QTY	LOCATION	FOB	EXT COST
3315	1473C	QUARTER PANEL SKIN RH 66-67	CHEVELLE	1	J152	\$68.41	\$68.41
3315	1473D	QUARTER PANEL SKIN LH 66-67	CHEVELLE	1	J152	\$68.27	\$68.27
3315	1473N	69 LOWER REAR QUARTER PATCH PANELRH	CHEVELLE	2	G105	\$41.82	\$40.84
3315	1473P	69 LOWER REAR QUARTER PATCH PANELLH	CHEVELLE	2	G105	\$40.42	\$40.84
3317	1476A	66-67 FENDER PATCH PANEL RH	CHEVELLE	2	A136	\$36.28	\$38.08
3317	1477A	66-67 FENDER PATCH PANEL LH	CHEVELLE	1	A136	\$18.17	\$19.04
3315	1488E	RADIATOR SUPPORT 70	3957351 CHEVELLE	_ 2	F148	\$149.88	\$147.96
3315	1489B	DECK LID FILLER PANEL 66-67	4534269 CHEVELLE	3	C33	\$66.57	\$71.67
3320	1489BA	68-72 ROCKER PANEL RH	EL CAMINO	1	E95	\$75.58	\$77.39
3320	1489BB	68-72 ROCKER PANEL LH	EL CAMINO	2	E95	\$151.20	\$154.82
3321	1489DB	68-69 TRUNK LID RUBBER	CHEVELLE	1	B25	\$8.50	\$10.02
3321	1489DC	70-72 TRUNK LID RUBBER	CHEVELLE	2	B25	\$20.10	\$20.10
3317	1489G	68-72 TRUNK FLOOR BRACE LH70-72 MONTECARLO	CHEVELLE	1	F165	\$13.08	\$13.08
3306	1489WWT	64-67 ROCKER PANEL INNER RH* WTP *	CHEVELLE	1	E91	\$23.45	\$23.45
3319	1489Y	64-67 ROCKER OUTER PANEL RH	TP CHEVELLE	3	D92	\$161.34	\$168.84

PAGE:7