VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-11-03	CEVA	ORGIN	2017-11-07

CONTAINER 71107 DETAILS

PO# ITEM	ITEM	DESCRIPTION	VPART NO.	SHIP OTY	LOCATION	FOB	EXT COST
	1112.11	DESCRIPTION	MAKE	Sim Qii			
3325	1100C	BATTERY TRAY 58-59	CHEVY PU	2	F151	\$36.72	\$38.72
3325 1102BQ	60-66 FRONT LOWER DOOR		1	C74	\$16.85	\$17.00	
	PILLAR RH	CHEVY PU					
3326	1102M	72 DOOR ARM REST BLACK RH	CHEVY PU	1	B92	\$10.92	\$11.05
3326	1102N	72 DOOR ARM REST BLACK LH	CHEVY PU	1	B92	\$10.92	\$11.05
		DOOD SUPELL LILES STEELING	CHEVIFU				
3324	3324 1103	DOOR SHELL LH 67-7172 HAS HOLE FOR VENT WINDOW	CHEVY DI	3	031	\$467.46	\$501.60
		HOLE FOR VENT WINDOW	CHEVY PU				
3328	1103	DOOR SHELL LH 67-71	CHEVY PU	3	031	\$467.46	\$501.60
3328	1103D	DOOR SHELL LH 55-59	CHEVY PU	2	N11	\$479.28	\$507.48
		47-54 WIPER MOTOR TRANS	,	2			
3328	3328 1103VX	ARM PR	CHEVY PU		B103	\$151.20	\$151.62
3328	1104A	ROCKER PANEL RH 60-66		2	C124	\$38.72	\$41.06
3326	1104A	ROCKER I AIVEE RII 00-00	CHEVY PU		C124	Ψ30.72	Ψ41.00
3328	1104B	ROCKER PANEL LH 60-66	CHEVY PU	3	C124	\$56.31	\$59.82
2225	1106AK	60-66 FRONT CAB FLOOR		2	D75	¢20.24	¢21.02
3325	1100AK	SUPPORTRH=LH * 1.60 MM *	CHEVY PU	3	B75	\$30.24	\$31.02
	3328 1106AQ	67-72 CAB FLOOR SUPPORT		1	7100	A-1- 1	A=0.40
3328		BRACE	CHEVY PU		F133	\$74.76	\$79.48
	3325 1106ARC	60-63 CAB FLOOR COMPLETE W			\	4.00 = -	\$
3325		/ O TANS COVER (1106ARB)		2	N71	\$689.72	\$741.74
3328	1106AT	63-66 CAB FLOOR RH		2	G42	\$75.60	\$86.02
3320	1100A1	03-00 CAD FLOOR RA	CHEVY PU		U-12	φ15.00	φ 60. 02
3328	1106AU	63-66 CAB FLOOR LH	CHEVY PU	2	G42	\$75.60	\$86.02

PAGE:4