VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-26	1	ORGIN	2017-09-26

CONTAINER 3318 DETAILS

PO# ITEM	DESCRIPTION	VPART NO.	CHID OTV	LOCATION	EOR	EXT	
	IIEWI	DESCRIPTION	MAKE	SHIPQTY	LOCATION	FOB	COST
3318	1772	59-72 TRUNK LID LATCH	IMPALA	2	A134	\$0.00	\$0.00
3318	1773	63-64 TRUNK LID HINGE PR	IMPALA	1	G102	\$88.40	\$88.40
3318	1781B	62-64 TRUNK SHELF PANEL	IMPALA	1	F82	\$192.65	\$192.65
3318	1781WT	65-70 REAR SEAT FLOOR PANWELD THROUGH PRIMER	IMPALA	1	G153	\$51.24	\$51.24
3318	1783D	65-70 FLOOR PAN UNDER SUPPORT RH	IMPALA	1	F177	\$24.45	\$24.45
3318	1783LWT	65-70 FULL FLOOR PAN LH*WTP*	IMPALA	1	G174	\$65.38	\$65.38
3318	1783RWT	65-70 FULL FLOOR PAN RH*WTP*	IMPALA	3	G172	\$197.43	\$197.43
3318	1785	62-64 OUTER COWL PANELLH	IMPALA	1	F177	\$0.00	\$0.00
3318	1787WT	65-70 ROCKER PANEL INNER LH*WTP*	IMPALA	1	E91	\$33.12	\$33.12
3318	1789A	64 ROCKER PANEL LH	IMPALA	3	E101	\$227.88	\$227.88
3318	1789WT	62-64 COMPLETE ROCKER PANEL LH*WTP*	IMPALA	1	F34	\$152.20	\$152.20
3318	1792	63 HEADLAMP BUCKET ASSY RH	IMPALA	2		\$0.00	\$0.00
3318	1793	63 HEADLAMP BUCKET ASSY LH	IMPALA	2		\$0.00	\$0.00
3318	1860	70 FRONT BUMPER	CUTLASS	2	F102	\$393.70	\$393.70
3318	1862	70 REAR BUMPER442	CUTLASS	2	F113	\$349.34	\$349.34

PAGE:68