VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2018-01-09	CEVA	ORGIN	2018-01-11

## **CONTAINER 80110 DETAILS**

	1109A	DESCRIPTION	MAKE		LOCATION	FOB	EXT COST
3357	1109A		WAKE				
3337	1109A	73-80 FRONT BUMPER CHROME		_ 2	F114	¢1.64.04	\$173.42
555/ 1109A	FLEETSIDE	CHEVY PU		F114	\$164.04	\$173.42	
2255	3355 <b>1109C</b>	70-83 R.BUMPER CHROME		_ 2	F101	\$162.12	\$169.44
3333		FLEETSIDE	CHEVY PU				
2255	1109T	HOOD HINGE RH 55-57 W /		3	A106	\$77.82	\$78.87
3333	3355 <b>1109T</b>	SPRING	CHEVY PU		A100	\$11.82	\$/0.8/ 
3355	3355 <b>1109U</b>	HOOD HINGE LH 55-57 W / SPRING		2	A106	\$51.84	\$52.54
3333 11090	11090		CHEVY PU				
3350 1110	HOOD HINGE LH 67-72	3911705	2	A95	\$44.74	\$46.00	
		CHEVY PU		Ays	<b>\$44.</b> /4	\$40.00	
3350 1111	HOOD HINGE RH 67-72	3911706	_ 2	A95	\$44.76	\$46.02	
		CHEVY PU					
3355	1112P	55-59 ROOF PANEL	CHEVY PU	1	F82	\$137.38	\$152.06
	3314 <b>1114E</b>			6	C122 /	_	
3314		CAB CORNER RH 67-72	CHEVY PU		C123	\$37.62	2 \$38.22
2271	444.00	a. a		10	C122 /	<b></b>	ΦΠ < 10
3354 <b>1114F</b>	CAB CORNER LH 67-72	CHEVY PU	10	C123	\$62.70	\$76.10	
3350 <b>1114FE</b>	72 OF PANED CAR CORNER BY	TP	1	F171	\$9.67	\$10.13	
	73-87 INNER CAB CORNER RH	CHEVY PU					
3350 <b>1114FF</b>	73-87 INNER CAB CORNER LH	TP	2	F171	\$19.56	\$20.48	
		CHEVY PU					
3308	1115D	WINDOW REGULATOR LH 55-59	CHELTA DI	2	A114	\$56.92	\$57.54
3300	11130	WINDOW REGUERTION EIT 33-37	CHEVY PU		AII4	ψ30.72	Ψ57.54
3355	1115E	HEAD LAMP BEZEL 58-59 PAIR	CHEVY PU		C43	\$27.90	\$28.19
3351 <b>1116A</b>	11164	REAR BUMPER CHROME	3885643	2	F92	\$154.50	\$160.42
	1110A	STEPSIDE 67-87	CHEVY PU		F 72	\$154.50	\$100.42
3317 <b>1116B</b>	1116D	REAR BUMPER CHROME 67-72		3	F124	\$237.75	\$244.53
	1110B	FLEETSIDE	CHEVY PU	¬ '	F 144	\$231.13	\$244.33

PAGE:7