VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-11-22	CEVA	ORGIN	2017-11-21

## **CONTAINER 71121 DETAILS**

PO# ITEM	ITEM	DESCRIPTION	VPART NO.	SHIP OTV	LOCATION	FOB	EXT
	1112111	DESCRII IION	MAKE	Sim QII			COST
3320	1076FH	67-69 DOOR HANDLE RELAY LH	CAMARO	2	A126	\$13.42	\$13.62
3321	3321 <b>1076FX</b>	69 DOOR GLASS ASSEMBLY LH	SS ASSEMBLY LH		B104	\$157.94	\$161.70
3321	10/0FA	CPE& CONVT CLEAR GLASS	CAMARO	1	D104	\$157.94	\$161.70
3332	1097E	47-55 REAR FENDER STEPSIDE			N123	\$934.85	\$1,026.70
3332	3332 1097E	RH	CHEVY PU	,	11123	Ψ/34.03	Ψ1,020.70
3332	1097Y	FENDER RH 58-59	CHEVY PU	<del> </del> 4	N92	\$706.48	\$798.28
			CHEVIFU				
3332	1097Z	FENDER LH 58-59	CHEVY PU	4	N93	\$691.92	\$783.72
3334	1099K	FENDER LH 60-66	CHEVY PU		N14	\$198.96	\$210.22
			CHEVIPU				·
3300	1099MC	73-80 HOOD	CHEVY PU	1	D51	\$88.53	\$98.92
2222	3333 <b>1099TA</b>	47-52 HOOD 1PC W / EMBLEM		2	E71	\$509.72	\$573.42
3333		HOLES	CHEVY PU				
3293	1099YA	67-68 GMC RADIATOR SUPPORT	CHEVA DI	1	F72	\$134.52	\$140.88
			CHEVY PU	+		ψ10 ···02	
3334	3334 <b>1100F</b>	BATTERY TRAY ASSEMBLY 67- 72 W / O AC	CHEVA DII	_ 2	F161	\$35.40	\$37.56
			CHEVY PU	1 3			
3335	1100G	BATTERY TRY ASSEMBLY 67-72 W / AC	CHEVY DII		F161	\$19.51	\$21.27
		W/AC	CHEVY PU 3765864				
3334	3334 <b>1100Н</b>	BATTERY TRAY 60-66			F151	\$59.64	\$62.34
			CHEVY PU	3			
3335	1100Q	73-80 BATTERY TRAY	CHEVY PU		F151	\$13.41	\$13.83
2224	110117	DOOR HINGE 55-59 LOWER			A 124	¢120.40	¢122.62
3334 110	1101U	RH=LH W/ SPRING	CHEVY PU	6	A124	\$132.42	\$133.62
3335 <b>1101Z</b>	11017	DOOR SKIN, PARTIAL LOWER		1	D102	\$9.42	\$9.52
	11012	LH 67-729"	CHEVY PU	1			

PAGE:3