VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2018-01-25	CEVA	ORGIN	2018-01-25

## **CONTAINER 80125 DETAILS**

PO#	ITEM	DESCRIPTION	VPART NO. MAKE	SHIP QTY	LOCATION	FOB	EXT COST
3365	1114FF	73-87 INNER CAB CORNER LH	TP CHEVY PU	_ 2	F171	\$22.96	\$23.88
3360	1119ZWT	47-54 RADIATOR SUPPORT * WTP *	CHEVY PU	3	E106	\$432.60	\$440.67
3352	1130	DOOR HANDLE INSIDE 47-66	CHEVY PU	20	A125	\$82.80	\$84.80
3342	1131	WINDOW REGULATOR CRANK HANDLE 47-66	CHEVY PU	6	A125	\$24.84	\$25.44
3359	1137	67-68 HOOD LATCH	CHEVY PU	3	A35	\$68.19	\$68.91
3365	1146	67-72 DASH PAD	CHEVY PU	2	C81	\$71.40	\$72.28
3360	1146	67-72 DASH PAD	CHEVY PU	2	C81	\$71.40	\$72.28
3367	1155D	60-71 INTERIOR REAR VIEW MIRROR BKT	CHEVY PU	2	F164	\$18.74	\$18.94
3359	1155E	69-71 INTERIOR REAR VIEW MIRROR BKT E / BLACK COVER	CHEVY PU	2	F164	\$29.40	\$29.60
3359	1159A	60-66 REAR ROLL PAN FOR STEPSIDE W / LICENSE BOX(NO LICENSE LAMP HOLE)	CHEVY PU	1	C31	\$56.46	\$58.19
3335	1159B	67-72 REAR ROLL PAN FOR FLEETSIDE W / LICENSE BOX(NO LICENSE LAMP HOLE)	CHEVY PU	1	C21	\$63.00	\$64.57
3359	1159B	67-72 REAR ROLL PAN FOR FLEETSIDE W / LICENSE BOX(NO LICENSE LAMP HOLE)	CHEVY PU	1	C21	\$75.60	\$77.17
3359	1160LA	67 BEDSIDE RH 8' FLEETSIDE BED	CHEVY PU	1	S41	\$355.69	\$355.79
3359	1160MA	67 BEDSIDE LH 8' FLEETSIDE BED	CHEVY PU	1	S41	\$354.17	\$354.27
3359	1167	TAILGATE 58-66 FLETSIDE W / CHEVROLET	CHEVY PU	2	M91	\$376.78	\$388.88

PAGE:7