VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-11-22	CEVA	ORGIN	2017-11-21

## **CONTAINER 71121 DETAILS**

PO# ITEM	TOTAL A	DESCRIPTION	VPART NO.	CHID OTY	LOCATION	FOB	EXT COST
	HEM	DESCRIPTION	MAKE	SHIPQIY			
3299	1104D	ROCKER PANEL LH 67-72	CHEVY PU	4	E102	\$36.64	\$44.40
2225	2225 110454	73-87 ROCKER PANEL RH OE	TP	2	E101	\$25.26	\$28.26
3335	1104DA	STYLE	CHEVY PU				
3335	1104DB	73-87 ROCKER PANEL LH OE STYLE	TP	2	E101	\$25.26	\$28.26
3333	110400		CHEVY PU				
3334	1106AG	47-55 CAB FLOOR REAR		1	D103	\$12.87	\$13.00
	HOUAG	SUPPORT LH	CHEVY PU	*			
3335	1106AL	67-72 FRONT CAB FLOOR		10	B75	\$58.80	\$61.00
	HOOAL	SUPPORT MOUNTRH=LH	CHEVY PU	10	D/3	ψ.30.60	ψ01.00
3328	1106AO	67-72 CAB FLOOR SUPPORT BRACE		1	F133	\$74.76	\$79.48
3320	HOUNQ		CHEVY PU	1			
3335	1106AX	47-54 COMPLETE FLOOR PAN	CHEVY PU	1	N51	\$319.15	\$341.85
3293	1106B	47-54 FIRE WALL	CHEVY PU	3	G142	\$321.39	\$345.87
3303	1106B	47-54 FIRE WALL	CHEVY PU	1	G142	\$107.13	\$115.29
	3335 <b>1106BC</b>	67-72 OUTER CAB FLOOR /			G63	\$60.48	\$60.68
3335		INNER ROCKERPATCH RH	CHEVY PU	2			
2225	44060477	47-54 COWL OUTER LOWER			E111	\$71.37	\$79.02
3335	1106DAWT	PANEL LH* NON WTP *	CHEVY PU	3			
2216	2216 110CDD	47-55 LOWER OUTER COWL		- 1	015	Ф <b>2</b> 0. 40	ф <b>20.71</b>
3316	1106DB	PATCH RH	CHEVY PU		C15	\$29.40	\$29.71
2225	1106GA	47-55 TRANS SHIFT COVEWR 4 SPEED	TP	1	G74	\$34.03	\$34.61
3335	1106GA		CHEVY PU				
3287	1107C	55-59 COMPLETE FLOOR PAN	CHEVY PU	1	N81	\$326.14	\$350.85
3335	1109K	REAR BUMPER BRACKET 67-72	CHEVY PU	3	F147	\$76.89	\$78.15

PAGE:5