GOLDEN LEAF AUTOMOTIVE

GOLDEN LEAF AUTOMOTIVE

170 ZENWAY BLVD UNIT#2 WOODBRIDGE, ONTARIO L4H 2Y7 TELEPHONE 905/850-3433

BILL TO: SCOTTS SUPER TRUCK 1972 HWY 592 WEST. PENHOLD AB TOM 1R0 TELEPHONE: 403/886-5572

INVOICE 64395

INVOICE DATE 2018-01-16

PAGE: 1

SHIP TO: SCOTTS SUPER TRUCK 1972 HWY 592 WEST. PENHOLD, AB T0M 1R0 CANADA

*** INVOICE ***

| OLIGINO 3 | TED. | CHIP X/I * | EOD | | OICE *** | CALEC | DATE | OUD ODDER " |
|-----------|-------|-------------|----------|--|-----------|-----------|------------|-------------|
| CUSTOMER | | SHIP VIA | F.O.B | TERMS | PO NUMBER | SALES | DATE | OUR ORDER # |
| S0004 | | BEST | ORIGIN | PREPAID | FAX | M | 2018-01-08 | 52323 |
| ORDER | SHII | B.O. | ITEM | ITEM DESCRIPTION | | PRICE | EXT.PRICE | |
| | SIIII | D.O. | MAKE | | | DIS% | EXT.1 RICE | |
| 4 | 4 | 0 | LH11 | 55-57 HEADLAMP BUCKET RH / LH W / RETAINER RING | | \$ 52.00 | \$ 208.00 | |
| 4 | 7 | | CHEVY PU | | | 0 % | | |
| 1 | 1 | 0 | 1106ARB | 60-63 CAB FLOOR LOWER HUMP COVER | | \$ 132.00 | \$ 132.00 | |
| | | | CHEVY PU | | | 0 % | \$ 132.00 | |
| 2 | 2 | 0 | 1135 | 55-57 HOOD LATCH | | \$ 57.00 | \$ 114.00 | |
| | | | CHEVY PU | | | 0 % | \$ 114.00 | |
| 1 | 1 | 0 | 1127 | FRONT BUMPER GUARD 60-62 PR | | \$ 113.00 | \$ 113.00 | |
| | | | CHEVY PU | | | 0 % | \$ 113.00 | |
| 1 | 1 | 0 | 1160MA | 67 BEDSIDE LH 8' FLEETSIDE BED | | \$ 714.00 | 6.714.00 | |
| | | | CHEVY PU | | | 0 % | \$ 714.00 | |
| 1 | 1 | 0 | 1160LA | 67 BEDSIDE RH 8' FLEETSIDE BED | | \$ 714.00 | \$ 714.00 | |
| | | 0 | CHEVY PU | | | 0 % | | |
| 2 | 2 | 0 | LP05C | 60-66 PARKING LAMP HOUSING EA | | \$ 17.00 | ¢ 24 00 | |
| | | 0 | CHEVY PU | | | 0 % | \$ 34.00 | |
| 1 | 1 | 0 | 1009B | 67-72 KICK PANEL VENT DOOR LH | | \$ 46.00 | \$ 46.00 | |
| | | 0 | CHEVY PU | | | 0 % | | |
| 1 | 1 | 0 | 1009A | 67-72 KICK PANEL VENT DOOR RH | | \$ 46.00 | 0.46.00 | |
| | | 0 | CHEVY PU | | | 0 % | \$ 46.00 | |
| 4 | 4 | 0 | 1131 | WINDOW REGULATOR CRANK HANDLE 47-66 | | \$ 9.00 | \$ 36.00 | |
| | | 0 | CHEVY PU | | | 0 % | | |
| 4 | 4 | | 1130 | DOOR HANDLE INSIDE 47-66 | | \$ 9.00 | \$ 36.00 | |
| | | 0 | CHEVY PU | | | 0 % | | |
| 2 | 1 | | 1103T | DOOR LATCH LH 67-72 | | \$ 52.00 | Φ.52.00 | |
| | | 1 | CHEVY PU | | | 0 % | \$ 52.00 | |
| | | 1 | | | | | • | CONTINUE |
| | | | | | | | | |