VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-08-15	CEVA	ORGIN	2017-08-16

CONTAINER 70816 DETAILS

PO#	ITEM	DESCRIPTION	VPART NO. MAKE	SHIP QTY	LOCATION	FOB	EXT COST
3287	1067C	QUARTER PANEL SKIN RH 69	CAMARO	1	G177	\$43.12	\$58.86
3287	1067D	QUARTER PANEL SKIN LH 69	CAMARO	1	G177	\$42.71	\$58.33
3289	1076M	67-69 QUARTER VENT WINDOW LH CPE	CAMARO	1	B103	\$88.21	\$91.20
3293	1097QD	47-53 FENDER LOWER REAR PANEL LH	CHEVY PU	1	D82	\$52.10	\$54.83
3293	1097QE	55-57 FENDER REAR LOWER PANEL RH	CHEVY PU	1	D104	\$17.09	\$17.61
3293	1097QF	55-57 FENDER REAR LOWER PANEL LH	CHEVY PU	1	D104	\$17.97	\$18.49
3293	1097QG	58-59 FENDER REAR LOWER PANEL RH	CHEVY PU	2	D104	\$34.62	\$36.30
3293	1097QK	60-66 LOWER FENDER PANEL REAR LH	CHEVY PU	3	B92	\$27.09	\$29.07
3293	1097QM	67-72 REAR LOWER FENDER PANEL LH	CHEVY PU	2	D114	\$21.78	\$22.95
3293	1099C	FENDER RH 1967	CHEVY PU	1	N62	\$95.14	\$108.03
3293	1099MA	73-80 3"COWL INDUCTION W/BUG SCREEN	CHEVY PU	2	E51	\$428.00	\$495.23
3293	10B52200	70-74 CARPET BLACK 80/20 LOOP 1PC	CAMARO	2	F183	\$202.82	\$213.08
3293	10B53140-2	67-69 CARPET BLACK 80/20	CAMARO	1	F186	\$101.41	\$105.14
3289	1100D	BATTERY TRAY ASSEMBLY 47- 55	CHEVY PU	2	F151	\$39.18	\$41.07
3293	1102BS	67-72 FRONT LOWER DOOR PILLAR RH	CHEVY PU	2	C74	\$10.38	\$11.07

PAGE:3