VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-26	1	ORGIN	2017-09-26

## **CONTAINER 3317 DETAILS**

PO#	ITEM	DESCRIPTION	VPART NO. MAKE	SHIP QTY	LOCATION	FOB	EXT COST
3317	1067FA	TAIL LIGHT PANEL 69RS	CAMARO	1	F34	\$85.00	\$85.00
3317	1067G	ROCKER PANEL RH 67-69 H / T	CAMARO	4	E111	\$140.92	\$140.92
3317	1067H	ROCKER PANEL LH 67-69 H / T	CAMARO	3	E111	\$105.51	\$105.51
3317	1067J	ROCKER PANEL RH 70-81	CAMARO	1	E95	\$47.46	\$47.46
3317	1067K	ROCKER PANEL LH 70-81	CAMARO	1	E105	\$46.68	\$46.68
3317	1067KAWT	70-73 COMPLETE ROCKER PANEL RH* WTP *	CAMARO	1	F62	\$198.11	\$198.11
3317	1067KC	70-81 ROCKER INNER PANEL RH	CAMARO	1	E91	\$35.88	\$35.88
3317	1067KD	70-81 ROCKER INNER PANEL LH	CAMARO	1	E91	\$36.22	\$36.22
3317	1067M	70-73 TAIL LIGHT PANEL	CAMARO	2	F137	\$69.40	\$69.40
3317	1067MA	70-73 REAR CROSS RAIL	CAMARO	2	F146	\$77.16	\$77.16
3317	1067MB	74-81 REAR CROSS RAIL75-81 TRANSAM / FIREBIRD	CAMARO	1	C33	\$49.43	\$49.43
3317	1067P	78-81 REAR BODY INNER PANEL	CAMARO	1	E105	\$29.30	\$29.30
3317	1067PA	71-73 REAR VALANCE PANEL	CAMARO	2	F64	\$64.00	\$64.00
3317	1067Q	69 REAR CROSS RAIL	CAMARO	3	F126	\$69.00	\$69.00
3317	1067R	67-69 ROCKER PANEL INNER RH** COUPE **	CAMARO	5	E95	\$183.50	\$183.50

PAGE:16