VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-08-10	CEVA	ORGIN	2017-08-10

CONTAINER 70804 DETAILS

PO#	ITEM	DESCRIPTION	VPART NO. MAKE	SHIP QTY	LOCATION	FOB	EXT COST
3284	1069CWT	67-69 COWL TOP VENT GRILLE PANEL	CAMARO	2	A117	\$122.68	\$127.36
3284	1069K	67-69 COWL INDUCTION W/BUG SCREEN	CAMARO	2	E61	\$439.10	\$473.64
3284	1069N	70-76 TRANS AM HOOD	FIREBIRD	2	D81	\$617.84	\$647.90
3284	1072C	67-68 WIPER MOTOR TRANSMISSION ARM	CAMARO	2	F157	\$91.50	\$91.86
3284	1073L	67-69 OUTER COWL SIDE LH	CAMARO	3	A86	\$109.83	\$115.83
3284	1073R	67-69 OUTER COWL SIDE RH	CAMARO	3	A86	\$109.98	\$115.98
3284	1102AR	55-59 DOOR INNER BOTTOM RH	CHEVY PU	2	D82	\$64.52	\$67.90
3284	1102AS	55-59 DOOR INNER BOTTOM LH	CHEVY PU	2	D82	\$64.52	\$67.90
3284	1102Ј	55-59 DOOR ARM REST BLACK RH=LH	CHEVY PU	1	В92	\$19.32	\$19.42
3284	1102M	72 DOOR ARM REST BLACK RH	CHEVY PU	1	B92	\$10.92	\$11.05
3284	1102N	72 DOOR ARM REST BLACK LH	CHEVY PU	1	B92	\$10.92	\$11.05
3284	1106BD	67-72 OUTER CAB FLOOR/INNER ROCKER	CHEVY PU	2	G63	\$60.48	\$64.70
3284	1107G	55-59 CAB REAR INNER WINDOW PANEL	CHEVY PU	2	J94	\$231.10	\$257.48
3284	1109Q	REAR LICENSE PLATE BRACKET 60-66	CHEVY PU	2	B21	\$26.74	\$27.32
3270	1114X	60-66 FOOT WALL PANEL LH	CHEVY PU	1	D94	\$12.24	\$12.41
3270	1114Z	67-72 FOOT WELL PANEL LH	CHEVY PU	2	D93	\$14.30	\$14.62
3284	1116B	REAR BUMPER CHROME 67- 72 FLEETSIDE	CHEVY PU	4	F124	\$311.56	\$320.60

PAGE:1