VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-26	1	ORGIN	2017-09-26

CONTAINER 3317 DETAILS

PO#	ITEM	DESCRIPTION	VPART NO. MAKE	SHIP QTY	LOCATION	FOB	EXT COST
			WIAKE	+			COSI
3317	1076YB	70-81 DOOR SKIN LH	FIREBIRD	2	J182	\$94.98	\$94.98
3317	1076YC	77-81 DOOR SHELL RHFIREBIRD		1	C111	\$333.08	\$333.08
3317	10/010	/ TRANS AM	FIREBIRD				
3317	1076YD	77-81 DOOR SHELL LHFIREBIRD		1	C111	\$333.08	\$333.08
3317	10/01D	/ TRANS AM	FIREBIRD				
		77-81 DOOR SHELL RH FB /					
3317 1076YE	TRANS AMCUSTOM NO DOOR	EIDEDIDD	1		\$0.00	\$0.00	
		HANDLE HOLES	FIREBIRD				
	3317 1076YF	77-81 DOOR SHELL LH FB /		1		40.00	40.00
3317		TRANS AMCUSTOM NO DOOR HANDLE HOLES	FIREBIRD			\$0.00	\$0.00
			TINEDIKE	+			
2217	3317 1076YX	75-81 DOOR SHELL RH CUSTOMNO DOOR HANDLE,		1		\$0.00	\$0.00
3317		KEY, MIRROR HOLES	CAMARO			\$0.00	\$0.00
		<u> </u>					
3317	1076ZA	75-81 DOOR SHELL RH	CAMARO	1		\$0.00	\$0.00
3317	1076ZB	75-81 DOOR SHELL LH	CAMARO	1		\$0.00	\$0.00
			CAMARO	 		7 0 1 0 0	7
3317	3317 1076ZX	75-81 DOOR SHELL LH CUSTOMNO DOOR HANDLE,		_ 1		\$0.00	\$0.00
331/ 10/0ZA	KEY, MIRROR HOLES	CAMARO	1		\$0.00	\$0.00	
		OUTER DOOR HANDLE RH 73-81		11	A32	\$24.31	\$24.31
3317	1077A	*CHROME*	CAMARO				
		OUTER DOOR HANDLE LH 73-81	C/ HVII/ HCO	+			
3317 1077B	*CHROME*	CAMARO	3	A32	\$6.63	\$6.63	
		FRONT INNER FENDER RH 58-59	C/ HVI/ HCO	1	2112		
3317	1090E		CHEVY PU		C113	\$55.97	\$55.97
3317	1090F	FRONT INNER FENDER LH 58-59	CHEVY PU	1	C113	\$57.21	\$57.21
			CHEVIPU	_		,	,
3317	1090G	58-59 INNER WHEELHOUSE RH / LHFLEETSIDE	CHEVY DI	_ 2	J181	\$132.72	\$132.72
			CHEVY PU				
3317 1091 C	47-54 SKIRT BRACEPARKING BRAKE BRACKET	CHEVY PU	1	G95	\$19.84	\$19.84	
	DRAKE DRACKET	CHEVIPU					

PAGE:22