## **GOLDEN LEAF AUTOMOTIVE**

## GOLDEN LEAF AUTOMOTIVE

170 ZENWAY BLVD UNIT#2 WOODBRIDGE, ONTARIO L4H 2Y7 TELEPHONE 905/850-3433

VENDOR: DYNACORN INTERNATIONAL INC.

4030 VIA PESCADOR CAMARILLO CA 93012 PERMIT: 805/987-8818

## **PURCHASE ORDER 3360**

PURCHASE ORDER DATE 2018-01-11

PAGE:5

SHIP TO: GOLDEN LEAF AUTOMOTIVE 170 ZENWAY BLVD UNIT#2

**WOODBRIDGE, ONTARIO L4H 2Y7** 

## \*\*\* PURCHASE ORDER \*\*\*

| VENDOR  | R V      | ENDOR FAX NO     | VENDOR TELEPHONE NO<br>805/987-8818<br>REMARKS            | SHIP VIA<br>CEVA<br>FREIGHT | F.O.B      | TERMS<br>120 |
|---------|----------|------------------|-----------------------------------------------------------|-----------------------------|------------|--------------|
| DII     | 80       | 5/388-0786 SALES |                                                           |                             |            |              |
| BUYER   | C        | ONFIRMING TO     |                                                           |                             | TAX        |              |
|         |          |                  |                                                           |                             | N          |              |
| QTY.ORD | QTY.OPEN | YOUR ITEM #      | ITEM DESCRIPTION                                          |                             | UNIT PRICE | EXT.PRICE    |
|         |          | OUR ITEM #       | TIEM DESCRIPTION                                          |                             | REQ.DATE   |              |
| 1       | 1        |                  | 70 74 EDONT WHEEL OPENING MOLDI                           | NCIU                        | \$ 15.38   |              |
|         |          | M6019            | 70-74 FRONT WHEEL OPENING MOLDING LH                      |                             | 2018-01-11 | \$ 15.38     |
| 1       | 1        |                  | -70-74 REAR WHEEL OPENING MOLDING LH                      |                             | \$ 16.44   | \$ 16.44     |
|         |          | M6021            |                                                           |                             | 2018-01-11 |              |
| 5       | 5        |                  | FULL FLOOR PAN RH 62-67 ** * NON WELD THROUGH FINISH *    |                             | \$ 35.17   | \$ 175.85    |
|         |          | 1630WT           |                                                           |                             | 2018-01-11 |              |
| 5       | 5        |                  | FULL FLOOR PAN LH 62-67 ** * NON WELD<br>THROUGH FINISH * |                             | \$ 32.39   | \$ 161.95    |
|         |          | 1631WT           |                                                           |                             | 2018-01-11 |              |
| 2       | 2        |                  | │<br>─65-67 GAS CAP FLAT BLACK                            |                             | \$ 7.76    | \$ 15.5      |
|         |          | 1623N            | 03-07 GAS CAI TEAT BEACK                                  |                             | 2018-01-11 | φ 15.52      |
| 2       | 2        |                  | │<br>─67-72 DASH PAD                                      |                             | \$ 30.24   | \$ 60.48     |
|         |          | 1146             | 07-72 DASHTAD                                             |                             | 2018-01-11 | φ 00.46      |
| 2       | 2        |                  | -60-66 FRONT LOWER DOOR PILLAR RH                         |                             | \$ 16.85   | \$ 33.70     |
|         |          | 1102BQ           |                                                           |                             | 2018-01-11 |              |
| 6       | 6        |                  | -70-74 DOOR STRIKER                                       | _                           | \$ 6.47    | \$ 38.82     |
|         |          | 6052E            | , o , , 2 dd , dd , dd , dd , dd , dd ,                   |                             | 2018-01-11 | Ψ 30.02      |
| 1       | 1        |                  | -70-71 FRONT BUMPER                                       |                             | \$ 106.20  | \$ 106.20    |
|         |          | 6021             | 70 /TROIVI BOM ER                                         |                             | 2018-01-11 |              |
| 2       | 2        |                  | <br> -70-71 REAR BUMPER                                   | _                           | \$ 105.97  | \$ 211.94    |
|         |          | 6022             | , , , , , , , , , , , , , , , , , , ,                     |                             | 2018-01-11 |              |
| 1       | 1        |                  | <br> -70-74 DOOR SHELL RH                                 |                             | \$ 301.20  | \$ 301.20    |
|         |          | 6050             | , o 2 ook siless kii                                      |                             | 2018-01-11 |              |
|         |          |                  |                                                           |                             |            | CONTINUE     |

VENDOR ORIGINAL