## **GOLDEN LEAF AUTOMOTIVE**

## **INVOICE 63297**

## GOLDEN LEAF AUTOMOTIVE

170 ZENWAY BLVD UNIT#2 WOODBRIDGE, ONTARIO L4H 2Y7 TELEPHONE 905/850-3433

BILL TO: COUNTER SALES UNUSED PART EXCHANGE/RETURN WITHIN 30 DAYS W/ORIGINAL INV.

TELEPHONE: / -

**INVOICE DATE 2017-10-02** 

PAGE: 1

SHIP TO: CURTIS MICHAEL 7452 WELLINGTON RD 11 RR1 5165777838 MOOREFIELD, ON N0G2K0 CANADA

## \*\*\* INVOICE \*\*\*

CUSTOMER		SHIP VIA		F.O.B	TERMS	PO NUMBER	SALES	DATE	OUR ORDER #
CSALE		PU OCT 2		ORIGIN	PREPAID	WEB	AY	2017-09-28	51409
ODDED	CIII		D ()	ITEM	WEEN DESCRIPTION		PRICE	EVE PRICE	
ORDER	SHIP		B.O.	MAKE	ITEM DESCRIPTION			DIS%	EXT.PRICE
1	1		0	1039N	FENDER RH 67 RS W / EXT		\$ 332.00	£ 222 00	
	1		0	CAMARO	FENDER RH 0/ RS W / EAT		0 %	\$ 332.00	
1	1		0	1039P	FENDER LH 67 RS W / EXT		\$ 332.00	\$ 332.00	
	1		U	CAMARO	FENDER LH 0/ KS W / EX I		0 %	\$ 332.00	
1	1		0	1039W	FRONT INNER FENDER RH 67-68		\$ 155.00	\$ 155.00	
			U	CAMARO			0 %		
1	1		0	1039X	FRONT INNER FENDER LH 67-68		\$ 155.00	\$ 155.00	
			U	CAMARO			0 %	\$ 155.00	
1	1		0	1047A	FRONT APRON 67 RS		\$ 90.00	\$ 90.00	
			0	CAMARO			0 %		
1	1		0	1047J	HEADER PANEL 67-68		\$ 87.00	\$ 87.00	
				CAMARO			0 %		
1	0		1	1047L	RADIATOR SUPPORT 67-69CAMARO AND FIREBIRD		\$ 165.00	\$ 0.00	
			1	CAMARO			0 %		
1	1		0	1048B	FRONT BUMPER BRACKET RH 67-68 INNER		\$ 29.00	\$ 29.00	
				CAMARO			0 %	Ψ 27.00	
1	1		0	1048C	FRONT BUMPER BRACKET LH 67-68 INNER		\$ 29.00	\$ 29.00	
				CAMARO			0 %	\$ 25.00	
1	1		0	1048M	FRONT BUMPER OUTER BRACKET RH 67		\$ 17.00	\$ 17.00	
				CAMARO			0 %	\$ 17.00	
1	0		1	1048N	FRONT BUMPER OUTER BRACKET LH 67		\$ 17.00	\$ 0.00	
				CAMARO			0 %	\$ 0.00	
1	1		0	1068F	HOOD LATCH ASSY 67-68 RS		\$ 87.00	\$ 87.00	
				CAMARO			0 %		
									CONTINUE