VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
B0018	2018-01-30	DEL	ORGIN	2018-01-30

## **CONTAINER 3364 DETAILS**

PO# ITEM	ITEM	DESCRIPTION	VPART NO.	CHID OTV	LOCATION	FOB	EXT COST
	TIENI	DESCRIPTION	MAKE	SHIPQIY			
3364 GL10-	64-72 CLUTCH ROD HOLE		4		\$44.00	\$44.00	
0504-CC		COVER W/HARDWARE		CHEVY PU		Ψ+1.00	Ψ-100
	GL12-422-	60-63 DOOR CHECK SUPPORT					
3364 S	ON A PILLAR W/ROLL PIN AND HARDWARE	CHEVY PU	4		\$70.00	\$70.00	
2264	3364 GL14- 4141-R	63-66 REAR CAB TO FRAME		2		0.54.00	064.00
3364		SUPPORT	CHEVY PU			\$64.00	\$64.00
3364	GL14-525-	67-72 CAB SUPPORT REPAIR		6		\$36.00	\$36.00
3304	CFP	PLATE	CHEVY PU	0		\$30.00	
3364	GL14-525-	67-72 REAR CAB TO FRAME		4	\$132.00	\$132.00	\$132.00
3304	CR	SUPPORT W/HARDWARE	CHEVY PU	<u> </u>		\$132.00	\$132.00
3364	GL16-	60-72 SEAT REAR COIL SPRING UPPER W/HARDWARE		2		\$52.00	\$52.00
	0510-S		CHEVY PU				
3364	3364 <b>GL17-0519</b>	66-72 PARK CABLE BUSHING IN FRAME CROSS MEMBER OE	17-0519	10	\$44.80	\$44.80	
3304		NYLON PR CHEVY P		10	φ44.00	Ψ-700	
3364	3364 GL19-405- 60C	60-61 PARKING LAMP LEN		_ 4	\$10	\$104.00	\$104.00
3304		CLEAR W/GASKET GMC	CHEVY PU	<b>~</b>		\$104.00	
3364	3364 GL19-505- S	67-72 PARK LAMP HOUSING				\$55.00	\$55.00
3304		SUPPORT W/HARDWARE GMC	CHEVY PU	10			
3364	3364 GL20-510-	67-72 INNER FENDER TO CAB		4		\$23.88	\$23.88
	СВ	BOLT W/WASHER	CHEVY PU				
3364	3364 GL23-202- G1	47-55 FIRST SERIES GMC 100		4		\$120.00	\$120.00
		EMBLEM W/HARDWARE	CHEVY PU			,	,
3364	3364 <b>GL3-206</b>	47-55 FILLER PANELS AT		4	\$32.0	\$32.00	\$32.00
		FIREWALL/FENDER W/SCREWS	CHEVY PU			·	
3364	GL3-320- HS-S	55-59 HOOD ADJUSTER BOLT	CHEVY PU	10		\$55.00	\$55.00
3364	GL30-2724	47-53 BED BLOCK W/PAD KIT	CHEVY PU	5		\$60.00	\$60.00
G G	GL31-	54-72 BED PAD SET 10 PCS	31-0201-P	10		<b>450.00</b>	<b># 7</b> 0 0 =
3364	3364 <b>0201-P</b>	RUBBER SET	CHEVY PU			\$50.00	\$50.00

PAGE:1