GOLDEN LEAF AUTOMOTIVE

170 ZENWAY BLVD UNIT#2 WOODBRIDGE, ONTARIO L4H 2Y7 TELEPHONE 905/850-3433

BILL TO: WALKER AUTO PARTS 1170 SANFORD STREET WINNIPEG MB R3E 2Z9 TELEPHONE: 204/775-2222

INVOICE 63815

INVOICE DATE 2017-11-14

PAGE: 1

SHIP TO: WALKER AUTO PARTS 1170 SANFORD STREET WINNIPEG, MB R3E 2Z9 CANADA

CUSTOM	ER	SHIP VIA	F.O.B	TERMS	PO NUMBER	SALES	DATE	OUR ORDER#
W0004		BEST	ORIGIN	NET 10TH	NET 10TH WK OF OCT 30TH M		2017-10-30	51739
ORDER	SHII	Р В.О.	ITEM MAKE	I	TEM DESCRIPTION	N	PRICE DIS%	EXT.PRICE
1	1	0	1478 CHEVELLE		FENDER RH 67**		\$ 299.00 0 %	\$ 299.00
1	1	0	1479 CHEVELLE		FENDER LH 67**		\$ 299.00	\$ 299.00
1	1	0	M1017 CAMARO		ADE 7 BLADE CAMA -72,CHEVELLE 68-7		\$ 67.00	\$ 67.00
1	1	0	3649E MUSTANG	TR	UNK FLOOR RH 65-	\$ 37.00	\$ 37.00	
1	1	0	3649F MUSTANG	TR	UNK FLOOR LH 65-	\$ 37.00	\$ 37.00	
1	1	0	1612 NOVA	FRONT	BUMPER CHROME	E 68-69	\$ 185.00 0 %	\$ 185.00
1	1	0	1614 NOVA	REAR B	UMPER 68-72 NOV <i>A</i> VENTURA	A71 / 72	\$ 185.00 0 %	\$ 185.00
2	2	0	1106DAWT CHEVY PU	47-54 COWI	L OUTER LOWER PA	ANEL LH*	\$ 53.00	\$ 106.00
2	2	0	1102BF CHEVY PU	47-54 FRON	NT LOWER DOOR P	ILLAR LH	\$ 33.00	\$ 66.00
1	1	0	1102AM CHEVY PU	47-55 DOOR INNER BOTTOM RH		\$ 36.00	\$ 36.00	
1	1	0	1102AN CHEVY PU	47-55 DOOR INNER BOTTOM LH \$ 36.00 0 %		\$ 36.00		
2	2	0	1102BE CHEVY PU	47-54 FRON	NT LOWER DOOR P	ILLAR RH	\$ 33.00	\$ 66.00
		'		•			•	CONTINUE

GOLDEN LEAF AUTOMOTIVE

170 ZENWAY BLVD UNIT#2 WOODBRIDGE, ONTARIO L4H 2Y7 TELEPHONE 905/850-3433

BILL TO: WALKER AUTO PARTS 1170 SANFORD STREET WINNIPEG MB R3E 2Z9 TELEPHONE: 204/775-2222

INVOICE 63815

INVOICE DATE 2017-11-14

PAGE: 2

SHIP TO: WALKER AUTO PARTS 1170 SANFORD STREET WINNIPEG, MB R3E 2Z9 CANADA

CUSTOM	ER	SHIP VIA	F.O.B	TERMS	PO NUMBER	SALES	DATE	OUR ORDER#
W0004	W0004		ORIGIN	NET 10TH WK OF OCT 30TH M 2		2017-10-30	51739	
ORDER	SHIP	B.O.	ITEM MAKE	· II	TEM DESCRIPTION	N	PRICE DIS%	EXT.PRICE
6	6	0	M1118B CHEVY PU		OOOR SCUFF PLAT SOWTIESTAINLESS		\$ 23.00	\$ 138.00
1	1	0	1099T CHEVY PU		47-52 HOOD		\$ 528.00	\$ 528.00
1	1	0	1099J CHEVY PU		FENDER RH 60-66		\$ 199.00	\$ 199.00
1	1	0	1099K CHEVY PU		FENDER LH 60-66		\$ 199.00	\$ 199.00
1	1	0	1047ZB FIREBIRD	69 RAD SUP	PORT TO HEADER PR	\$ 39.00	\$ 39.00	
1	1	0	1047YA FIREBIRD	69 HEAI	69 HEAD PANEL SEAL 2PCS / SET		\$ 142.00	\$ 142.00
1	1	0	1048QB FIREBIRD	69 FRONT I	BUMPER BRACKET	4PCS SET	\$ 106.00	\$ 106.00
1	1	0	M1724W IMPALA	LOW	ER GRILL MOLDIN	\$ 54.00		\$ 54.00
1	1	0	M1724B IMPALA	EYEB	ROW MOLDING 64	PAIR	\$ 77.00 0 %	\$ 77.00
1	1	0	1466 CHEVELLE	HOOD HINGE RH 70-72EL CAMINO,IMPALA,MONTE CARLO		\$ 43.00	\$ 43.00	
1	1	0	1467 CHEVELLE	HOOD HINGE LH 70-72EL CAMINO, \$43.00 IMPALA, MONTE CARLO 0 %		\$ 43.00		
1	1	0	M1728C IMPALA	67-68 BOD	Y BUSHING KIT W CONV	/ BOLTS	\$ 93.00	\$ 93.00
		1		ı			1	CONTINUE

GOLDEN LEAF AUTOMOTIVE

170 ZENWAY BLVD UNIT#2 WOODBRIDGE, ONTARIO L4H 2Y7 TELEPHONE 905/850-3433

BILL TO: WALKER AUTO PARTS 1170 SANFORD STREET WINNIPEG MB R3E 2Z9 TELEPHONE: 204/775-2222

INVOICE 63815

INVOICE DATE 2017-11-14

PAGE: 3

SHIP TO: WALKER AUTO PARTS 1170 SANFORD STREET WINNIPEG, MB R3E 2Z9 CANADA

1	CHICTON	(ED		TITID X/I A	EOB		DO MIMBER	CALEC	DATE	OLID ODDER "			
Note	CUSTOM	IER		SHIP VIA	F.O.B	TERMS		SALES	DATE	OUR ORDER#			
NAKE SHIP B.O. MAKE STEM DESCRIPTION DIS% EXT.PRICE	W0004	1		BEST	ORIGIN	NET 10TH		M	2017-10-30	51739			
MAKE	ODDED GI		m	n o	ITEM	THEM DESCRIPTION			PRICE	EVE DDICE			
CHEVY PU	ORDER	SHI	uP	B.O.	MAKE] 11	EM DESCRIPTION	•	DIS%	EXI.PRICE			
CHEVY PU	((0	1106AL	67-72 FRC	ONT CAB FLOOR SU	JPPORT	\$ 11.00	\$ 66.00			
2 2 0 CHEVY PU ROCKERPATCH RH 0 % \$132.0	0	0		0	CHEVY PU		MOUNTRH=LH		0 %	\$ 60.00			
CHEVY PU	2			0	1106BC	67-72 OU	TER CAB FLOOR /	INNER	\$ 66.00	\$ 122.00			
1	2	4		U	CHEVY PU	F	ROCKERPATCH RH		0 %	\$ 132.00			
CHEVY PU	2	2		0	1106BD	67-72 OU	TER CAB FLOOR /	INNER	\$ 66.00	\$ 122.00			
S	2	4		U	CHEVY PU	F	ROCKERPATCH LH		\$ 11.00 0 % \$ 66.00 0 % \$ 66.00 0 % \$ 19.00 0 % \$ 22.00 0 % \$ 22.00 0 % \$ 22.00 0 % \$ 250.00	\$ 132.00			
CHEVY PU	5	-			0	1104C	POC	VED DANEL DU 67	72	\$ 19.00	\$ 05.00		
The image of the	3	n		U	CHEVY PU	ROC	KER PANEL KH 0/	0 %	\$ 95.00				
1	5	0	5	5	1104D	ROCKER PANEL LH 67-72			\$ 19.00	\$ 0.00			
1	J	U		3	CHEVY PU				0 %				
1	1	1		0	1104DA	73-87 ROCKER PANEL RH OE STYLE			\$ 22.00	\$ 22.00			
1	1	1		0	CHEVY PU				0 %				
1	1	1	1		1104DB	73-87 ROCKER PANELLH OF S		E STVI E	<u> </u>	\$ 22.00			
1 1 0 CHEVY PU DOOR SKIN, PARTIAL LOWER LH 67-729" 0 % \$19.0 1 1 0 1134A CHEVY PU 67-72 EXT. DOOR HANDLEPR \$50.00 0 % \$50.00 0 % \$50.00 0 % \$50.00 0 % \$107.00 0 %<	1	1		U	CHEVY PU	73-87 KO	CKER I ANEL LII OI	STILL	0 %	\$ 22.00			
1	1	1			1101Z	DOOD SKIN	DADTIAL LOWED	I Ц 67 720"	\$ 19.00	\$ 10.00			
1 1 0 67-72 EXT. DOOR HANDLEPR 0 % \$50.0 1 1 0 1159B CHEVY PU CHEVY PU LICENSE BOX(NO LICENSE LAMP HOLE) \$107.00 0 0 % \$107.00 0 0 % 1 0 1 1109K CHEVY PU CHE	1	1		U	CHEVY PU	DOOK SKIN	, I ARTIAL LOWER	LII 07-729	0 %	\$ 19.00			
1 1 0 1159B (67-72 REAR ROLL PAN FOR FLEETSIDEW / LICENSE BOX(NO LICENSE LAMP HOLE) \$ 107.00 (9 %) 1 0 1 1109K (CHEVY PU (CHEV) PU (CHEVY PU (CHEV) PU (CHEV	1 1	1			1134A	67.72	EXT DOOR HANDI	EDD	\$ 50.00	\$ 50.00			
1 1 0 CHEVY PU LICENSE BOX(NO LICENSE LAMP HOLE) 0 % \$ 107.0 1 0 1 109K CHEVY PU REAR BUMPER BRACKET 67-72 \$ 60.00 0 % \$ 0.0 1 0 1 1100Q CHEVY PU 73-80 BATTERY TRAY \$ 9.00 0 % \$ 9.00 0 %	1	1		U	CHEVY PU	07-72	EAT. DOOK HANDI	JEI K	0 %	\$ 50.00			
1 0 1 109K CHEVY PU REAR BUMPER BRACKET 67-72 \$ 60.00 \$ 0.00 1 0 1 100Q CHEVY PU 73-80 BATTERY TRAY \$ 9.00 \$ 0.00	1	1	1	1	1	1		1159B	67-72 REAR I	ROLL PAN FOR FLE	ETSIDEW /	\$ 107.00	\$ 107.00
1 0 1 CHEVY PU REAR BUMPER BRACKET 67-72 0 % \$0.0 1 0 1 1100Q 73-80 BATTERY TRAY 0 % \$0.0	1	1	1		CHEVY PU	LICENSE BOX(NO LICENSE LAMP HOLE			0 %	\$ 107.00			
CHEVY PU 1	1	0		. 1	1 1	1109K	DEAD RUMDED RDACKET 67.77		67.72	\$ 60.00	\$0.00		
1 0 1 CHEVY PU 73-80 BATTERY TRAY 0 % \$ 0.0	1	U		1	CHEVY PU	KLAK I	JOHN ER BRACKET	01-12	0 %	ŷ 0.00			
CHEVY PU 0 %	1	Λ		1	1100Q	72 90 DATTEDV TD AV		v	\$ 9.00	\$0.00			
CONTINUE	1	U		1	CHEVY PU	/3	-ou DAITENT IKA	1	0 %	\$ 0.00			
CONTINUE.										CONTINUE			

GOLDEN LEAF AUTOMOTIVE

170 ZENWAY BLVD UNIT#2 WOODBRIDGE, ONTARIO L4H 2Y7 TELEPHONE 905/850-3433

BILL TO:

WALKER AUTO PARTS 1170 SANFORD STREET WINNIPEG MB R3E 2Z9 TELEPHONE: 204/775-2222

INVOICE 63815

INVOICE DATE 2017-11-14

PAGE: 4

SHIP TO: WALKER AUTO PARTS 1170 SANFORD STREET WINNIPEG, MB R3E 2Z9 CANADA

CUSTOM	IER		SHIP VIA	F.O.B	TERMS	PO NUMBER	SALES	DATE	OUR ORDER#			
W0004			BEST	ORIGIN	NET 10TH	WK OF OCT 30TH	М	2017-10-30	51739			
ORDER SHII		ID.	B.O.	ITEM	17	ITEM DESCRIPTION			EXT.PRICE			
OKDEK	3111	ur	в.О.	MAKE	1.	EM DESCRIPTION	`	DIS%	EAT.FRICE			
1	1		0	1100G	BATTEDV'	BATTERY TRY ASSEMBLY 67-72 W / AC		\$ 50.00	\$ 50.00			
1	1		U	CHEVY PU	DATIERT	IKI ASSEMBLI 07	-12 W / AC	0 %	\$ 50.00			
1	1		0	GL-1100A	47-54 INNER	FRONT COWL SIDE	E PANELLH	\$ 54.00	\$ 54.00			
1	1		U	CHEVY PU	CHEVY / GM	IC*47-50 NEED LOU	VER CUT*	0 %	\$ 54.00			
1	0		1	1106DWT	47-54 COWI	OUTER LOWER PA	ANEL RH*	\$ 53.00	\$ 0.00			
1	U		1	CHEVY PU		NON WTP *		0 %	\$ 0.00			
1		0	0	0	1	1106AC	17-5	4 CAB FLOOR PAN	ıп	\$ 63.00	\$ 0.00	
1	U		1	CHEVY PU	47-3	4 CAB I LOOK I AN	0 %	\$ 0.00				
1	1		0	1107CB	55-59 CAB FLOOR LH		\$ 63.00	\$ 63.00				
1	1		0	CHEVY PU	33-39 CAB FLOOR LH				0 %			
1	1		0	1104H	INNER DOOR STEP WITH ROCKER LH 55-59		\$ 89.00	\$ 89.00				
1				CHEVY PU			0 %					
1	1	0	0	1104G	INNER DOOR STEP WITH ROCKER RH 55-		\$ 89.00	\$ 89.0				
1	1		V	CHEVY PU		59		0 %	\$ 67.0			
1	1	1	1	0	1153M	67-72 E	XTERIOR MIRROR	ARM	\$ 26.00	\$ 26.00		
1	1		U	CHEVY PU		LHSTAINLESS		0 %	Ψ 20.0			
1	0	0	,	1	1153P	67-72 E	XTERIOR MIRROR	ARM	\$ 26.00	\$ 0.00		
1	v		1	CHEVY PU		RHSTAINLESS		0 %	\$ 0.00			
1	1	1 0	1 0	1 0	1	0	1153L	67-72 FXTFR	IOR MIRROR ARM	BLACKIH	\$ 17.00	\$ 17.00
1			Ů	CHEVY PU	VY PU 07-72 EXTERIOR WIRROR THRIVI BENEF	DL/ICK LI	0 %					
1	1	1	0	1153N	67-72 EXTERIOR MIRROR ARM BLACK RH		\$ 17.00	\$ 17.00				
1			Ŭ	CHEVY PU	0, 72 E211EN	aon minaon man	DE ICIX IXI	0 %	Ψ17.00			
2	,	2	0	LP21	54-55 TAIL LAMP ASSY BLK /		\$ 33.00	\$ 66.00				
2			U	CHEVY PU		STAINLESSBEZEL		0 %	φ 00.00			
									CONTINUE			

INVOICE 63815

GOLDEN LEAF AUTOMOTIVE

170 ZENWAY BLVD UNIT#2 WOODBRIDGE, ONTARIO L4H 2Y7 TELEPHONE 905/850-3433

BILL TO:

WALKER AUTO PARTS 1170 SANFORD STREET WINNIPEG MB R3E 2Z9 TELEPHONE: 204/775-2222 **INVOICE DATE 2017-11-14**

PAGE: 5

SHIP TO: WALKER AUTO PARTS 1170 SANFORD STREET WINNIPEG, MB R3E 2Z9 CANADA

*** INVOICE ***

CUSTOM	IER	R SHIP VIA		F.O.B	TERMS	PO NUMBER	SALES	DATE	OUR ORDER#							
W0004	1	BEST		ORIGIN	NET 10TH	WK OF OCT 30TH	M	2017-10-30	51739							
ODDED	CIT	TD	n o	ITEM	177	THE A DESCRIPTION			EVE DDICE							
ORDER	SH	IP	B.O.	MAKE	11	TEM DESCRIPTION	\	DIS%	EXT.PRICE							
2.	2 1		1	1	1	1			1	1	LP23	55-59	TAIL LAMP ASSY E	LK /	\$ 33.00	\$ 33.00
	1		1	CHEVY PU	STAINLESSBEZEL			0 %	\$ 55.00							
2.	0		2.	LP61	TAILIA	MP ASSY 60-66 FLE	ETCIDE	\$ 38.00	\$ 0.00							
	U		2	CHEVY PU	I AIL LA	WIP ASS 1 00-00 FLE	EISIDE	0 %	\$ 0.00							
4	4	4	4	0	LP47	60.72 TAIL	LAMP BEZEL FLEETSIDE RH		\$ 16.00	\$ 64.00						
4	4			CHEVY PU	09-72 TAIL LAWF BEZEL FLEETSIDI		ISIDE KII	0 %	\$ 04.00							
4	4	4			LP48	60.72 TAIL	LAMP BEZEL FLEETSIDE LH		\$ 16.00	\$ 64.00						
4	4		0	CHEVY PU	09-72 TAIL	LAMP BEZEL FLEE	I SIDE LH	0 %	\$ 04.00							

SHIP BY : WESTERN CANADA EXPRESS. TRACKING NUMBER : 11245211731 NUMBER OF PACKAGE: 2 SKIDS

CURRENCY: NOTE :

 SHIPPING:
 \$ 0.00

 NON-TAXABLE SUBTOTAL
 0

 TAXABLE SUBTOTAL
 \$ 4,357.00

 TAX @ 5 %
 \$ 217.85

 TOTAL:
 \$ 4,574.85