VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-10-11	CEVA	ORGIN	2017-10-12

CONTAINER 71011 DETAILS

PO# ITEM	DESCRIPTION	VPART NO.	VPART NO.		FOR	EXT	
	ITEM	DESCRIPTION	MAKE	SHIP QTY	LOCATION	FOB	COST
3316 1103	DOOR SHELL LH 67-7172 HAS		3	031	\$167.16	\$501.60	
3310	3310 1103	HOLE FOR VENT WINDOW	CHEVY PU	3	031	\$467.46	\$301.00
3311	1103D	DOOR SHELL LH 55-59	CHEVY PU	4	N11	\$780.00	\$1,014.96
2214	1102DI	55-59 ROOF FRONT FILLER		- 6	C74	\$139.44	\$139.44
3314	3314 1103DJ	BRACE	CHEVY PU				
3306	3306 1103DK	55-59 EXTERIOR WINDSHIELD		1	E102	\$84.00	\$86.72
3300	1103DK	SUNVISOR	CHEVY PU				
3303	1103DL	47-53 WINDSHIELD SUNVISOR		_ 1	B92	\$8.82	\$8.92
	1103DL	BRACKETRH	CHEVY PU		D74	φ0.02	φο.92
3306	3306 1103DN	54-55 WINDSHIELD SUNVISOR		_ 1	B92	\$8.82	\$8.92
3300		BRACKETRH 1ST SERIES	CHEVY PU	1		ψ0.02	ψ0.72
3314	1103M	DOOR LATCH LH 47-51	CHEVY PU	2	B32	\$44.22	\$44.22
2206	3306 1103WD	51-54 VENT WINDOW ASSY W /		1	B94	\$123.08	\$124.29
3300		GLASS RHPAINTED	CHEVY PU	1			
3306	3306 1103WE	51-54 VENT WINDOW ASSY W /		_ 1	B94	\$123.56	\$124.77
		GLASS LHPAINTED	CHEVY PU			Ψ123.30	Ψ124.//
3287	3287 1103XL	64-66 VENT WINDOW RH		1	B121	\$178.50	\$180.01
3207	11002112	CHROME	CHEVY PU		10121	Ψ170.50	Ψ100.01
3306	1103Y	DOOR LATCH RH 52-54	CHEVY PU	<u> </u>	B32	\$14.74	\$14.80
3306	1103Z	DOOD LATCHLILES 54		3	B32	642.00	¢44.40
3300	11032	DOOR LATCH LH 52-54	CHEVY PU		B32	\$43.02	\$44.40
3309	1104A	ROCKER PANEL RH 60-66	CHEVY PU	2	C124	\$38.72	\$36.26
3309	1104B	ROCKER PANEL LH 60-66	CHEVY PU	4	C124	\$75.04	\$70.44
2206	1104D 4	73-87 ROCKER PANEL RH OE	TP		E101	#25.26	¢20.25
3306	3306 1104DA	STYLE	CHEVY PU	2	E101	\$25.26	\$28.26

PAGE:5