VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-12-13	CEVA	ORGIN	2017-12-15

CONTAINER 71215 DETAILS

PO#	ITEM	DESCRIPTION	VPART NO. MAKE	SHIP QTY	LOCATION	FOB	EXT COST
		67-69 CONTROL ARM UPPER RH	WIAKE				
3348 1003F	OE STYLE	CAMARO	_ 2	E83	\$70.54	\$74.08	
		67-69 TUBULAR CONTROL ARM	CAMCA01RL		C64	\$106.70	\$109.96
3348	1003H	LOWER RH 68-74 NOVA SS	CAMARO	2			
		67-69 TUBULAR CONTROL ARM	CAMCA01LL				
3348 1003I	LOWER LH 68-74 NOVA SS	CAMARO	2	C64	\$101.60	\$104.28	
22.10	10007	67-69 TUBULAR CONTROL ARM	CAMCA01UR	2	C64	\$71.80	\$73.80
3348 1003J	1003J	UPPER RH 68-74 NOVA SS	CAMARO				
22.40	4000	67-69 TUBULAR CONTROL ARM UPPER LH 68-74 NOVA SS	CAMCA01UL		C64	\$81.04	\$83.04
3348	1003K		CAMARO	_ 2			
3344	1004	67-69 ROOF PANEL	CALLAND	3	L101	\$289.86	\$290.16
	3344 1004	3, 3, 3, 3, 3, 3, 3, 3, 3, 3, 3, 3, 3, 3	CAMARO	2	2101	Ψ207.00	Ψ290.10
3347	1006B	69 EMERGENCY BREAK ASSEMBLY	CAMARO		A75	\$55.74	\$56.44
			CAMARO	+	 		
3316	3346 1006C	67-69 ACCELERATOR ASSEMBLY CABLE STYLE 6 CYL	l l		A75	\$41.54	\$42.22
3340		/ DUAL CARB	CAMARO	2	AIS	Φ41.54	Φ⁴∠.∠∠
		69 FRONT DISC BACKING PLATE		2	G125	\$29.34	\$29.80
3345	3345 1006G	PR69-72 GM A BODY, 69-74 NOVA	CAMARO				
2245	100¢T	67-69 SHOCK MOUNT UPPER		4	A33	¢12.12	¢12.52
3343	3345 1006J	07-09 SHOCK MOUNT UPPER	CAMARO		ASS	\$13.12	\$13.52
3336	1010B	67-68 HORN SET W / WELDED	KEEN	1	F176	\$80.33	\$80.53
		BRACKETS PR	CAMARO			Ψ00.00	+
3336	3336 1010C	69 HORN SET W / WELDED	KEEN	3	F176	\$240.99	\$241.68
		BRACKETS PR	CAMARO				
3344	1020L	70-73 HEADLAMP MOUNTING BRACKET LH		2	A35	\$31.12	\$31.44
			CAMARO			, - ,	
3344	1020R	70-73 HEADLAMP MOUNTING	G.13.5.1.D.0	2	A35	\$31.20	\$31.52
		BRACKET RH	CAMARO		 		
3336	1024	69 DASH AC VENT69-72 NOVA	CAMARO	2	C53	\$16.80	\$17.00
	ļ.	<u> </u>	DACE:1				

PAGE:1