VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-08-11	SS	ORGIN	2017-08-11

PO#	ITEM	DESCRIPTION	VPART NO. MAKE	SHIP QTY	LOCATION	FOB	EXT COST
3274	1041A	INNER WHEELHOUSE LH 67	CAMARO	8	G145	\$180.00	\$208.32
3274	1048L	FR BUMPER INNER EXT. BRACKET LH 69	CAMARO	10	G132	\$43.80	\$44.70
3274	1048ZWT	70-73 TRUNK FLOOR PAN	CAMARO	2	J101	\$370.50	\$428.25
3274	1049	FRONT BUMPER 67-68	3929954 CAMARO	4	F102	\$270.24	\$285.12
3274	1049A	FRONT BUMPER 69	3927422 CAMARO	6	F94	\$350.04	\$416.79
3274	1049LE	67-69 TRUNK LID W/SPOILER HOLES	CAMARO	- 6	F41	\$426.84	\$466.89
3274	1049Y	69 LICENSE PLATE BRACKET	CAMARO	4	F143	\$22.52	\$24.02
3274	1049Z	67-68 LICENSE PLATE BRACKET	CAMARO	8	F143	\$45.04	\$47.16
3274	1050	69 SEAT FRAME SUPPORT, RH.	CAMARO	- 12	B23	\$266.52	\$285.78
3274	1051	69 SEAT FRAME SUPPORT, LH.	CAMARO	12	B22	\$266.52	\$285.78
3274	1052J	67-69 SEAT BOTTOM SPRING RH=LH	CAMARO	4	G115	\$64.72	\$73.06
3274	1064B	GRILLE 67 STANDARD	3891693 CAMARO	2	C65	\$46.94	\$49.43
3274	1064C	GRILLE 68 STANDARD	3914772 CAMARO	3	C54	\$116.82	\$128.85
3274	1064НА	70-71 Z28 & SS GRILLE W/MOLDING	CAMARO	4	C71	\$266.56	\$280.54
3274	1064R	GRILLE STANDARD 69 SILVER	CAMARO	2	C54	\$244.32	\$249.59
3274	10648	GRILLE 69 RS	CAMARO	3	C65	\$210.93	\$230.84
3274	1066B	FULL QUARTER PANEL RH 68 CPE	CAMARO	2	K32	\$299.82	\$364.46

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-08-11	SS	ORGIN	2017-08-11

3274 1066C FULL QUARTER PANEL LH 68 CPE CAMARO 3 K42 \$449.73 \$546.60	PO#	ITEM	DESCRIPTION	VPART NO.	SHIP QTY	LOCATION	FOB	EXT COST
3274 1066C 68 CPE CAMARO 3 K42 3449.73 5346.60 3274 1066U 68 FULL QUARTER PANEL RH COUPE FIREBIRD 2 K33 \$317.76 \$380.98 3274 1066V 68 FULL QUARTER PANEL 7738877 2 K33 \$331.32 \$395.64 3274 1067PB 74-81 REAR VALANCE PANEL CAMARO 2 F64 \$62.38 \$64.12 3274 1075G REAR FILLER(BEHIND RR WINDOW) 70-81 CAMARO 4 C32 \$62.60 \$65.90 3274 1100P 55-56 BATTERY TRAY HOLD DOWN J-BOLT CHEVY PU 10 B34 \$23.70 \$24.15 3274 1154 47-59 INTERIOR REAR VIEW MIRROR CHEVY PU 10 F156 \$100.80 \$101.70 3274 1404 RH OUTSIDE DOOR HANDLE 20099251 78-87 EL CAMINO 4 C52 \$8.84 \$9.20 3274 1462B TRUNK FLOOR CENTER 64/7 CHEVELLE CHEVELLE 4 G183 \$77.96 \$99.12 3274 1462C TRUNK FLOOR CH 64-67 CHEVELLE CHEVELLE 3 G183 \$77.96 \$99.12 3274 1639A 62-64 RADIATOR SUPPORT NOVA 1 F137 \$91.63 \$102.70 3274 1639WT 66-67 RADIATOR SUPPORT NOVA 2 F54 \$224.42 \$239.18 3274 1701A HOOD HINGE RH 63/4 IMPALA, 64/7 GTO IMPALA A94 \$89.24 \$90.98 3274 1701B HOOD HINGE RH 63/4 IMPALA, 64/7 GTO IMPALA A94 \$89.24 \$90.98 3274 1701S 65 TELESCOPING ANTENNA 2 B74 \$60.48 \$50.08 3274 1702X 65 TELESCOPING ANTENNA 2 B74 \$60.48 \$50.08 3274 1702X 65 TELESCOPING ANTENNA 2 B74 \$60.48 \$50.08 3274 1702X 65 TELESCOPING ANTENNA 2 B74 \$60.48 \$50.08 3274 1702X 65 TELESCOPING ANTENNA 2 B74 \$60.48 \$50.08 3274 1702X 65 TELESCOPING ANTENNA 2 B74 \$60.48 \$50.08 3274 1702X 65 TELESCOPING ANTENNA 2 B74 \$60.48 \$50.08 3274 1702X 65 TELESCOPING ANTENNA 2 B74 \$60.48 \$50.08 3274 1702X 65 TELESCOPING ANTENNA 2 B74 \$60.48 \$50.08 3274 1702X 65 TELESCOPING ANTENNA 2 B74 \$60.48 \$50.08 3274 1702X 65 TELESCOPING ANTENNA 2 B74 \$60.48 \$50.08 3274 1702X 65 TELESCOPING ANTENNA 2 B74	ΓΟ#	TIENI	DESCRIPTION	MAKE	Silir Q11	LOCATION	гов	EAT COST
3274 1066U 68 FULL QUARTER PANEL RH COUPE FIREBIRD 2 K33 S317.76 S380.98	3274	1066C			3	к42	\$449.73	\$546.60
3274 1066U RH COUPE FIREBIRD 2 K33 S317.76 S380.98 3274 1066V 68 FULL QUARTER PANEL T738877 FIREBIRD 2 K33 S331.32 S395.64 3274 1067PB 74-81 REAR VALANCE PANEL CAMARO 2 F64 S62.38 S64.12 3274 1075G REAR FILLER(BEHIND RR WINDOW) 70-81 CAMARO 4 C32 S62.60 S65.90 3274 1100P 55-56 BATTERY TRAY HOLD DOWN 1-BOLT CHEVY PU 10 B34 S23.70 S24.15 3274 1154 47-59 INTERIOR REAR VIEW MIRROR CHEVY PU 10 F156 S100.80 S101.70 3274 1404 RH OUTSIDE DOOR HANDLE 78-87 EL CAMINO 4 C52 S8.84 S9.20 3274 1405 LH OUTSIDE DOOR HANDLE 78-87 EL CAMINO 4 C52 S8.84 S9.20 3274 1462B TRUNK FLOOR CENTER 64/7 CHEVELLE CHEVELLE CHEVELLE CHEVELLE CHEVELLE 3 G183 S77.96 S99.12 3274 1462C TRUNK FLOOR LH 64-67 CHEVELLE CHEVELLE CHEVELLE CHEVELLE 3 G183 S58.50 S76.72 3274 1639A 62-64 RADIATOR SUPPORT NOVA 1 F137 S91.63 S102.70 3274 1639WT 66-67 RADIATOR SUPPORT NOVA 2 F54 S224.42 S239.18 3274 1701A HOOD HINGE RH 63/4 IMPALA,64/7 GTO IMPALA A94 S89.24 S90.98 3274 1701B HOOD HINGE LH 63/4 IMPALA,64/7 GTO IMPALA A94 S89.24 S90.98 3274 1701X 1701X 65 TELESCOPING ANTENNA 2 B74 S60.48 S60.48 S60.08 S6	3274	10000	68 CPE			13.42	ψττ2.13	φυ+0.00
3274 1066V 68 FULL QUARTER PANEL T738877 FIREBIRD 2 K33 \$331.32 \$395.64	3274	106611			2	К33	\$317.76	\$380.98
3274 1066V	3271	10000	RH COUPE			1100	ψ317.70	ψ300.90
1067PB	3274	1066V	_	7738877	2	K33	\$331.32	\$395.64
1067PB		1000,	LH COUPE	FIREBIRD	_	1100	\$551.5 2	ψ5/5101
3274 1075G REAR FILLER (BEHIND RR WINDOW) 70-81 CAMARO	3274	1067PB			2	F64	\$62.38	\$64.12
1078G WINDOW) 70-81 CAMARO 4 C32 \$62.60 \$63.90		100712	PANEL	CAMARO	_	10.	ψο 2. εσ	ψο12
3274 1100P 55-56 BATTERY TRAY HOLD DOWN J-BOLT CHEVY PU 10 B34 \$23.70 \$24.15	3274	1075G	`		4	C32	\$62.60	\$65.90
1100P DOWN J-BOLT CHEVY PU 10 B34 \$23.70 \$24.15 3274 1154 47-59 INTERIOR REAR VIEW MIRROR CHEVY PU 10 F156 \$100.80 \$101.70 3274 1404 RH OUTSIDE DOOR HANDLE 78-87 EL CAMINO EL CAM	3214	10750	WINDOW) 70-81	CAMARO	,	C32	Ψ02.00	ψ03.70
3274 1154 47-59 INTERIOR REAR VIEW MIRROR CHEVY PU 10 F156 \$100.80 \$101.70	3274	1100P			10	R34	\$23.70	\$24.15
1154 MIRROR CHEVY PU 10	3214	11001	DOWN J-BOLT	CHEVY PU	10	D 34	Ψ23.70	Ψ24.13
3274 1404 RH OUTSIDE DOOR HANDLE 78-87 EL CAMINO Sep. 20	3274	1154			10	F156	\$100.80	\$101.70
1404 178-87 EL CAMINO 4 C52 \$8.84 \$9.20	3214	1134	MIRROR	CHEVY PU	10	1130	Ψ100.00	Ψ101.70
3274 1405	3274	1404	RH OUTSIDE DOOR HANDLE	20099250	4	C52	\$8.84	\$9.20
1405 78-87 EL CAMINO 4 C52 \$8.84 \$9.20	3214	1404	78-87	EL CAMINO		C32	ψ0.04	\$7.20
3274 1462B TRUNK FLOOR CENTER 64/7 CHEVELLE CHEVELLE CHEVELLE 3 G183 \$77.96 \$99.12	3274	1405	LH OUTSIDE DOOR HANDLE	20099251	4	C52	\$8.84	\$9.20
32/4 1462B CHEVELE CHEVELLE 4 G183 \$77.96 \$99.12 3274 1462C TRUNK FLOOR LH 64-67 CHEVELLE 3 G183 \$58.50 \$76.72 3274 1573 70-72 REAR BUMPER GTO 4 F123 \$792.08 \$824.60 3274 1639A 62-64 RADIATOR SUPPORT NOVA 1 F137 \$91.63 \$102.70 3274 1639WT 66-67 RADIATOR SUPPORT NOVA 2 F54 \$224.42 \$239.18 3274 1701A HOOD HINGE RH 63/4 IMPALA 3825828 6 A94 \$133.86 \$136.47 3274 1701B HOOD HINGE LH 63/4 IMPALA 3825827 4 A94 \$89.24 \$90.98 3274 1702X 65 TELESCOPING ANTENNA 2 B74 \$60.48 \$61.08	3214	1403	78-87	EL CAMINO	7	C32	C32 \$6.64	Ψ7.20
CHEVELE CHEVELLE 3274 1462C TRUNK FLOOR LH 64-67 CHEVELLE 3 G183 \$58.50 \$76.72 3274 1573 70-72 REAR BUMPER GTO 4 F123 \$792.08 \$824.60 3274 1639A 62-64 RADIATOR SUPPORT NOVA 1 F137 \$91.63 \$102.70 3274 1639WT 66-67 RADIATOR SUPPORT NOVA 2 F54 \$224.42 \$239.18 3274 1701A HOOD HINGE RH 63/4 IMPALA 3825828 6 A94 \$133.86 \$136.47 3274 1701B HOOD HINGE LH 63/4 IMPALA 3825827 4 A94 \$89.24 \$90.98 3274 1702X 65 TELESCOPING ANTENNA 2 B74 \$60.48 \$61.08	3274	1462R				C183	\$77.96	\$99.12
32/4 1462C CHEVELLE CHEVELLE 3 G183 \$58.50 \$76.72 3274 1573 70-72 REAR BUMPER GTO 4 F123 \$792.08 \$824.60 3274 1639A 62-64 RADIATOR SUPPORT NOVA 1 F137 \$91.63 \$102.70 3274 1639WT 66-67 RADIATOR SUPPORT NOVA 2 F54 \$224.42 \$239.18 3274 1701A HOOD HINGE RH 63/4 IMPALA 3825828 6 A94 \$133.86 \$136.47 3274 1701B HOOD HINGE LH 63/4 IMPALA 3825827 4 A94 \$89.24 \$90.98 3274 1702X 65 TELESCOPING ANTENNA 2 B74 \$60.48 \$61.08	3214	1402D	CHEVELE	CHEVELLE		0105	\$77.50	Ψ77.12
CHEVELLE CHEVELLE CHEVELLE CHEVELLE 3274 1573 70-72 REAR BUMPER GTO 4 F123 \$792.08 \$824.60 3274 1639A 62-64 RADIATOR SUPPORT NOVA 1 F137 \$91.63 \$102.70 3274 1639WT 66-67 RADIATOR SUPPORT NOVA 2 F54 \$224.42 \$239.18 3274 1701A HOOD HINGE RH 63/4 IMPALA 3825828 6 A94 \$133.86 \$136.47 3274 1701B HOOD HINGE LH 63/4 IMPALA 3825827 4 A94 \$89.24 \$90.98 3274 1702X 65 TELESCOPING ANTENNA 2 B74 \$60.48 \$61.08	3274	1462C	TRUNK FLOOR LH 64-67		3	C183	\$58.50	\$76.72
3274 1639A 62-64 RADIATOR SUPPORT NOVA 1 F137 \$91.63 \$102.70 3274 1639WT 66-67 RADIATOR SUPPORT NOVA 2 F54 \$224.42 \$239.18 3274 1701A HOOD HINGE RH 63/4 IMPALA, 64/7 GTO 3825828 IMPALA 6 A94 \$133.86 \$136.47 3274 1701B HOOD HINGE LH 63/4 IMPALA 3825827 IMPALA 4 A94 \$89.24 \$90.98 3274 1702X 65 TELESCOPING ANTENNA 2 B74 \$60.48 \$61.08	3274	14020	CHEVELLE	CHEVELLE	3	G103	\$36.30	\$70.72
3274 1639A 62-64 RADIATOR SUPPORT NOVA 1 F137 \$91.63 \$102.70 3274 1639WT 66-67 RADIATOR SUPPORT NOVA 2 F54 \$224.42 \$239.18 3274 1701A HOOD HINGE RH 63/4 IMPALA 3825828 6 A94 \$133.86 \$136.47 3274 1701B HOOD HINGE LH 63/4 IMPALA 3825827 4 A94 \$89.24 \$90.98 3274 1702X 65 TELESCOPING ANTENNA 2 B74 \$60.48 \$61.08	3274	1573	70-72 REAR BUMPER	GTO	4	F123	\$792.08	\$824.60
3274 1639WT 66-67 RADIATOR SUPPORT NOVA 2 F54 \$224.42 \$239.18 3274 1701A HOOD HINGE RH 63/4 IMPALA, 64/7 GTO IMPALA 3274 1701B HOOD HINGE LH 63/4 IMPALA, 64/7 GTO IMPALA 3274 1701B HOOD HINGE LH 63/4 IMPALA, 64/7 GTO IMPALA 3274 1702X 65 TELESCOPING ANTENNA 2 B74 \$60.48 \$61.08	3274	1639A	62-64 RADIATOR SUPPORT		1	F137	\$91.63	\$102.70
3274 1701A HOOD HINGE RH 63/4 IMPALA,64/7 GTO IMPALA 3274 1701B HOOD HINGE LH 63/4 IMPALA,64/7 GTO IMPALA 3274 1701B HOOD HINGE LH 63/4 IMPALA,64/7 GTO IMPALA 3274 1702X 65 TELESCOPING ANTENNA 2 B74 \$60.48 \$61.08		100311	02 0 110 12 111 010 2011 0101	NOVA		1107	Ψ, 1.05	Ψ10 2 ., 0
3274 1701A IMPALA,64/7 GTO IMPALA 3274 1701B HOOD HINGE LH 63/4 IMPALA,64/7 GTO IMPALA 3274 1701B 65 TELESCOPING ANTENNA 3274 1702X 65 TELESCOPING ANTENNA 2 B74 \$60.48 \$61.08	3274	1639WT	66-67 RADIATOR SUPPORT	NOVA	2	F54	\$224.42	\$239.18
IMPALA,64/7 GTO	3274	2274 1 701 A	HOOD HINGE RH 63/4	3825828		1 494	\$122.86	\$136.47
3274 1701B IMPALA,64/7 GTO IMPALA 4 A94 \$89.24 \$90.98 3274 1702X 65 TELESCOPING ANTENNA 2 B74 \$60.48 \$61.08	3274	1/01A	IMPALA,64/7 GTO	IMPALA	U	A)7	\$155.60	\$130.47
3274 1702X 65 TELESCOPING ANTENNA 2 B74 \$60.48 \$61.08	2274	1701D	HOOD HINGE LH 63/4	3825827		A 0.4	\$90.24	\$00.00
32/4 1702X	3214	1/01B	IMPALA,64/7 GTO	IMPALA	-	A34	φο9.24 	φ90.98
32/4 1/02A WITH CABLE IMPALA 2 B/4 \$00.48 \$01.08	2274	1702V	65 TELESCOPING ANTENNA			P74	¢60.49	¢61.00
**************	3214	1/02A	WITH CABLE	IMPALA		B/4	\$60.48	\$61.08

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-08-11	SS	ORGIN	2017-08-11

PO#	ITEM	DESCRIPTION	VPART NO. MAKE	SHIP QTY	LOCATION	FOB	EXT COST
3274	1710K	67 PARKING LAMP LENS PR	IMPALA	1	A81	\$7.56	\$7.63
3274	1781Z	65 TAIL PANEL BRACE	IMPALA	2	F121	\$114.54	\$116.38
3274	3616G	66 GLOVE BOX LATCH	MUSTANG	2	B74	\$17.82	\$18.66
3274	3640Y	69-70 DOOR SHELL RH	MUSTANG	8	G03	\$1,463.20	\$1,573.44
3274	3640Z	69-70 DOOR SHELL LH	MUSTANG	6	G02	\$1,093.26	\$1,169.22
3274	4009	55-57 ACCELERATOR PEDAL	CHEVROLET	4	A81	\$40.32	\$38.52
3274	EM4676	70 "CHEVELLE BY CHEVROLET" TRUNK EM	CHEVELLE	4		\$99.20	\$99.56
3274	L70A	70 PARKING LAMP ASSEMBLY EACH RH/LH	CHEVELLE	14	A12	\$311.50	\$312.55
3274	L70F	70 LOWER FENDER LAMP PAIR	CHEVELLE	6	A13	\$109.50	\$110.94
3274	LP31A	67-72 TAIL LAMP ASSY STAINLESS	CHEVY PU	8	A15	\$235.20	\$236.88
3274	M1414	GRILLE MOLDING UPPER 72	6261909 CHEVELLE	4	A101	\$33.52	\$34.12
3274	M1415	GRILLE MOLDING CENTER 72 (2 PER CAR	6261925 CHEVELLE	4	A101	\$33.84	\$35.46
3274	M1416	GRILLE MOLDING LOWER 72	6261910 CHEVELLE	4	A101	\$33.12	\$35.46
3274	M1440A	68-70 DOME LIGHT LENS	CHEVELLE	10	A27	\$13.90	\$14.20
3274	M1440D	68-70 DOME LIGHT BASE	CHEVELLE	12	A27	\$104.04	\$104.58
3274	M1600	OUTSIDE DOOR HANDLE 1962-65 PAIR	NOVA	3	A32	\$65.43	\$65.70
3274	M1604	INSIDE DOOR HANDLE DLB ARM	NOVA	12	A32	\$51.00	\$50.76

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-08-11	SS	ORGIN	2017-08-11

PO#	ITEM	DESCRIPTION	VPART NO. MAKE	SHIP QTY	LOCATION	FOB	EXT COST
3274	M3692B	1965-66 WINDOW ROLLER & CLIP 50 PC	MUSTANG	4	A113	\$37.92	\$38.10
	•				TOTAL	\$10251.14	\$11160.08