VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-11-22	CEVA	ORGIN	2017-11-21

CONTAINER 71121 DETAILS

PO# ITEM	DESCRIPTION	VPART NO.	CHID OTY	LOCATION	EOD	EXT	
	II EWI	DESCRIPTION	MAKE	7SHIP QI Y	LOCATION	FOB	COST
3335 M1451	RADIATOR SUPPORT BUSHING		- 5	C52	\$34.55	\$35.05	
	68-72A-BODY ONLY	CHEVELLE					
3335	3335 M1452	BODY BUSHING 64-67 H / T ,10		5	C51	\$121.45	\$121.95
3333 1411452	SETS KIT	CHEVELLE	3	CSI	\$121.43	\$121.93	
3338	M1461	VINYL TOP MOLDING 66-67 4PC		2	A111	\$108.58	\$109.00
3330	1/11-101	/ SETGTO 66-67 (NO CLIPS)	CHEVELLE				
3333	M1600A	1966-67 OUTSIDE DOOR		3	C62	\$65.49	\$65.79
3333 WIIOUA	HANDLE PAIR	NOVA		C02	φυσ.49	φυ3.79	
3320	3320 M1628	DRIP RAIL MOLDING 1966-67 (2		3	B51	\$98.31	\$99.57
3320		PC)	NOVA				
3306	M1630B	73-74 HOOD MOLDING	NOVA	1	A111	\$30.33	\$30.51
3324	M1648	PARK LAMP ASSY RH=LH 71-		3	A15	\$65.34	\$65.64
3324	W11040	72AMBER	NOVA	<u> </u>			
3333	3332 M1649B	70-74 REAR SIDE MARKER		2	A27	\$14.26	\$14.46
3332		BEZEL	NOVA				
3334	3334 М1705Н	62-64 REAR WINDOW MOLDING		1	B63	\$9.30	\$9.40
3334		CLIPS 6PCHARD TOP ONLY	IMPALA	1			
3334	3334 M1717E	DOOR WINDOW LOWER FRAME		3	A33	\$66.51	\$67.35
3334		RH 61-64	IMPALA	,			
3334	3334 M1717F	DOOR WINDOW LOWER FRAME		2	A33	\$44.34	\$44.90
3334 WII/I/F	LH 61-64	IMPALA		ASS	Ψ++.J4	Ψ44.20	
3334	3334 M1724N	REAR WINDOW MOLDING 62-64		1	B41	\$80.01	\$81.23
3334 W11724N	5PC	IMPALA	1	D-11	ψου.01	Ψ01.23	
3335 M1728 C	67-68 BODY BUSHING KIT W /		2	C51	\$93.90	\$94.40	
3333	1117200	BOLTS CONV	IMPALA			Ψ/3.90	Ψ/4.40
3314	M3509A	67-70 FOLDDOWN LATCH FB RH	MUSTANG	2	B23	\$39.28	\$39.48
3332 M3514	M2514	QUARTER PANEL ORNAMENT	C6ZZ65290A76/7A	2	В33	\$43.06	\$43.38
	66 PAIR	MUSTANG		Вээ	\$45.00	\$45.58	

PAGE:19