VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-08-14	1	ORGIN	2017-08-14

CONTAINER 70814B DETAILS

PO#	ITEM	DESCRIPTION	VPART NO. MAKE	SHIP QTY	LOCATION	FOB	EXT COST
3293	1097QF	55-57 FENDER REAR LOWER PANEL LH	CHEVY PU	1	D104	\$16.64	\$16.64
3293	1102BT	67-72 FRONT LOWER DOOR PILLAR LH	CHEVY PU	2	C74	\$10.36	\$10.36
3293	1102BU	67-72 REAR LOWER DOOR PILLAR RH	CHEVY PU	2	C74	\$12.18	\$12.18
3293	1104DA	73-87 ROCKER PANEL RH OE STYLE	TP CHEVY PU	3	E101	\$34.92	\$34.92
3293	1104G	INNER DOOR STEP WITH ROCKER RH	CHEVY PU	2	C91	\$81.84	\$81.84
3293	1106B	47-54 FIRE WALL	CHEVY PU	3	G142	\$389.19	\$389.19
3293	1114Z	67-72 FOOT WELL PANEL LH	CHEVY PU	2	D93	\$14.30	\$14.30
3293	1462E	TRUNK FLOOR CENTER 68- 72 A BODY	CHEVELLE	2	G182	\$38.22	\$38.22
3293	20030351	71-81 DOME LIGHT BASE	CAMARO	2	A26	\$9.98	\$9.98
			TOTAL	\$607.63	\$607.63		

PAGE:1