VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-26	1	ORGIN	2017-09-26

3312   106M   77-81 FRONT DISC BRAKE BRACKET PR   CAMARO   4   D83   S83.72   S83.73   S83.73   S83.72   S83.73   S83.	PO#	ITEM	DESCRIPTION	VPART NO.	CHID OTV	LOCATION	FOB	EXT
3312   1049W   67-73 BUMPER BOLT BULK PACKSO PCS(3 /8" X 1")   CAMARO   8   D91   \$164.00   \$164.00   \$164.00   \$312   1067QA   70-81 CROSS MEMBER TRANNY SUPPORTTURBO 400 TRAN.   CAMARO   4   G143   \$110.68   \$110.	PO#	IIEMI	DESCRIPTION	MAKE		LUCATION	гов	COST
3312   1068G	2212	100¢M	77-81 FRONT DISC BRAKE			D03	¢02.70	¢02.70
3312   1067QA   70-81 CROSS MEMBER TRANNY SUPPORTTURBO 400 TRAN.   CAMARO	3312	1000101	BRACKET PR	CAMARO	4	роз	\$63.72	\$65.72
3312   1068Q   TO-81 CROSS MEMBER TRANNY SUPPORTTURBO 400 TRAN.   CAMARO	2212	1040337	67-73 BUMPER BOLT BULK		Q	D01	\$164.00	\$164.00
3312   1068G	3312	1049 W	PACK50 PCS(3 / 8" X 1")	CAMARO	o	D91	\$104.00	\$104.00
3312   1068Q	2212	106701	70-81 CROSS MEMBER TRANNY		<b>」</b>	C1/12	\$110.69	¢110.69
1068G	3312	1007QA	SUPPORTTURBO 400 TRAN.	CAMARO	4	G143	\$110.06	\$110.00
3312   1068H   HOOD HINGE LH 67 / 9   CAMARO	2212	10680	HOOD HINGE RH 67 / 9			A 0.1	\$442.20	\$442.20
3312   1068H   CAMARO,65 / 7 IMPA   CAMARO   20   A91   \$442.20   \$442.20   \$442.21   \$442.20   \$442.21   \$442.22	3312	1000G	CAMARO,65 / 7 IMPA	CAMARO	20	A91	\$442.20	\$442.20
1068Q   67-73 HOOD SAFETY LATCH BLACK   CAMARO   6   A133   \$71.28   \$71.29	3312	106811	HOOD HINGE LH 67 / 9			A 01	\$442.20	\$442.20
3312   1071   HOOD COWL VENT GRILLE70-73   CAMARO   CAM	3312	100011	CAMARO,65 / 7 IMPA	CAMARO	20	A91	\$442.20	\$442.20
3312   1071   HOOD COWL VENT GRILLE70-73   CAMARO   4   E105   \$266.44   \$266.44   \$266.44   \$312   1096   47-54 GMC BUMPER FILLERGMC ONLY   CHEVY PU   6   F135   \$284.52   \$284.53   \$312   1096E   GRILLE UPPER BAR 57 CHEVY ONLY   CHEVY PU   2   A65   \$52.66   \$52.66   \$52.66   \$52.66   \$312   1097G   68-72 REAR FENDER STEPSIDE RH   CHEVY PU   6   N33   \$1,738.80   \$1,738.80   \$1,738.80   \$312   1097H   68-72 REAR FENDER STEPSIDE LH   CHEVY PU   6   N32   \$1,750.02   \$1,750.03   \$1312   1099G   INNER FENDER RH 67-72   CHEVY PU   8   J161   \$218.48   \$218.44   \$312   1099H   INNER FENDER LH 67-72   CHEVY PU   4   J161   \$109.40   \$109.40   \$312   1103DJ   55-59 ROOF FRONT FILLER BRACE   CHEVY PU   12   C74   \$281.76	2212	10690	67-73 HOOD SAFETY LATCH			A 122	¢71.20	¢71.00
3312   1096   47-54 GMC BUMPER FILLERGMC ONLY   CHEVY PU   6   F135   \$284.52   \$284.52   \$284.52   \$3312   1096E   GRILLE UPPER BAR 57 CHEVY ONLY   CHEVY PU   2   A65   \$52.66   \$52.66   \$52.66   \$52.66   \$3312   1097G   68-72 REAR FENDER STEPSIDE RH   CHEVY PU   6   N33   \$1,738.80   \$1,738.80   \$1,738.80   \$3312   1097H   68-72 REAR FENDER STEPSIDE LH   CHEVY PU   6   N32   \$1,750.02   \$1,750.02   \$1,750.02   \$3312   1099G   INNER FENDER RH 67-72   CHEVY PU   8   J161   \$218.48   \$218.49   \$3312   1099H   INNER FENDER LH 67-72   CHEVY PU   4   J161   \$109.40   \$109.40   \$3312   1103DJ   55-59 ROOF FRONT FILLER BRACE   CHEVY PU   12   C74   \$281.76   \$28	3312	1000Q	BLACK	CAMARO	<b>O</b>	A133	\$/1.20	\$/1.28
3312   1096   47-54 GMC BUMPER FILLERGMC ONLY   CHEVY PU   6   F135   \$284.52   \$284.52   \$284.52   \$3312   1096E   GRILLE UPPER BAR 57 CHEVY ONLY   CHEVY PU   2   A65   \$52.66   \$52.66   \$52.66   \$52.66   \$3312   1097G   68-72 REAR FENDER STEPSIDE RH   CHEVY PU   6   N33   \$1,738.80   \$1,738.80   \$1,738.80   \$3312   1097H   68-72 REAR FENDER STEPSIDE LH   CHEVY PU   6   N32   \$1,750.02   \$1,750.02   \$1,750.02   \$3312   1099G   INNER FENDER RH 67-72   CHEVY PU   8   J161   \$218.48   \$218.48   \$3312   1099H   INNER FENDER LH 67-72   CHEVY PU   4   J161   \$109.40   \$109.40   \$3312   1103DJ   55-59 ROOF FRONT FILLER BRACE   CHEVY PU   12   C74   \$281.76   \$28	3312	1071	HOOD COWL VENT GRILLE70-73	CAMARO	4	E105	\$266.44	\$266.44
3312   1096   ONLY   CHEVY PU   6   F135   \$284.52   \$284.52   \$284.52   \$3312   1097G   68-72 REAR FENDER STEPSIDE RH   CHEVY PU   6   N33   \$1,738.80   \$1,738.80   \$1,738.80   \$1,738.80   \$1,750.02   \$1,750				CAMARO			7-00111	+
3312   1096E   GRILLE UPPER BAR 57 CHEVY ONLY   CHEVY PU   2   A65   \$52.66   \$52.66     3312   1097G   68-72 REAR FENDER STEPSIDE RH   CHEVY PU   6   N33   \$1,738.80   \$1,738.80     3312   1097H   68-72 REAR FENDER STEPSIDE LH   CHEVY PU   6   N32   \$1,750.02   \$1,750.02     3312   1099G   INNER FENDER RH 67-72   CHEVY PU   8   J161   \$218.48   \$218.49     3312   1099H   INNER FENDER LH 67-72   CHEVY PU   4   J161   \$109.40   \$109.40     3312   1103DJ   55-59 ROOF FRONT FILLER BRACE   CHEVY PU   12   C74   \$281.76   \$281.76     3313   3314   3315   CHEVY PU   C74   \$281.76	3312	1096	1	CHEVY DII	6	F135	\$284.52	\$284.52
3312   1097G   68-72 REAR FENDER STEPSIDE RH   CHEVY PU   6   N33   \$1,738.80   \$1,738.80   \$1,738.80   \$1,738.80   \$1,738.80   \$1,738.80   \$1,750.02   \$1,750.0				CHEVYPU				
3312   1097G   68-72 REAR FENDER STEPSIDE RH   CHEVY PU   6   N33   \$1,738.80   \$1,738.80   \$1,738.80   \$1,738.80   \$1,738.80   \$1,738.80   \$1,750.02   \$1,750.0	3312	1096E	I -	CHEVY DI	_ 2	A65	\$52.66	\$52.66
3312   1097G   RH   CHEVY PU   6   N33   \$1,738.80				CHEVYPU				
3312   1097H   68-72 REAR FENDER STEPSIDE   CHEVY PU   6   N32   \$1,750.02	3312	1097G	I	CHEVY DI	6	N33	\$1,738.80	\$1,738.80
3312 1099G INNER FENDER RH 67-72 CHEVY PU 8 J161 \$218.48 \$218.44 \$3312 1099H INNER FENDER LH 67-72 CHEVY PU 4 J161 \$109.40 \$109.40 \$3312 1103DJ 55-59 ROOF FRONT FILLER BRACE CHEVY PU 12 C74 \$281.76 \$281.76 \$281.76 \$281.76				CHEVYPU				
3312 1099G INNER FENDER RH 67-72 CHEVY PU 8 J161 \$218.48 \$218.44  3312 1099H INNER FENDER LH 67-72 CHEVY PU 4 J161 \$109.40 \$109.40  3312 1103DJ 55-59 ROOF FRONT FILLER BRACE CHEVY PU 12 C74 \$281.76 \$281.76	3312	1097H	I	CHEVY DII	6	N32	\$1,750.02	\$1,750.02
3312 1099H INNER FENDER LH 67-72 CHEVY PU 4 J161 \$109.40 \$109.40  3312 1103DJ 55-59 ROOF FRONT FILLER BRACE CHEVY PU 12 C74 \$281.76 \$281.76			LII	CHEVYPU				
3312 1103DJ 55-59 ROOF FRONT FILLER BRACE CHEVY PU 12 C74 \$281.76 \$281.76	3312	1099G	INNER FENDER RH 67-72	CHEVY PU	8	J161	\$218.48	\$218.48
3312 1103DJ 55-59 ROOF FRONT FILLER BRACE CHEVY PU 12 C74 \$281.76 \$281.76	3312	1099Н	INNER FENDER LH 67-72	CHEVY DI	4	J161	\$109.40	\$109.40
3312 1103DJ BRACE CHEVY PU 12 C74 \$281.76 \$281.76				CHEVYPU				,
2212 1103M DOOD I ATCH I I 47 51 4 D22 600 44 600 4	3312	1103DJ	I	CHEAN DIT	12	C74	\$281.76	\$281.76
3312   1103M   DOOR LATCH I H 47-51   4   R32   \$88.44   \$88.45			BRACE	CHEVY PU				
5512   110511   DOOK LATCH LIT 47-51   CHEVY PU   4   D32   \$600.44   \$600.44	3312	1103M	DOOR LATCH LH 47-51	CHEVY PU	4	B32	\$88.44	\$88.44

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-26	1	ORGIN	2017-09-26

PO#	ITEM	DESCRIPTION	VPART NO. MAKE	SHIP QTY	LOCATION	FOB	EXT COST
3312	1104LE	67-72 BED STEP FOR SHORTBED,PAINTEDRH	CHEVY PU	2	C125	\$105.00	\$105.00
3312	1104P	68-72 VENT WINDOW ASSY RHCLEAR GLASS-WILL FIT 67-	CHEVA DI	2	B102	\$258.44	\$258.44
3312	1106W	SEE NOTE 67-72 WIPER TRANSMISSION	CHEVY PU	4	B102	\$163.44	\$163.44
3312	1107W	ARMSPR 47-50 BED REAR CROSS BRACE9	CHEVY PU	_ 2	F34	\$109.20	\$109.20
3312	1109JD	BOARD FLOOR 60-66 LOWER FENDER BRACE	CHEVY PU	4	B92	\$71.72	\$71.72
3312	1109KD	REAR RH 60-66 LOWER FENDER BRACE	CHEVY PU	2	B92	\$35.82	\$35.82
3312	1109R	REAR LH HOOD HINGE RH 47-55	CHEVY PU  CHEVY PU	4	A95	\$72.00	\$72.00
3312	1114E	CAB CORNER RH 67-72	CHEVY PU	14	C122 / C123	\$87.64	\$87.64
3312	1114F	CAB CORNER LH 67-72	CHEVY PU	- 8	C122 / C123	\$49.28	\$49.28
3312	1114I	47-53 DASH SPEAKER GRILLECHEVY W / ASH TRAY	CHEVY PU	4	A133	\$255.36	\$255.36
3312	1115I	HEADLAMP BEZEL 47-55 PAIR	CHEVY PU	8	A63	\$94.72	\$94.72
3312	1135	55-57 HOOD LATCH	CHEVY PU	14	A35	\$337.12	\$337.12
3312	1151C	47-72 ROUND MIRROR STAINLESS 5-5 / 8"SMOOTH	CHEVY PU	14	F164	\$117.60	\$117.60
3312	1153B	47-55 EXTERIOR MIRROR ARM BLACK RH	CHEVY PU	4	F174	\$40.32	\$40.32
3312	1402EWT	64-72 SEAT MOUNTING RAIL 4PCS SET* WTP *	CHEVELLE	6	A104	\$103.68	\$103.68

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-26	1	ORGIN	2017-09-26

PO#	ITEM	DESCRIPTION	VPART NO.	CHID OTV	LOCATION	FOB	EXT
ro#	IIEMI	DESCRIPTION	MAKE	Shir Q11	SHIP QTY LOCATION		COST
3312	1485J	66-67 WINDOW ASSEMBLY VENT RHCHEVELLE / GTO CLEAR	CHEVELLE	4	B125	\$747.92	\$747.92
3312	1485K	66-67 WINDOW ASSEMBLY VENT LHCHEVELLE / GTO CLEAR	CHEVELLE	2	B104	\$377.90	\$377.90
3312	1488E	RADIATOR SUPPORT 70	CHEVELLE	4	F148	\$299.76	\$299.76
3312	1490DWT	WINDSHIELD CHANNEL 64- 67*** WTP *	CHEVELLE	4	F132	\$83.96	\$83.96
3312	1496	SHIFTER 68-72 (W / 0 ROD)	CHEVELLE	2	A65	\$76.68	\$76.68
3312	1615D	FRONT BUMPER FILLER 68-72 PLASTIC	NOVA	10	E95	\$176.70	\$176.70
3312	1636B	64-67 FLOOR TRANSMISSION COVERMANUAL	NOVA	4	F177	\$60.52	\$60.52
3312	1643C	68-72 HOOD LATCH ASSY	NOVA	4	A104	\$139.28	\$139.28
3312	1644WT	66-67 COWL VENT GRILLE* WTP	NOVA	_ 2	F137	\$212.44	\$212.44
3312	1705L	62 REAR BUMPER	IMPALA	4	F113	\$773.84	\$773.84
3312	1705M	65 FRONT BUMPER	IMPALA	2	F93	\$380.56	\$380.56
3312	1710G	63 PARKING LAMP LENS AMBER PR	IMPALA	4	A12	\$47.64	\$47.64
3312	1737RWT	65-66 TRUNK FLOOR DROP OFF RH*WTP*	IMPALA	4	E112	\$105.40	\$105.40
3312	3631MWT	OUTER WHEEL HOUSE RH 65- 66* WELD THROUGH PRIMER *	MUSTANG	10	G168	\$220.90	\$220.90
3312	3631NWT	OUTER WHEEL HOUSE LH 65- 66* WELD THROUGH PRIMER *	MUSTANG	6	G168	\$120.00	\$120.00

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-26	1	ORGIN	2017-09-26

PO#	ITEM	DESCRIPTION	VPART NO.	SHIP OTY	LOCATION	FOB	EXT
		22014111011	MAKE		102	COST	
3312	3639B	64-66 REAR BUMPER GUARD		4	G92	\$34.40	\$34.40
3312	30371	BRACKET PR	MUSTANG		G92	Φ34.40	ψ <b>34.4</b> 0
3312	3643NC	70 TAIL LAMP HOUSING TO		4	A37	\$57.52	\$57.52
3312	3043NC	BODY SEALRH=LH	MUSTANG	4	ASI	\$31.32	\$31.32
3312	3643WA	69 TAIL LAMP LENSALL BODY		8	A45	\$206.48	¢206.49
3312	3043 WA	STYLE	MUSTANG	•	A45	\$200.48	\$206.48
2212	26471 DWT	67-70 ROCKER PANEL OUTER			E01	¢5.42.69	¢£42.60
3312	3647LDWT	RH*WTP*	MUSTANG	8	E91	\$543.68	\$543.68
2212	2645140114	67-70 ROCKER PANEL OUTER		10	F01	Ф.C70, с0	Ф.С <b>7</b> О. СО
3312	3647MDWT	LH* WTP *	MUSTANG	10	E91	\$679.60	\$679.60
3312	3649E	TRUNK FLOOR RH 65-70		10	G116	\$110.00	\$110.00
3312	3049E	TRONK FLOOR KII 03-70	MUSTANG	10	G110	\$110.00	\$110.00
3312	3649F	TRUNK FLOOR LH 65-70	MUSTANG	10	G116	\$110.00	\$110.00
2212	26400000	65-68 SEAT SUPPORT		4	C05	¢00.16	¢00.16
3312	3649PWT	PLATFORMRH *WTP *	MUSTANG	4	G95	\$99.16	\$99.16
2212	264003377	65-68 SEAT SUPPORT			G05	<b>#00.26</b>	<b>#00.2</b> 6
3312	3649QWT	PLATFORMLH *WTP *	MUSTANG	4	G95	\$98.36	\$98.36
2212	2<5277	65-66 TORQUE BOX RH CONVT		,		<b>0.4.10. 7.</b> 4	
3312	3652WT	*WTP*67-68 AS WELL	MUSTANG	4	A97	\$149.56	\$149.56
		67-68 TRAP DOOR BEHIND REAR		_			
3312	3661	SEAT FB	MUSTANG	2	G143	\$187.96	\$187.96
		71-72 "SS" REAR BUMPER					
3312	EM4755	EMBLEM	CHEVELLE	4		\$96.12	\$96.12
		67-72 DOOR GLASS RH=LH					
3312	G1130	CLEAR	CHEVY PU	4	N131 / G2	\$75.36	\$75.36
		47-54 HEADLAMP BUCKET RH /					
3312	LH10	LH	CHEVY PU	20	C84	\$406.80	\$406.80
		60-72 DOME LAMP ASSY WHITE	0112 : 1 1 0				
3312	LP53	BASE	CHEVY PU	6	A15	\$47.88	\$47.88
		2.22	DAGE 4				

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-26	1	ORGIN	2017-09-26

PO#	ITEM	DESCRIPTION	VPART NO.	CHID OTY	LOCATION	FOB	EXT
PO#	HEM	DESCRIPTION	MAKE	SHIPQIY	LOCATION	гов	COST
3312	M3506A	67-70 FOLD DOWN SEAT ASSY		2	A131	\$885.02	\$885.02
3312	WISSUUA	FB	MUSTANG	2	AISI	\$665.02	\$665.02
		FOLD DOWN SEAT MOULDING					
3312	M3507	65-68 F / B14PCS SET*W / O	) WIGE 1 NG	<b>⊣</b> 4	A34	\$418.12	\$418.12
		RECESSED STRIKE AREA*	MUSTANG				
3312	M3509A	67-70 FOLDDOWN LATCH FB RH		4	B23	\$77.24	\$77.24
3312	W13307A	07-701 OLDDOWN EXTERNIB KII	MUSTANG	Ţ	<b>B2</b> 3	ψ//.2¬	ψ//.2¬
3312	M3509B	67-70 FOLDDOWN LATCH FB LH	MIIOTANO	<b>⊣</b> 4	B23	\$76.84	\$76.84
			MUSTANG			7.000	7.000
3312	M3547	HOOD LATCH SUPPORT 65-66	MUSTANG	4	A94	\$19.52	\$19.52
			MUSTANG				
3312	SW29	47-66 HORN CONTACT PIN /		4	C42	\$6.60	\$6.60
3312	5 11 29	SWITCH	CHEVY PU	1	C-12	\$0.00	\$0.00
	TOTAL						\$16215.66