VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-26	1	ORGIN	2017-09-26

PO#	ITEM	DESCRIPTION	VPART NO.	SHID OTV	LOCATION	FOB	EXT	
ru#	IIEMI	DESCRIPTION	MAKE	Shir Q11	LUCATION	FOD	COST	
3312	1006M	77-81 FRONT DISC BRAKE		4	D83	\$83.72	\$83.72	
3312	1000141	BRACKET PR	CAMARO	7	1003	φου.12	φου.12	
3312	1049W	67-73 BUMPER BOLT BULK		8	D91	\$164.00	\$164.00	
3312	104211	PACK50 PCS(3 / 8" X 1")	CAMARO	•	D)1	Ψ104.00	Ψ104.00	
3312	1067QA	70-81 CROSS MEMBER TRANNY		4	G143	\$110.68	\$110.68	
3312	1007 Q/1	SUPPORTTURBO 400 TRAN.	CAMARO	ļ ,	0140	Ψ110.00	Ψ110.00	
3312	1068G	HOOD HINGE RH 67 / 9		20	A91	\$442.20	\$442.20	
3312	10000	CAMARO,65 / 7 IMPA	CAMARO		1171	Ψ112.20	Ψ112.20	
3312	1068H	HOOD HINGE LH 67 / 9		20	A91	\$442.20	\$442.20	
3312	100011	CAMARO,65 / 7 IMPA	CAMARO		1171	Ψ112.20	Ψ112.20	
3312	1068Q	67-73 HOOD SAFETY LATCH		6	A133	\$71.28	\$71.28	
0012	1000 Q	BLACK	CAMARO		11100	Ψ/1.20	Ψ/1.20	
3312	1071	HOOD COWL VENT GRILLE70-73	CAMARO	4	E105	\$266.44	\$266.44	
		47-54 GMC BUMPER FILLERGMC			F135	\$284.52		
3312	1096	ONLY	CHEVY PU	6			\$284.52	
2212	400 (77	GRILLE UPPER BAR 57 CHEVY						
3312	1096E	ONLY	CHEVY PU	2	A65	\$52.66	\$52.66	
2212	1097G	68-72 REAR FENDER STEPSIDE			NICO	¢1 720 00	¢1 720 00	
3312	109/G	RH	CHEVY PU	6	N33	\$1,738.80	\$1,738.80	
3312	1097H	68-72 REAR FENDER STEPSIDE		6	N32	\$1,750.02	\$1,750.02	
3312	109/П	LH	CHEVY PU	0	N32	\$1,730.02	\$1,730.02	
3312	1099G	INNER FENDER RH 67-72	CHEVY PU	8	J161	\$218.48	\$218.48	
			CHEVYPU			,		
3312	1099H	INNER FENDER LH 67-72	CHEVY PU	7 4	J161	\$109.40	\$109.40	
2212	3312 1103DJ	55-59 ROOF FRONT FILLER		10 074		\$281.76	¢201.74	
3312	1102D1	BRACE	CHEVY PU	12	C74	\$281.76	\$281.76	
3312	1103M	DOOR LATCH LH 47-51	CHEWA DA	4	B32	\$88.44	\$88.44	
2212	11001.1		CHEVY PU			Ψ00.11	Ψ00.111	

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-26	1	ORGIN	2017-09-26

PO#	ITEM	DESCRIPTION	VPART NO.	CHID OTV	LOCATION	FOB	EXT COST
ΙΟ#	TIENI	DESCRIPTION	MAKE	Shir Q11	LUCATION	FOB	
3312	1104LE	67-72 BED STEP FOR		2	C125	\$105.00	\$105.00
3312	1104LE	SHORTBED,PAINTEDRH	CHEVY PU	2	C125	\$105.00	\$103.00
		68-72 VENT WINDOW ASSY					
3312	1104P	RHCLEAR GLASS-WILL FIT 67-	CHELLY DIA	_ 2	B102	\$258.44	\$258.44
		SEE NOTE	CHEVY PU				
3312	1106W	67-72 WIPER TRANSMISSION		4	B102	\$163.44	\$163.44
3312	110011	ARMSPR	CHEVY PU		D102	Ψ105.11	Ψ103.11
3312	1107W	47-50 BED REAR CROSS BRACE9			F34	\$109.20	\$109.20
3312	1107 11	BOARD FLOOR	CHEVY PU		134	Ψ107.20	Ψ107.20
3312	1109JD	60-66 LOWER FENDER BRACE		4	B92	\$71.72	\$71.72
3312	11053D	REAR RH	CHEVY PU	•	D92	\$/1./2	φ/1./2
3312	1109KD	60-66 LOWER FENDER BRACE		2	B92	\$35.82	\$35.82
3312	1107KD	REAR LH	CHEVY PU	2	B92	φ33.62	φ33.62
3312	1109R	HOOD HINGE RH 47-55	CHEVY PU	4	A95	\$72.00	\$72.00
			CHEVIPU		C122 /	,	
3312	1114E	CAB CORNER RH 67-72	CHEVY PU	14	C122 / C123	\$87.64	\$87.64
			CHEVYPU	_			
3312	1114F	CAB CORNER LH 67-72	CHEVY DIA	8	C122 / C123	\$49.28	\$49.28
			CHEVY PU		C125		
3312	1114I	47-53 DASH SPEAKER		4	A133	\$255.36	\$255.36
		GRILLECHEVY W / ASH TRAY	CHEVY PU				
3312	1115I	HEADLAMP BEZEL 47-55 PAIR	CHEVY PU	8	A63	\$94.72	\$94.72
3312	1135	55-57 HOOD LATCH		14	A35	\$337.12	\$337.12
3312	1135	33-37 HOOD LATER	CHEVY PU	14	AJS	φ337.12	φυυ/.12
3312	1151C	47-72 ROUND MIRROR		14	F164	\$117.60	\$117.60
3312	11010	STAINLESS 5-5 / 8"SMOOTH	CHEVY PU		1101	Ψ117.00	Ψ117.00
3312	1153B	47-55 EXTERIOR MIRROR ARM		4	F174	\$40.32	\$40.32
JJ12	11330	BLACK RH	CHEVY PU		11/7	Ψ+0.52	ψτ0.32
3312	1402EWT	64-72 SEAT MOUNTING RAIL		6	A104	\$103.68	\$103.68
3312	140212771	4PCS SET* WTP *	CHEVELLE		AIVT	\$105.08	\$105.68

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-26	1	ORGIN	2017-09-26

PO#	ITEM	DESCRIPTION	VPART NO.	CHID OTV	LOCATION	FOB	EXT
ro#	IIEMI	DESCRIPTION	MAKE	Shir Q11	LOCATION	гов	COST
3312	1485J	66-67 WINDOW ASSEMBLY VENT RHCHEVELLE / GTO CLEAR	CHEVELLE	4	B125	\$747.92	\$747.92
3312	1485K	66-67 WINDOW ASSEMBLY VENT LHCHEVELLE / GTO CLEAR	CHEVELLE	2	B104	\$377.90	\$377.90
3312	1488E	RADIATOR SUPPORT 70	CHEVELLE	4	F148	\$299.76	\$299.76
3312	1490DWT	WINDSHIELD CHANNEL 64- 67*** WTP *	CHEVELLE	4	F132	\$83.96	\$83.96
3312	1496	SHIFTER 68-72 (W / 0 ROD)	CHEVELLE	2	A65	\$76.68	\$76.68
3312	1615D	FRONT BUMPER FILLER 68-72 PLASTIC	NOVA	10	E95	\$176.70	\$176.70
3312	1636B	64-67 FLOOR TRANSMISSION COVERMANUAL	NOVA	4	F177	\$60.52	\$60.52
3312	1643C	68-72 HOOD LATCH ASSY	NOVA	4	A104	\$139.28	\$139.28
3312	1644WT	66-67 COWL VENT GRILLE* WTP	NOVA	_ 2	F137	\$212.44	\$212.44
3312	1705L	62 REAR BUMPER	IMPALA	4	F113	\$773.84	\$773.84
3312	1705M	65 FRONT BUMPER	IMPALA	2	F93	\$380.56	\$380.56
3312	1710G	63 PARKING LAMP LENS AMBER PR	IMPALA	4	A12	\$47.64	\$47.64
3312	1737RWT	65-66 TRUNK FLOOR DROP OFF RH*WTP*	IMPALA	4	E112	\$105.40	\$105.40
3312	3631MWT	OUTER WHEEL HOUSE RH 65- 66* WELD THROUGH PRIMER *	MUSTANG	10	G168	\$220.90	\$220.90
3312	3631NWT	OUTER WHEEL HOUSE LH 65- 66* WELD THROUGH PRIMER *	MUSTANG	6	G168	\$120.00	\$120.00

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-26	1	ORGIN	2017-09-26

PO#	ITEM	DESCRIPTION	VPART NO.	SHIP OTY	LOCATION	FOB	EXT
		22014111011	MAKE	5111 Q11		102	COST
3312	3639B	64-66 REAR BUMPER GUARD		4	G92	\$34.40	\$34.40
3312	30371	BRACKET PR	MUSTANG		G72	φ 34.4 0	ψ 34.4 0
3312	3643NC	70 TAIL LAMP HOUSING TO		4	A37	\$57.52	\$57.52
3312	3043NC	BODY SEALRH=LH	MUSTANG	4	ASI	\$31.32	\$31.32
3312	3643WA	69 TAIL LAMP LENSALL BODY		8	A45	\$206.48	¢206.49
3312	3043 WA	STYLE	MUSTANG	•	A45	\$200.48	\$206.48
2212	26471 DWT	67-70 ROCKER PANEL OUTER			E01	¢542.60	¢£42.60
3312	3647LDWT	RH*WTP*	MUSTANG	8	E91	\$543.68	\$543.68
2212	2645140114	67-70 ROCKER PANEL OUTER		10	F01	Ф.C70, с0	Ф.С 7 О. СО
3312	3647MDWT	LH* WTP *	MUSTANG	10	E91	\$679.60	\$679.60
3312	3649E	TRUNK FLOOR RH 65-70		10	G116	\$110.00	\$110.00
3312	3049E	TRONK FLOOR KII 03-70	MUSTANG	10	G110	\$110.00	\$110.00
3312	3649F	TRUNK FLOOR LH 65-70	MUSTANG	10	G116	\$110.00	\$110.00
2212	2640DWF	65-68 SEAT SUPPORT		4	C05	¢00.16	¢00.16
3312	3649PWT	PLATFORMRH *WTP *	MUSTANG		G95	\$99.16	\$99.16
2212	2640011/15	65-68 SEAT SUPPORT			C05	#00.26	#00.2 6
3312	3649QWT	PLATFORMLH *WTP *	MUSTANG	4	G95	\$98.36	\$98.36
2212	2<5277	65-66 TORQUE BOX RH CONVT				0.4.10. 7. 4	
3312	3652WT	*WTP*67-68 AS WELL	MUSTANG	4	A97	\$149.56	\$149.56
		67-68 TRAP DOOR BEHIND REAR		_			
3312	3661	SEAT FB	MUSTANG	2	G143	\$187.96	\$187.96
		71-72 "SS" REAR BUMPER					
3312	EM4755	EMBLEM	CHEVELLE	4		\$96.12	\$96.12
		67-72 DOOR GLASS RH=LH		4			
3312	G1130	CLEAR	CHEVY PU		N131 / G2	\$75.36	\$75.36
		47-54 HEADLAMP BUCKET RH /		20			
3312	LH10	LH	CHEVY PU		C84	\$406.80	\$406.80
		60-72 DOME LAMP ASSY WHITE					
3312	LP53	BASE	CHEVY PU	6	A15	\$47.88	\$47.88
		2.22	DAGE 4				

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-26	1	ORGIN	2017-09-26

PO#	ITEM	DESCRIPTION	VPART NO.	CHID OTY	LOCATION	FOB	EXT
PO#	HEM	DESCRIPTION	MAKE	SHIPQIY	LOCATION	гов	COST
3312	M3506A	67-70 FOLD DOWN SEAT ASSY		2	A131	\$885.02	\$885.02
3312	WISSUUA	FB	MUSTANG	2	AISI	\$665.02	\$665.02
		FOLD DOWN SEAT MOULDING					
3312	M3507	65-68 F / B14PCS SET*W / O) WIGE 1 NG	4	A34	\$418.12	\$418.12
		RECESSED STRIKE AREA*	MUSTANG				
3312	M3509A	67-70 FOLDDOWN LATCH FB RH		4	B23	\$77.24	\$77.24
3312	W13307A	07-701 OLDDOWN EXTERNIB KII	MUSTANG	Ţ	B2 3	ψ//.2¬	ψ//.2¬
3312	M3509B	67-70 FOLDDOWN LATCH FB LH	MIIOTANO	⊣ 4	B23	\$76.84	\$76.84
			MUSTANG			7.000	7.000
3312	M3547	HOOD LATCH SUPPORT 65-66	MUSTANG	4	A94	\$19.52	\$19.52
			MUSTANG				
3312	SW29	47-66 HORN CONTACT PIN /		4	C42	\$6.60	\$6.60
3312	3312 34429	SWITCH	CHEVY PU	1	C-12	\$0.00	\$0.00
	TOTAL						\$16215.66