VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2018-01-25	CEVA	ORGIN	2018-01-25

CONTAINER 80125 DETAILS

PO#	ITEM	DESCRIPTION	VPART NO. MAKE	SHIP QTY	LOCATION	FOB	EXT COST
3347 1004C	68-69 ROOF RAIL		2	C53	\$142.74	\$143.78	
3347	3347 1004C	WEATHERSTRIP RETAIN 6PCS	CAMARO		C33	\$142.74	\$143.76
3367	1004F	67-69 ROOF DRIP RAIL PR	CAMARO	2	A134	\$80.78	\$80.98
3367	3367 1004H	67-69 WINDSHIELD PILLAR		2	B64	\$33.36	\$33.56
3307	100411	DRIPRAIL PR	CAMARO				
		55-79 HORN SET W /			F176	\$61.43	\$61.66
3365	1010U	UNIVERSIAL BRACKET 6 PCS	ALL GM	1			
		SET. GM APPLICATIONS	ALL GM				
22.42	3363 1010U	55-79 HORN SET W /			F176	\$61.43	\$61.66
3363		UNIVERSIAL BRACKET 6 PCS SET. GM APPLICATIONS	ALL GM	1			
		FENDER RH 67 RS W / EXT	3904688	+	L22	\$199.64	\$243.20
3365	3365 1039N		CAMARO	2			
		FENDER LH 67 RS W / EXT	3904687	4	L22	\$399.28	\$399.68
3365	1039P		CAMARO				
		+	3935918	+			
3336	3336 1039Y	FRONT INNER FENDER RH 69	CAMARO	11	J151	\$510.18	\$659.89
		+	CAMAKO	2		_	
3359	1041M	INNER FENDER RH 70-81	CAMARO		J171	\$84.10	\$109.10
3359	1041N	INNER FENDER LH 70-81	CAMARO	1	J171	\$42.05	\$54.55
			14034928				
3360 1044	FENDER RH Z28 78-81	CAMARO	2	L24	\$173.78	\$202.92	
			14034928	 	1		***
1045	FENDER LH Z28 78-81	CAMARO	3	L34	\$260.67	\$304.38	
2250	1046	67-69 FLOOR PAN UNDER		3	G131	\$109.86	\$116.52
3359	1046E	BRACE CONVT	CAMARO				
2250	10467	67-69 FRONT FLOOR PAN BRACE		4	G93	\$80.08	\$84.44
3359	1046J	RH CONVT	CAMARO				
3359	1046L	69 FIRE WALL TO FLOOR BRACE		4	A83	\$78.28	\$79.16
3339	1040L	RH	CAMARO	4			

PAGE:1