| VENDOR | SHIP DATE | SHIP VIA | F.O.B | ONSHIP ETA |
|--------|------------|----------|--------|------------|
| H0013 | 2017-07-26 | UPS | ORIGIN | 2017-07-27 |

| PO# ITEM | | DESCRIPTION | VPART NO. | SHIP QTY | LOCATION | EXT COST |
|----------|--------|-------------------------------------|-----------|----------|-------------|------------|
| ru# | IIEWI | DESCRIPTION | MAKE | Sim Q11 | LOCATION | EAT COST |
| 3273 | 1006G | 69 FRONT DISC BACKING PLATE PR | CAMARO | 5 | G125 | \$135.00 |
| 3273 | 1010H | HORN HIGH ALL GM | ALL GM | 10 | A133 | \$220.00 |
| 3273 | 1067Q | 69 REAR CROSS RAIL | CAMARO | 3 | F126 | \$69.00 |
| 3273 | 1072B | 69 LOWER COWL PANEL | CAMARO | 2 | F54 | \$240.00 |
| 3273 | 1078 | 69 LICENSE PLATE BRACKET REAR | CAMARO | 10 | F156 | \$85.00 |
| 3273 | 1097C | REAR STEPSIDE FENDER RH 55-66 | CHEVY PU | 5 | N12 | \$750.00 |
| 3273 | 1097F | 47-55 REAR FENDER STEPSIDE LH | CHEVY PU | 10 | N23 | \$1,500.00 |
| 3273 | 1101C | 47-54 DOOR HINGE RH UPPER & LOWER | CHEVY PU | 5 | B121 | \$300.00 |
| 3273 | 1101D | 47-54 DOOR HINGE LH UPPER & LOWER | CHEVY PU | 5 | B121 | \$300.00 |
| 3273 | 1102AD | 67-72 DOOR WINDOW GLASS TRACK RH | CHEVY PU | 3 | В92 | \$60.00 |
| 3273 | 1102AE | 67-72 DOOR WINDOW GLASS TRACK LH | CHEVY PU | 3 | B92 | \$60.00 |
| 3273 | 1110E | REAR BUMPER 55-59 STEPSIDE | CHEVY PU | 5 | F111 | \$355.00 |
| 3273 | 1121W | 47-54 HOOD LATCH PANEL PAINTED | CHEVY PU | 2 | C126 | \$126.00 |
| 3273 | 1151A | 47-72 ROUND CHROME 5" RIBBED MIRROR | CHEVY PU | 30 | F162 / F161 | \$150.00 |
| 3273 | 1152L | 70-72 RECTANGLE MIRROR ASSY LH | CHEVY PU | 10 | F174 | \$200.00 |
| 3273 | 1161 | 47-53 TAILGATE W/CHEVROLET | CHEVY PU | 1 | M91 | \$88.00 |
| 3273 | 1426 | FRAME MOUNT 66-67 BIG BLOCK PAIR | CHEVELLE | 4 | A42 | \$120.00 |

| VENDOR | SHIP DATE | SHIP VIA | F.O.B | ONSHIP ETA |
|--------|------------|----------|--------|------------|
| H0013 | 2017-07-26 | UPS | ORIGIN | 2017-07-27 |

| PO# | ITEM | DESCRIPTION VPART NO. MAKE SHIP QTY | | LOCATION | EXT COST | |
|------|---------|--|----------------------------|----------|-----------|----------|
| 3273 | 1488L | UPPER RADIATOR SUPPORT V8** BLACK | CHEVELLE | 10 | F126 | \$90.00 |
| 3273 | 1489EWT | GAS TANK BRACE 64-67 ** | CHEVELLE | 4 | F165 | \$58.00 |
| 3273 | 1489K | GAS TANK MOUNT BRACE 68-72 ** CHEVELLE 10 | | F142 | \$120.00 | |
| 3273 | 1593LWT | 68-69 FULL QUARTER PANEL LH | GTO | 2 | J113 | \$350.00 |
| 3273 | 1593RWT | 68-69 FULL QUARTER PANEL RH | GTO | 2 | J103 | \$350.00 |
| 3273 | 1762WT | 65-70 TRUNK FLOOR CENTRE | IMPALA | 2 | G174 | \$55.00 |
| 3273 | 1764WT | 65-70 TRUNK FLOOR RH | IMPALA | 5 | G164 | \$170.00 |
| 3273 | 1765WT | 65-70 TRUNK FLOOR LH | | | G164 | \$170.00 |
| 3273 | 3631C | SHOCK TOWER CAP RH=LH 65-66 BLACK | MUSTANG | 10 | A125 | \$60.00 |
| 3273 | 3631D | SHOCK TOWER CAP RH=LH 67-70 BLACK** | MUSTANG | 10 | A73 | \$60.00 |
| 3273 | 3634A | FENDER APRON FRONT & REAR RH 65-66 | | | C44 | \$90.00 |
| 3273 | 3634B | FENDER ARPON FRONT & REAR LH 65-66 MUSTANG 3 | | 3 | C44 | \$90.00 |
| 3273 | 3636 | FRONT BUMPER 64-66 | C5ZZ17757A MUSTANG | - 5 | F95 | \$305.00 |
| 3273 | 3636 | FRONT BUMPER 64-66 | C5ZZ17757A | 10 | F95 | \$610.00 |
| 3273 | 3636B | DELUXE BUMPER BOLT KIT 65-68 | MUSTANG | 20 | A125 | \$120.00 |
| 3273 | 3637 | FRONT BUMPER 67-68 | MUSTANG C7ZZ17757A MUSTANG | 5 | F94 / F95 | \$305.00 |
| 3273 | 3637 | FRONT BUMPER 67-68 | C7ZZ17757A MUSTANG | 10 | F94 / F95 | \$610.00 |

| VENDOR | SHIP DATE | SHIP VIA | F.O.B | ONSHIP ETA |
|--------|------------|----------|--------|------------|
| H0013 | 2017-07-26 | UPS | ORIGIN | 2017-07-27 |

| PO# | ITEM | DESCRIPTION | VPART NO. | SHIP QTY | LOCATION | EXT COST |
|------|--------------|--------------------------------------|--------------|-----------|-------------|----------|
| ΙΟ# | TIEWI | DESCRIPTION | MAKE | Shir Q11 | LOCATION | |
| 3273 | 3639 | REAR BUMPER 64-66 | C5ZZ17906A | 5 | F103 | \$305.00 |
| 3213 | 3039 | KEAR BUMI ER 04-00 | MUSTANG | | F 103 | \$303.00 |
| 3273 | 3639 | REAR BUMPER 64-66 | C5ZZ17906A | 10 | F103 | \$610.00 |
| 3213 | 3039 | KEAR BUMI ER 04-00 | MUSTANG | 10 | F 103 | \$010.00 |
| 3273 | 3640 | REAR BUMPER 67-68 | C7ZZ17906A | 5 | F102 | \$305.00 |
| 3213 | 3040 | KEAR BUMI ER 07-06 | MUSTANG | 3 | F 102 | \$303.00 |
| 3273 | 3640 | REAR BUMPER 67-68 | C7ZZ17906A | 10 | F102 | \$610.00 |
| 3213 | 3040 | REAR BUNIFER 07-08 | MUSTANG | 10 | F 102 | \$010.00 |
| 3273 | 3640W | 67-68 DOOR SHELL RH | MUSTANG | 2 | G22 | \$326.00 |
| | | | MUSTANG | | _ | |
| 3273 | 3640X | 67-68 DOOR SHELL LH | MUSTANG | 2 | G22 | \$326.00 |
| 3273 | 3641U | 67-68 F/B FIBERGLASS HOOD | | 2 | D31 | \$430.00 |
| 3213 | 30410 | OF GOTFB TIBERGE/1855 TICOB | MUSTANG | | D 31 | Ψ-30.00 |
| 3273 | 3642F | VALANCE REAR 65-66 W/LT & EXH HOLE | C5ZZ6540544E | 5 | F96 | \$80.00 |
| | | | MUSTANG | | | |
| 3273 | 3643B | VALANCE LOWER REAR 67-68 STD | MUSTANG | 2 | F106 | \$34.00 |
| | | | SFP-14 | | | |
| 3273 | 3643D | REAR LIGHT PANEL 65-66 | MUSTANG | 5 | F117 | \$155.00 |
| 2272 | 2645TA | C7 C0 OLLADTED/DOOD ED AME A CCV VIT | | 1 | J32 | \$275.00 |
| 3273 | 3645TA | 67-68 QUARTER/DOOR FRAME ASSY KIT | MUSTANG | 1 | J32 | \$375.00 |
| 3273 | 3645UA | 67-68 QUARTER/DOOR FRAME ASSY KIT | MUSTANG | 1 | J32 | \$375.00 |
| | 2 < 407 7777 | 47 TO THE OOD DAY SUPPORT | Westring | _ | 71.11 | |
| 3273 | 3648LWT | 67-70 FLOOR PAN SUPPORT | MUSTANG | 5 | F141 | \$125.00 |
| 3273 | 3648W | 65-70 FLOOR PAN PLUG | MUSTANG | 20 | C83 | \$17.00 |
| | | | MIOSTANG | | | |
| 3273 | 3649B | TRUNK LID 69-70 FAST BACK | MUSTANG | 5 | B123 | \$395.00 |
| 2272 | 2272 264611 | TDIMU I ID 77 (0 E/D | C7ZZ6340110A | 3 F41/C91 | 421100 | |
| 3273 | 3649Н | TRUNK LID 67-68 F/B | MUSTANG | | F41 / C91 | \$216.00 |
| 3273 | 3654WT | 67-70 TORQUE BOX RH CPE/FB |) GIGTIAN'S | 5 | A97 | \$175.00 |
| 3213 | 3054771 | DACE 2 | MUSTANG | | 11/1 | φ173.00 |

| VENDOR | SHIP DATE | SHIP VIA | F.O.B | ONSHIP ETA |
|--------|------------|----------|--------|------------|
| H0013 | 2017-07-26 | UPS | ORIGIN | 2017-07-27 |

| DO# ITEM | DESCRIPTION | VPART NO. | CHID OTY | LOCATION | EVE COCE | |
|----------|-------------|----------------------------------|-------------------------|----------|----------|------------|
| PO# | ITEM | DESCRIPTION | MAKE | SHIP QTY | LOCATION | EXT COST |
| 3273 | 3655AWT | 69-70 TORQUE BOX LH CPE/FB | MUSTANG | 5 | A96 | \$205.00 |
| 3273 | 6052A | 70-74 DOOR HINGE LOWER RH | CHGDH01LR CHALLENGER | 5 | D111 | \$125.00 |
| 3273 | 6052B | 70-74 DOOR HINGE LOWER LH | CHGDH01LL CHALLENGER | 5 | D111 | \$125.00 |
| 3273 | 6052C | 70-74 DOOR HINGE UPPER RH | CHGDH01UR CHALLENGER | 5 | D111 | \$100.00 |
| 3273 | 6083WT | 70 TAIL LAMP PANEL | CHALLENGER | 2 | D114 | \$220.00 |
| 3273 | LP60 | 60-66 TAIL LAMP HOUSING | CHEVY PU | 10 | A25 | \$75.00 |
| 3273 | M1016 | HEADLAMP RETAINER RING,PU 62/78 | 5952000 CAMARO | 30 | C63 | \$69.00 |
| 3273 | M1030 | OUTER DOOR MIRROR RH RECTANGLE | 3914753 CAMARO | 14 | F163 | \$130.20 |
| 3273 | M1035 | OUTSIDE DOOR MIRROR 63/5 CORVAIR | IMPALA | 10 | F163 | \$93.00 |
| 3273 | M1125 | 55-56 GRILLE CHROME | CHEVY PU | 5 | C55 | \$875.00 |
| 3273 | M1618 | REAR LICENSE LAMP 1966-72 NOVA | CV05-M103 CAMARO | 30 | A25 | \$285.00 |
| 3273 | M3534 | BATTERY TRAY 65-66 | C5ZZ10732A MUSTANG | 8 | F153 | \$38.40 |
| 3273 | M3535 | BATTERY TRAY 67-70 | MUSTANG | 20 | F161 | \$96.00 |
| 3273 | M6000 | 70-74 SCUFF PLATE PR | CHALLENGER | 3 | A84 | \$99.00 |
| 3273 | MS67FB | 67 MUSTANG BODY SHELL FB | MUSTANG | 1 | | \$7,000.00 |
| 3273 | MS68FB | 68 MUSTANG BODY SHELL FB | MUSTANG | 1 | | \$7,000.00 |
| | | | 4 | | TOTAL | \$29765.6 |