GOLDEN LEAF AUTOMOTIVE

GOLDEN LEAF AUTOMOTIVE

170 ZENWAY BLVD UNIT#2 WOODBRIDGE, ONTARIO L4H 2Y7 TELEPHONE 905/850-3433

BILL TO: PHILS SERVICE CENTRE 7633 HWY#6 BOX 82 ARTHUR ONT N0G1A0 519/848-6682

SALES ORDER 51696

SALES ORDER DATE 2017-10-24 LAST MODIFIED 2017-10-27 PAGE: 1

SHIP TO: PHILS SERVICE CENTRE 7633 HWY#6 BOX 82 ARTHUR, ONT N0G1A0 CANADA

*** SALESORDER ***

CUSTOMER	SHIP VIA	F.O.B	TERMS	PO NUMBER	SALES	REF.NUMBER
P0009	PU	ORIGIN	PREPAID	VERBAL		

ODDED	FILL	B.O.	ITEM	WEIN DESCRIPTION	MAKE	PRICE	EXT.PRICE
ORDER			LOC	ITEM DESCRIPTION	MAKE	DIS%	
1			M1037D	DOOR INNER HANDLE RH STD68- 72CHEVEL68 / 9 CAMARO,68-70 IMPALA	CAMARO ·	\$ 12.00	\$ 12.00
1			A32			0 %	
1			M1037E	DOOR INNER HANDLE LH STD68- 72CHEVEL68 / 9 CAMARO,68-74 NOVA,68- 70 IMPALA	CAMARO	\$ 12.00	\$ 12.00
1			A32		CAMARO	0 %	
1			1134A	67-72 EXT. DOOR HANDLEPR	CHEVY PU	\$ 50.00	\$ 50.00
1			A124			0 %	
1			M1046	- GRILLE MOULDING UPPER 67 / 8 RS	CAMARO	\$ 54.00	\$ 54.00
1			A41			0 %	
1			1104H	INNER DOOR STEP WITH ROCKER LH55-	CHEVY PU	\$ 89.00	\$ 89.00
1			C92	59		0 %	
1			1104S	55-59 ROCKER PANEL LH	CHEVY PU	\$ 28.00	\$ 28.00
1			E101			0 %	
1			1104C	ROCKER PANEL RH 67-72	CHEVY PU	\$ 19.00	\$ 19.00
1			E102			0 %	
1			1114E	CAB CORNER RH 67-72	CHEVY PU	\$ 14.00	\$ 14.00
1			C122			0 %	
1			1114F	CAB CORNER LH 67-72	CHEVY PU	\$ 14.00	\$ 14.00
1			C122			0 %	
1			1006E	69 LEAF SPRING MOUNTING BRACKETS	CAMARO	\$ 47.00	\$ 47.00
1			A72	PR67-69		0 %	
1			1097QJ	60-66 LOWER FENDER PANEL REAR RH	CHEVY PU	\$ 20.00	\$ 20.00
1			B92	00-00 EOWERTENDERTANEE REAR RIT		0 %	
1			1097QK	60-66 LOWER FENDER PANEL REAR LH	H CHEVY PU	\$ 20.00	\$ 20.00
1			B92	00 00 EO WERTENDER PRIVEE REAR EIT		0 %	
							CONTINUE