VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-11-22	CEVA	ORGIN	2017-11-21

CONTAINER 71121 DETAILS

PO#	ITEM	DESCRIPTION	VPART NO. MAKE	SHIP QTY	LOCATION	FOB	EXT COST
3334	1102AM	47-55 DOOR INNER BOTTOM RH	CHEVY PU	2	B45	\$43.30	\$44.76
3334	1102AN	47-55 DOOR INNER BOTTOM LH	CHEVY PU	1	B45	\$18.27	\$19.00
3333	1102AT	60-63 DOOR INNER BOTTOM RH	CHEVY PU	2	A145	\$57.04	\$58.98
3333	1102AU	60-63 DOOR INNER BOTTOM LH	CHEVY PU	2	A145	\$57.76	\$59.70
3333	1102AY	60-66 DOOR SKIN LOWER PANELRH=LH	CHEVY PU	4	A145	\$49.92	\$52.24
3334	1102BE	47-54 FRONT LOWER DOOR PILLAR RH	CHEVY PU	2	C42	\$29.86	\$30.06
3334	1102BF	47-54 FRONT LOWER DOOR PILLAR LH	CHEVY PU	2	C42	\$31.30	\$31.50
3334	1102BG	47-54 REAR LOWER DOOR PILLAR RH	CHEVY PU	2	C42	\$32.16	\$32.36
3334	1102BH	47-54 REAR LOWER DOOR PILLAR LH	CHEVY PU	2	C42	\$31.74	\$31.94
3319	1103A	DOOR SHELL RH 72	CHEVY PU	1	N31	\$153.09	\$153.19
3289	1103B	DOOR SHELL LH 72	CHEVY PU	2	031	\$304.46	\$327.64
3319	1104C	ROCKER PANEL RH 67-72	CHEVY PU	1	E102	\$9.17	\$11.11
3335	1104C	ROCKER PANEL RH 67-72	CHEVY PU	10	E102	\$91.70	\$111.10
3319	1104D	ROCKER PANEL LH 67-72	CHEVY PU	5	E102	\$45.85	\$55.55
3335	1104D	ROCKER PANEL LH 67-72	CHEVY PU	10	E102	\$91.70	\$111.10

PAGE:4