FILL UP DETAILS

| DATE | SONO | CUST# | ITEM# | DESCRIPTION | SALES | LOC | QTYORD | FILLED | AMOU |
|---------------------------------|-------|----------------|-----------------|--|-------|-----------|--------|--------|-------------|
| DATE: 2017-11-02 | | | | | | | | | |
| 2017-11-02 | 51787 | E0001 | 1067SX | 67-69 ROCKER PANEL INNER LHCPE W / O QUARTER SECTION | | E91 | 1 | 0 | \$ 0.00 |
| 2017-11-02 | 51787 | E0001 | 1067RX | 67-69 ROCKER PANEL INNER RHCPE W / O QUARTER SECTION | | E91 | 1 | 0 | \$ 0.00 |
| 2017-11-02 | 51787 | E0001 | M1349 | DRIP RAIL MLDG 6PC / SET 68-72 GTO68-9 CHEVELLE | | B61 | 1 | 0 | \$ 0.00 |
| DATE - 2017 11 00 | 0 | | | | | SUBTOTAL: | 3 | 0 | \$0.00 |
| DATE : 2017-11-09 2017-11-09 | 51856 | E0001 | M1503 | 1970-72 BODY SIDE MOLDING 10 PC | VY | A111 | 1 | 0 | \$ 0.00 |
| 2017-11-09 | 51856 | E0001 E0001 | 1047R | FENDER EXTENTION RH 68 ONLY | VY | B83 | 1 | 0 | \$ 0.00 |
| 2017-11-09 | 31630 | E0001 | 104/K | FENDER EATENTION RH 08 ONL I | V I | SUBTOTAL: | | 0 | \$0.00 |
| DATE : 2017-12-04 | 4 | | | | | SOBIOTAL. | | | ψ0.00 |
| 2017-12-04 | 52067 | E0001 | SB-20FLP | 20" BLK WEBBING CHROME PUSH BUCKLECHEVY PU BENCH SEAT | M | F172 | 1 | 0 | \$ 0.00 |
| | | | | | | SUBTOTAL: | 1 | 0 | \$0.00 |
| DATE : 2018-01-02 | | | | | | | | | |
| 2018-01-02 | 52259 | E0001 | 3643C | VALANCE LOWER REAR 67-68 DUAL EXST. | VY | F106 | 1 | 0 | \$ 0.00 |
| | | | | | | SUBTOTAL: | 1 | 0 | \$0.00 |
| DATE : 2018-01-04 | | F0004 | 1511 | COMPANY A LANGUE DE DE LA COMPANY DE LA COMP | | . 25 | | ٥ | |
| 2018-01-04 | 52305 | E0001 | 1714 | 65 TAIL LAMP LENS RED | M | A25 | 4 | 0 | \$ 0.00 |
| DATE : 2019 01 1: | 1 | | | | | SUBTOTAL: | 4 | 0 | \$0.00 |
| DATE: 2018-01-11 2018-01-11 | 52355 | E0001 | 1603A | HOOD 68-72 W / COWL 4 INCH | | D31 | 1 | 0 | \$ 0.00 |
| 2016-01-11 | 32333 | E0001 | 1003A | HOOD 06-72 W / COWL 4 INCH | | SUBTOTAL: | | 0 | \$0.00 |
| DATE : 2018-01-15 | 5 | | | | | SUBTOTAL. | 1 | O | φ0.00 |
| 2018-01-15 | 52383 | E0001 | 1423WT | 70-72 TAIL LAMP PANEL * WTP * | M | F146 | 1 | 1 | \$ 127.00 |
| 2018-01-15 | 52383 | E0001 | 1461B | 68-72 FIREWALL W / O AC CPE | M | G171 | 1 | 0 | \$ 0.00 |
| 2018-01-15 | 52383 | E0001 | L71AN | 71 PARKING LAMP LENS PAIR | M | A13 | 1 | 0 | \$ 0.00 |
| | | | | | | SUBTOTAL: | 3 | 1 | \$127.00 |
| DATE: 2018-01-18 | 8 | | | | | | | | |
| 2018-01-18 | 52433 | E0001 | 1066C | FULL QUARTER PANEL LH 68 CPE | VY | K42 | -1 | -1 | \$ -299.00 |
| 2018-01-18 | 52433 | E0001 | 1495H | 66-72 CONTROL ARM UPPER LH OE STYLE | VY | A91 | -1 | -1 | \$ -113.00 |
| 2018-01-18 | 52433 | E0001 | 1067H | ROCKER PANEL LH 67-69 H / T | VY | E111 | -1 | -1 | \$ -67.00 |
| 2018-01-18 | 52433 | E0001 | 1048J | FLOOR FULL PAN LH 67-69 | VY | G173 | -1 | -1 | \$ -56.00 |
| 2018-01-18 | 52433 | E0001 | 1631WT | FULL FLOOR PAN LH 62-67 ** * NON WELD THROUGH FINISH * | VY | G153 | -1 | -1 | \$ -72.00 |
| 2018-01-18 | 52433 | E0001 | 1461FWT | 68-72 FIREWALL BRACKET PR * WTP * CPE ONLY | VY | A121 | -1 | -1 | \$ -109.00 |
| 2018-01-18 | 52433 | E0001 | 3653WT | 65-66 TORQUE BOX LH CONVT *WTP* 67- 68 AS WELL | VY | A96 | -1 | -1 | \$ -77.00 |
| 2018-01-18 | 52433 | E0001 | 1038A | 67-69 REINFORCEMENT TO SKIRT BRACE | VY | B94 | -1 | -1 | \$ -17.00 |
| 2010-01-10 | 32433 | L0001 | 1030/1 | RH | V 1. | Б/ч | -1 | -1 | φ-17.00 |
| 2018-01-18 | 52433 | E0001 | M1001 | FR WHEEL OPEN MLG LH 67-68 67-68 FIREBIRD | VY | A11 | -1 | -1 | \$ -15.00 |
| 2018-01-18 | 52433 | E0001 | M1000 | FR WHEEL OPEN MLG RH 67-68 67-68 FIREBIRD | VY | A11 | -1 | -1 | \$ -15.00 |
| 2018-01-18 | 52433 | E0001 | 1402B | 69-72 SEAT BACK LOCK ASSY RH=LH | VY | A91 | -1 | -1 | \$ -103.00 |
| 2018-01-18 | 52433 | E0001 | 3634E | FRONT FENDER APRON RH 71-73 | VY | G124 | -1 | -1 | \$ -33.00 |
| 2018-01-18 | 52433 | E0001 | M1355 | DRIP RAIL MOULDING 70-72 6 PCS | VY | B51 | -1 | -1 | \$ -67.00 |
| 2018-01-18 | 52433 | E0001 | M1067 | HEADLAMP BEZEL LH 69 STD WO / CHROME | VY | A17 | -1 | -1 | \$ -33.00 |
| 2018-01-18 | 52433 | E0001 | M1331 | RR WHEEL WELL MLGD LH 70 / 72 | VY | A71 | -1 | -1 | \$ -22.00 |
| 2018-01-18 | 52433 | E0001 | T32 | GAS TANK 64-67 WITH OUT GAS CAP FLANGE | VY | P43 | -1 | -1 | \$ -99.00 |
| 2018-01-18 | 52427 | E0001 | 1616B | FENDER TO VALANCE BRACKET 66 / 7 | M | B12 | 1 | 0 | \$ 0.00 |
| 2018-01-18 | 52427 | E0001 | | PAIR ** REAR BODY UPPER MOLDING 69 NO CLIPS | | B11 | 1 | 0 | \$ 0.00 |
| 2018-01-18 | 52427 | E0001 | M1486A 1460G | | M | F115 | 1 | 0 | \$ 0.00 |
| 2010-01-10 | J2721 | LOUI | 17000 | TROM BOM ERO, TREMIUM QUALITY | 171 | SUBTOTAL: | | -16 | \$-1,197.00 |
| | | | | | | SODIOIAL. | 1.0 | 10 | Ψ 1,177.00 |

| DATE | SONO | CUST# | ITEM# | DESCRIPTION | SALES | LOC | QTYORD | FILLED | AMOU |
|-----------------|-------|-------|---------|--|-------|----------|--------|--------|------------|
| DATE: 2018-01-2 | 5 | | | | | | | | |
| 2018-01-25 | 52506 | E0001 | M1039C | 69 PARK LAMP ASSY | M | A14 | 1 | 1 | \$ 123.00 |
| 2018-01-25 | 52506 | E0001 | L1009 | 69 LICENSE PLATE LAMP | M | A16 | 1 | 1 | \$ 29.00 |
| 2018-01-25 | 52506 | E0001 | 1048QC | 69 REAR BUMPER BRACKET 5PCS / SET | M | A45 | 1 | 1 | \$ 106.00 |
| 2018-01-25 | 52506 | E0001 | 1038A | 67-69 REINFORCEMENT TO SKIRT BRACE RH | M | B94 | 1 | 1 | \$ 17.00 |
| 2018-01-25 | 52506 | E0001 | 1038B | 67-69 REINFORCEMENT TO SKIRT BRACE LH | M | B94 | 1 | 1 | \$ 17.00 |
| 2018-01-25 | 52506 | E0001 | 1078 | 69 LICENSE PLATE BRACKET REAR * 5.25 INCH MOUNTING BOLT SPREAD * | M | F156 | 1 | 1 | \$ 22.00 |
| 2018-01-25 | 52506 | E0001 | 6022 | 70-71 REAR BUMPER | M | F123 | 1 | 1 | \$ 227.00 |
| 2018-01-25 | 52506 | E0001 | 6021 | 70-71 FRONT BUMPER | M | F114 | 1 | 1 | \$ 227.00 |
| 2018-01-25 | 52506 | E0001 | 1069A | HOOD 70-81 W / COWL INDUCTION | M | D11 | 1 | 1 | \$ 342.00 |
| 2018-01-25 | 52506 | E0001 | 6030 | 70-74 BATTERY TRAY "E" BODY 70-72 "B" BODY | M | F154 | 1 | 1 | \$ 17.00 |
| 2018-01-25 | 52506 | E0001 | M6001 | 68-70 SCUFF PLATE PR | M | A84 | 1 | 0 | \$ 0.00 |
| 2018-01-25 | 52506 | E0001 | M6010 | 68-69 FRONT WHEEL WELL MOLDING RH CORNET | M | A135 | 1 | 1 | \$ 42.00 |
| 2018-01-25 | 52506 | E0001 | M1050A | 67-69 DRIP RAIL MOLDING SET | M | A41 | 1 | 1 | \$ 70.00 |
| 2018-01-25 | 52506 | E0001 | 112 | 67 TRUNK LOCK LATER,63-65&68-72 GTO 64-66&68-69 CHEVL / MONTE,53-94 CHEVT | M | 1-2 | 1 | 1 | \$ 16.00 |
| 2018-01-25 | 52506 | E0001 | T16 | SENDING UNIT 68 V8 3 / 8" (M23) 69 8 CLY 3 / 8", 69 396 2 BBL CAM / NOV | M | B81 | 1 | 0 | \$ 0.00 |
| 2018-01-25 | 52506 | E0001 | M1618 | REAR LICENSE LAMP 1966-72 NOVA 67 / 9 CAMARO,CHEVELE 66-72,GTO 66-72 | M | A25 | 3 | 3 | \$ 60.00 |
| 2018-01-25 | 52506 | E0001 | M1070 | REAR WINDOW MOLDING SET 67-69 5PC CAMARO / FB | M | A41 | 1 | 1 | \$ 99.00 |
| 2018-01-25 | 52506 | E0001 | M1025A | WINDSHIELD MLDNG KIT 67-69 5PC HT | M | A22 | 1 | 1 | \$ 84.00 |
| 2018-01-25 | 52506 | E0001 | M1609 | BODY BUSHING KIT 68-74 NOVA 67-72 CAMARO / FB | M | C51 | 2 | 2 | \$ 66.00 |
| 2018-01-25 | 52506 | E0001 | M1029E | WIPER BLADE 67-69 PAIR 59-64 IMPALA 66-7 CHEVELLE 67-72 NOVA 65-6 PU | M | A22 | 1 | 1 | \$ 19.00 |
| 2018-01-25 | 52506 | E0001 | M1029A | WIPER ARM CHROME 67-69 CPE PAIR | M | A22 | 1 | 1 | \$ 21.00 |
| 2018-01-25 | 52506 | E0001 | M1013 | HEAD LAMP SWITCH CAMARO 67-68 STD, IMPALA 64 / 7,CHEVEL 64-72,NOVA 64-73 | M | C52 | 1 | 1 | \$ 11.00 |
| 2018-01-25 | 52506 | E0001 | 7660239 | 1 / 4 WINDOW REGULATOR LH 67-69 | M | A113 | 1 | 1 | \$ 52.00 |
| 2018-01-25 | 52506 | E0001 | 7660238 | 1 / 4 WINDOW REGULATOR RH 67-69 | M | A113 | 1 | 0 | \$ 0.00 |
| 2018-01-25 | 52506 | E0001 | M6070 | 70 TRUNK LID MOLDING | M | A135 | 1 | 1 | \$ 46.00 |
| 2018-01-25 | 52506 | E0001 | M6075 | 70 QUARTER EXTENSION MOLDING LH | M | A135 | 1 | 1 | \$ 20.00 |
| 2018-01-25 | 52506 | E0001 | M6074 | 70 QUARTER EXTENSION MOLDING RH | M | A135 | 1 | 1 | \$ 20.00 |
| | | | | | | SUBTOTAL | : 30 | 27 | \$1,753.00 |

TOTAL: 32 12 \$683.00