VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-12-13	CEVA	ORGIN	2017-12-15

## **CONTAINER 71215 DETAILS**

PO# ITEM	ITEM	DESCRIPTION	VPART NO.	SHID OTV	LOCATION	FOB	EXT
	DESCRIPTION	MAKE	Sim Q11	LOCATION	FOB	COST	
3336 <b>1047</b> C	FRONT APRON 67-68 STD	3925467	1	E113	\$26.25	\$29.01	
	FRONT AFRON 07-08 STD	CAMARO	1				
3346	3346 <b>1047J</b>	HEADER PANEL 67-68	3927907	5	C14	\$124.25	\$131.35
3340	104/3	TIEADER I AINEL 07-08	CAMARO		C14	\$124.23	\$131.33
3341	1047K	HEADER PANEL 69	1047K	5	E104	\$121.80	\$128.90
3341	104/K	TIEADER LAINEE 09	CAMARO	3	E104	\$121.60	\$120.90
3336	1047W	HEADER PANEL 70-73		1	B63	\$113.89	\$113.99
3330	3330 104/W	STANDARD	CAMARO	1	D03	\$113.89	\$113.99
3347	1047X	RADIATOR SUPPORT 70-73	CAMARO	- 2	F96	\$139.48	\$151.30
	3347 <b>1047ZC</b>	70 72 DADIATION TO FEMILED	CAMARO		G114	\$19.58	\$19.84
3347		70-73 RADIATOR TO FENDER REINFORCEM BAR PR	CAMARO	2			
		REINFORCEIVI BAR PR	CAMARO		G4 <b>=</b> 2.4		
3336	3336 <b>1048J</b>	FLOOR FULL PAN LH 67-69	CAMARO	5	G173 / S131	\$144.80	\$159.15
		ED ONE DIN (DED OVERED	CAMARO		5131		
3347	3347 <b>1048M</b>	FRONT BUMPER OUTER BRACKET RH 67	CAMARO	1 4	G132	\$6.39	\$6.49
			CAMARO		<del>                                     </del>		
3336	1048X	TRUNK FLOOR DROP OFF RH 69	CAMARO		G153	\$55.96	\$61.64
3336	1048Y	TRUNK FLOOR DROP OFF LH 69		3	G153	\$42.00	\$46.26
3330	3330 10461	TROWN LOOK BROT OH LITO	CAMARO		0133	Ψ+2.00	Ψ+0.20
3336	3336 <b>1049A</b>	FRONT BUMPER 69	3927422	3	F94	\$194.94	\$201.93
			CAMARO		'		
3346	3346 <b>1049LE</b>	67-69 TRUNK LID W / SPOILER		4	F61	\$284.52	\$302.32
		HOLES	CAMARO				
3336	1049Y	69 LICENSE PLATE BRACKET	CAMARO	7	F143	\$39.41	\$41.16
		67-68 LICENSE PLATE	CI IIII IIIO	1			
3336	1049Z	BRACKETFRONT	CAMARO		F143	\$5.63	\$5.82
			CHMINO	<del></del>			***
3346 <b>1054</b>	67-69 SEAT TRACK RH 2PC SET	CAMARO	1	A135	\$30.93	\$31.17	

PAGE:4