VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-19	CEVA	ORGIN	2017-09-19

## **CONTAINER 70919 DETAILS**

PO# ITEM	DESCRIPTION	VPART NO.	SHIP QTY	LOCATION	FOB	EXT COST	
	DESCRIPTION	MAKE					
3300	1099R	55-56 STD HOOD	CHEVY PU	1	D41	\$202.66	\$202.66
2204	2204 1000TN	47-52 CHEVY PU HOOD 2PCW /		1	D41	\$226.79	\$226.70
3304 <b>1099TN</b>	NO EMBLEM HOLE	CHEVY PU	1	D41	\$226.78	\$226.78	
3300	3300 <b>1099X</b>	RADIATOR SUPPORT 60-66W /			F96	\$177.72	\$177.72
3300		DIAGONAL BRACE	CHEVY PU	3	170	φ1//./2	φ1//./2
3300	1099Y	RADIATOR SUPPORT 67-68	CHEVY PU		F136	\$215.18	\$215.18
3300	0 <b>1100</b> L	BATTERY HOLD DOWN 58-66		4	F152	\$15.32	\$15.32
3300	1100L	BATTERY HULD DOWN 58-66	CHEVY PU		F152	\$13.32	\$13.32
3300	1100QA	73-87 BATTERY TRAY SUPPORT	TP	_ 2	F175	\$21.34	\$21.34
3300	1100QA		CHEVY PU		F1/3	φ21.34	Ψ21.34
3304	1101Y	DOOR SKIN, PARTIAL LOWER RH 67-729"		1	D102	\$9.30	\$9.30
3304	3304 11011		CHEVY PU		D102	φ7.30	Ψ7.30
2204	3304 <b>1101YA</b>	67-72 DOOR INNER BOTTOM		1	D104	\$15.05	\$15.05
3304		PANEL RH	CHEVY PU		D104	\$15.05	\$13.05
3304	1101Z	DOOR SKIN, PARTIAL LOWER		1	D102	¢0.41	¢0.41
3304 1101Z	LH 67-729"	CHEVY PU	1	D102	\$9.41	\$9.41	
2204	2204 110174	67-72 DOOR INNER BOTTOM		1 2	D104	¢20.0c	\$20.00
3304 <b>1101ZA</b>	PANEL LH	CHEVY PU	_ 2	D104	\$29.06	\$29.06	
3302	1102CD	55-59 COWL VENT LOWER LH	CHEVY PU	- 2	C32	\$54.20	\$54.20
			CHEVITO				
3303	1103A	DOOR SHELL RH 72	CHEVY PU	2	N31	\$304.46	\$304.46
3303	1103DM	47-53 WINDSHIELD SUNVISOR		2	B92	\$17.64	\$17.64
3303 1103DM	BRACKETLH	CHEVY PU		D72	φ17.0 <del>4</del>	φ17.0 <del>4</del>	
3305	1103G	DOOR RELAY RH 55-59	CHEVV DI	_ 2	B94	\$26.44	\$26.44
	11000		CHEVY PU			•	• •
3305	1103H	DOOR RELAY LH 55-59	CHEVY PU	2	B94	\$26.44	\$26.44

PAGE:4