VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2018-01-25	CEVA	ORGIN	2018-01-25

## **CONTAINER 80125 DETAILS**

PO# ITEM	ITEM	DESCRIPTION	VPART NO.	SHID OTV	LOCATION	FOB	EXT COST
	11151/1	DESCRIPTION	MAKE	Sim Q11			
3359 <b>M1191</b>	BED UP MLDG LH 73-80 6.5 FT	475547	5	B62	\$45.85	\$50.95	
	BED OF MEDGER 73-80 0.5 FT	CHEVY PU					
3359	M1194	BED LO MLG RR RH 73-80 6.5 F	475582	2	A71	\$10.50	\$11.02
3339 WIII94	W11194		CHEVY PU				
3359	M1195	BED LO MLG RR LH 73-80 6.5'	475581	2	A71	\$10.50	\$11.02
3339	W11193		CHEVY PU				
2262	M1100	1 / 4 LO MLG FR RH 73-80 JIMMY -	475588	2	A71	\$10.18	\$10.38
3363 <b>M1198</b>	MIII90		CHEVY PU				
2262	M1199	1 / 4 LO MLG FR LH 73-80 JIMMY	475587	2	A71	\$10.42	\$10.62
3363	MIII99		CHEVY PU				
3365 <b>M1210</b>	M1210	FENDER SIDE MOLDING 69-72			4.01	¢120.44	¢121 50
	RH / LH	CHEVY PU	6	A81	\$130.44	\$131.58	
3365	M1212	DOOR UPPER MOLDING RH 69-72	CHEVIA DI	$\exists$ 3	A81	\$45.33	\$45.75
	1,1111	, and the state of	CHEVY PU		1202	Ψ.υ.υυ	Ψ.ε., ε
3365	M1213	DOOR UPPER MOLDING LH 69-72	CHEVY PU	3	A81	\$45.36	\$45.78
2265	N/1014	UPPER CAB CORNER MOLDING			4.122	Ø17.20	¢17.40
3365 <b>M1214</b>	RH 69-72	CHEVY PU	2	A122	\$17.20	\$17.40	
2265	2265	UPPER CAB CORNER MOLDING		1	A 122	Φ0. <b>C</b> 0	¢0.70
3365 <b>M1215</b>	LH 69-72	CHEVY PU	1	A122	\$8.68	\$8.78	
3365 <b>M1216</b>	251217	UPPER BEDSIDE MOLDING 69-72			D(2	ф2 c 20	ф27.24
	SHORT	CHEVY PU	2	B62	\$36.38	\$37.24	
3365 <b>M1217</b>	UPPER BEDSIDE MOLDING 69-72		3	B63	\$66.96	\$69.69	
	LONG RH=LH	CHEVY PU					
3365 <b>M1222</b>		LOWER FRONT FENDER	CV01-M11A	2	A122	\$16.98	\$17.18
	M1222	MOLDING RH 69-72 WOOD	CHEVY PU				
22.5	7.54445	LOWER FRONT FENDER	CV01-M12A		A122	\$16.94	\$17.14
3365 <b>M12</b> 2	M1223	MOLDING LH 69-72 WOOD	CHEVY PU	2			
3365 <b>M1224</b>		LOWER REAR FENDER	CV01-M13		A122	\$16.98	\$17.18
	M1224	MOLDING RH 69-72 BLACK	CHEVY PU	2			
			DAGE 15				

PAGE:15