VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-08-15	CEVA	ORGIN	2017-08-16

PO#	ITEM	DESCRIPTION	VPART NO.	CHID OTV	LOCATION	FOB	EXT
10#	IIEMI	DESCRIPTION	MAKE	Shir Q11	LOCATION	FOB	COST
3287	1003H	67-69 TUBULAR CONTROL ARM	CAMCA01RL	3	C64	\$186.27	\$167.38
3207	100311	LOWER RH	CAMARO	3	C04	\$100.27	\$107.36
3287	1003I	67-69 TUBULAR CONTROL ARM	CAMCA01LL		C64	\$185.40	\$158.43
3207	10051	LOWER LH	CAMARO		C04	ψ10J. <del>4</del> 0	Ψ130.43
3287	1003J	67-69 TUBULAR CONTROL ARM	CAMCA01UR	4	C64	\$202.24	\$149.56
3207	10030	UPPER RH	CAMARO	7	204	Ψ202.2-1	Ψ147.50
3287	1003K	67-69 TUBULAR CONTROL ARM	CAMCA01UL	4	C64	\$196.40	\$168.04
3207	10031	UPPER LH	CAMARO	<b>-</b>	C04	Ψ170.40	Ψ100.04
3290	1020	79-81 HEADLAMP BACKING		_ 2		\$198.00	\$198.00
3270	1020	SUPPORT	TRANS AM			\$176.00	Ψ170.00
3289	1023E	67-69 QUARTER/DOOR FRAME		_ 2	J181	\$340.36	\$391.48
3207	10231	INNER RH	CAMARO		3101	ψ540.50	Ψ371.40
3288	1040	FENDER RH 70-77	359969		L73	\$171.62	\$258.24
3200	1040	TENDER RIT 70-77	CAMARO		173	Ψ171.02	Ψ230.24
3288	1041	FENDER LH 70-77	3981841		L73	\$171.48	\$258.22
3200	1041	TENDER EIT 70-77	CAMARO		LIS	ψ1/1. <del>4</del> 0	Ψ236.22
3288	1041C	INNER WHEELHOUSE RH 67-69	CAMARO	6	G145	\$135.06	\$154.56
			CAMARO				
3288	1041D	OUTER WHEELHOUSE RH 67-68	CAMARO	5	G145	\$95.25	\$140.78
3288	1041E	OUTER WHEELHOUSE LH 67-68	CAMARO	6	G155	\$114.30	\$167.73
			CAMARO	+			
3288	1041G	OUTER WHEELHOUSE LH 69	CAMARO	4	G154	\$76.24	\$113.94
3288	1041H	OUTER WHEELHOUSE RH 70-81	CAMARO	2	G146	\$55.92	\$74.72
			CAMARO			-	·
3288	1041J	WHEELHOUSE OUTER LH 70-81	CAMARO	1	G147	\$27.72	\$37.22
3288	1041K	HEATER BOX ASSY 67-75		3	A144	\$32.55	\$35.52
3200	1041K	SMALL BLOCK**	CAMARO	3	A144	φ32.33	φ33.32

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-08-15	CEVA	ORGIN	2017-08-16

PO#	ITEM	DESCRIPTION	VPART NO.	CHID OTV	LOCATION	FOB	EXT
PO#	TIEWI	DESCRIPTION	MAKE	SHIP Q11	LUCATION	LOP	COST
3288	1041M	INNER FENDER RH 70-81	CAMARO	1	J171	\$42.04	\$60.80
3288	1041N	INNER FENDER LH 70-81	CAMARO	2	J171	\$83.98	\$121.58
		69 TRUNK FLOOR PAN,6" INNER					
3287	1046CXWT	WHEEL	CAMARO	1	L31	\$195.39	\$226.88
2207	10470	EDONE ADDON 67 69 SED	3925467	2	E112	¢40.76	¢50.00
3287	1047C	FRONT APRON 67-68 STD	CAMARO	2	E113	\$49.76	\$58.02
2207	1047E	BATTERY TRAY CLAMP	3893882	15	CEA	<b>011.70</b>	¢11.02
3287	104/E	CAMARO 67-81	CAMARO	15	C52	\$11.70	\$11.93
3287	1048ZC	74-81 TRUNK FLOOR PAN		3	L21	\$269.52	\$316.23
3207	104020	74-01 TROTAL LOOK TAIN	CAMARO		121	Ψ207.52	Ψ310.23
3287	1049C	REAR BUMPER 69	3927424	4	F111	\$266.04	\$277.44
	10.50	THE IN SOME SILES	CAMARO	-		Ψ200.01	Ψ=//
3287	1049K	CONVERTIBLE TOP HEADER	7762132		G143	\$170.00	\$195.75
3207	10421	BOW 67-69	CAMARO		0143	Ψ170.00	Ψ1/3.73
3289	1064F	GRILLE 69 STANDARD BLACK	CAMARO		C65	\$244.32	\$262.20
2207	10646	CDU LE GUIDDOUNID 70 72 DG	3973942	1	1145	Φ <b>2</b> 70.66	<b>#20</b> < <b>5</b> 0
3287	1064G	GRILLE SURROUND 70-73 RS	CAMARO	1	A145	\$258.66	\$296.58
2207	106171	72-73 Z28 & SS GRILLE			0.61	Φ c 0. 2.2	<b>\$60.64</b>
3287	1064JA	W/MOLDING	CAMARO	1	C61	\$68.22	\$69.64
220=	10.550	67 FULL QUARTER PANEL RH	7702810		****	<b>44.5.5</b> 0	<b></b>
3287	1066S	COUPE	FIREBIRD	1	K13	\$166.29	\$191.14
2207	10.00	67 FULL QUARTER PANEL LH	7702811		7713	Φ1.50.51	φ101 ·=
3287	1066T	COUPE	FIREBIRD	1	K13	\$159.51	\$191.67
3287	1067A	QUARTER PANEL SKIN RH 67-68	CAMARO	1	G176	\$43.25	\$58.88
3287	1067B	QUARTER PANEL SKIN LH 67-68	CAMARO	2	G175	\$86.50	\$117.76

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-08-15	CEVA	ORGIN	2017-08-16

PO#	ITEM	DESCRIPTION	VPART NO. MAKE	SHIP QTY	LOCATION	FOB	EXT COST
3287	1067C	QUARTER PANEL SKIN RH 69	CAMARO	1	G177	\$43.12	\$58.86
3287	1067D	QUARTER PANEL SKIN LH 69	CAMARO	1	G177	\$42.71	\$58.33
3289	1076M	67-69 QUARTER VENT WINDOW LH CPE	CAMARO	1	B103	\$88.21	\$91.20
3293	1097QD	47-53 FENDER LOWER REAR PANEL LH	CHEVY PU	1	D82	\$52.10	\$54.83
3293	1097QE	55-57 FENDER REAR LOWER PANEL RH	CHEVY PU	1	D104	\$17.09	\$17.61
3293	1097QF	55-57 FENDER REAR LOWER PANEL LH	CHEVY PU	1	D104	\$17.97	\$18.49
3293	1097QG	58-59 FENDER REAR LOWER PANEL RH	CHEVY PU	2	D104	\$34.62	\$36.30
3293	1097QK	60-66 LOWER FENDER PANEL REAR LH	CHEVY PU	3	B92	\$27.09	\$29.07
3293	1097QM	67-72 REAR LOWER FENDER PANEL LH	CHEVY PU	2	D114	\$21.78	\$22.95
3293	1099C	FENDER RH 1967	CHEVY PU	1	N62	\$95.14	\$108.03
3293	1099MA	73-80 3"COWL INDUCTION W/BUG SCREEN	CHEVY PU	2	E51	\$428.00	\$495.23
3293	10B52200	70-74 CARPET BLACK 80/20 LOOP 1PC	CAMARO	2	F183	\$202.82	\$213.08
3293	10B53140-2	67-69 CAPPET BLACK 80/20	CAMARO	1	F186	\$101.41	\$105.14
3289	1100D	BATTERY TRAY ASSEMBLY 47- 55	CHEVY PU	2	F151	\$39.18	\$41.07
3293	1102BS	67-72 FRONT LOWER DOOR PILLAR RH	CHEVY PU	2	C74	\$10.38	\$11.07

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-08-15	CEVA	ORGIN	2017-08-16

PO#	ITEM	DESCRIPTION	VPART NO. MAKE	SHIP QTY	LOCATION	FOB	EXT COST
3293	1102BT	67-72 FRONT LOWER DOOR PILLAR LH	CHEVY PU	_ 2	C74	\$10.36	\$11.05
3293	1102BU	67-72 REAR LOWER DOOR PILLAR RH	CHEVY PU	_ 2	C74	\$13.44	\$13.77
3293	1102BW	67-72 REAR LOWER DOOR PILLAR LH	CHEVY PU	1	C74	\$6.08	\$6.25
3283	1102J	55-59 DOOR ARM REST BLACK RH=LH	CHEVY PU	1	B92	\$19.32	\$19.47
3285	1102XA	47-54 CHROME WINDOW FRAMES	CHEVY PU	3	B103	\$232.17	\$236.80
3287	1103DB	55-59 DOOR INNER PANEL LH	CHEVY PU	2	C123	\$65.32	\$71.49
3287	1103DF	51-54 DOOR WINDOW TRACK RH=LH	CHEVY PU	6	A37	\$66.30	\$66.48
3287	1103DK	55-59 EXTERIOR WINDSHIELD SUNVISOR	CHEVY PU	1	E102	\$84.00	\$88.08
3287	1103DL	47-53 WINDSHIELD SUNVISOR BRACKET	CHEVY PU	2	B92	\$17.64	\$17.94
3287	1103DM	47-53 WINDSHIELD SUNVISOR BRACKET	CHEVY PU	1	B92	\$8.82	\$8.97
3287	1103DS	60-66 WINDSHIELD SUNVISOR BRACKET	CHEVY PU	1	B92	\$8.82	\$8.94
3287	1103DT	60-66 WINDSHIELD SUNVISOR BRACKET	CHEVY PU	1	B92	\$8.82	\$8.94
3287	1103DU	67-72 WINDSHIELD SUNVISOR BRACKET	CHEVY PU	_ 2	B92	\$20.16	\$20.40
3288	1103DW	47-59 WINDSHIELD SUNVISOR PAS	CHEVY PU	12	B92	\$161.28	\$163.62
3285	1103DX	60-66 WINDSHIELD SUNVISOR PAS	CHEVY PU	2	B92	\$30.24	\$30.51

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-08-15	CEVA	ORGIN	2017-08-16

PO#	ITEM	DESCRIPTION	VPART NO.	SHIP OTY	LOCATION	FOB	EXT
_			MAKE			_	COST
3293	1103E	DOOR RELAY RH 47-54	CHEVY PU	2	B94	\$22.68	\$23.19
3287	1103F	DOOR RELAY LH 47-54	CHEVY PU	2	B94	\$22.68	\$23.19
3285	1103IB	60-63 DOOR RELAY LH	CHEVY PU	2	В93	\$21.00	\$21.51
2205	4400777	67-71 DOOR SHELL LH			D.(1	# <b>20 5</b> 00	<b>#245.20</b>
3287	1103KD	JIMMY/BLAZER	CHEVY PU	1	D61	\$205.00	\$245.28
2207	1102175	72 DOOR SHELL LH		1	D(1	#225 O.C	<b>#0.42.24</b>
3287	1103KE	BLAZER/JIMMY	CHEVY PU	1	D61	\$225.96	\$243.34
2207	11031717	73-87 DOOR OUTER LOWER	TP		F151	ф12.c2	Φ15 O7
3287	1103KK	PANEL RH	CHEVY PU	2	F171	\$13.62	\$15.07
2207	1102171	73-87 DOOR OUTER LOWER	TP	1	F171	¢	¢7.50
3287	1103KL	PANEL LH	CHEVY PU	1		\$6.79	\$7.52
2207	11021731	73-87 DOOR INNER LOWER	TP	1	CCA	¢10.50	¢10.0¢
3287	1103KN	PANEL LH	CHEVY PU	1	G64	\$18.50	\$19.86
3287	1103TB	72 DOOR LATCH/RODS REMOTE	CHEAN DIT	2	B32	\$75.40	\$74.21
	110012	, 2 D O STE ZATI OTZ TROĐE TREMIO TE	CHEVY PU	<del>                                     </del>	202	Ψ,εσ	Ψ,21
3287	1103XC	51-54 VENT WINDOW RH	CHEVY PU	1	B112	\$39.00	\$39.80
3287	1103XD	51-54 VENT WINDOW LH	CHEVY PU	1	B103	\$39.20	\$40.00
3287	1103XK	47-50 DOOR WINDOW GLASS LH	CHEVY PU	1	B101	\$66.13	\$68.95
		64-66 DOOR WINDOW GLASS		1 .			
3287	1103XU	ASSY LH	CHEVY PU	1	C94	\$43.45	\$45.15
3287	1103Z	DOOR LATCH LH 52-54		2	B32	\$28.68	\$29.67
3401	11032	DOOR LATCH LH 32-34	CHEVY PU	4	D32	\$∠0.08	\$29.07
3287	1104A	ROCKER PANEL RH 60-66	CHEVY PU	2	C124	\$38.70	\$42.21

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-08-15	CEVA	ORGIN	2017-08-16

PO#	ITEM			LCHID OTV	LOCATION	FOB	EXT
		DESCRIPTION	MAKE	Sim Q11	LOCATION	ГОБ	COST
3287	1104B	ROCKER PANEL LH 60-66	CHEVY PU	1	C124	\$18.76	\$20.52
3293	1104DA	73-87 ROCKER PANEL RH OE	TP	3	E101	\$37.89	\$44.64
3293	1104DA	STYLE	CHEVY PU	3	EIUI	\$37.69	\$44.04
3293	1104E	ROCKER PANEL RH 47-55		1	E103	\$21.53	\$23.12
3293	110412	W/RUNNING NOA	CHEVY PU	1	12103	\$21.33	\$23.12
3293	1104F	ROCKER PANEL LH 47-55		_ 2	E103	\$43.78	\$46.96
3293	11041	W/RUNNING BOA	CHEVY PU	2	E103	φ <del>4</del> 3.76	\$40.70
3293	1104G	INNER DOOR STEP WITH		_ 2	C91	\$79.20	\$90.30
3293	1104G	ROCKER RH	CHEVY PU	2	C91	\$19.20	\$90.30
3293	1104H	INNER DOOR STEP WITH			C92	\$119.88	\$136.53
3293	110411	ROCKER LH	CHEVY PU	3	C92	\$119.00	\$130.33
3289	1104K	55-66 SHORT BED STEP RH	CHEVY PU	4	C124	\$144.00	\$169.08
2200	11047	55.66 GHODT DED GTED I II		1 2	C124	Φ100 4 <b>2</b>	#122.07
3289	1104L	55-66 SHORT BED STEP LH	CHEVY PU	3	C124	\$108.42	\$122.07
3293	1104M	68-72 VENT WINDOW ASSY RH	CHEVY PU	3	B122	\$388.71	\$394.11
3293	1104S	55-59 ROCKER PANEL LH	CHEVY PU	2	E101	\$31.92	\$32.52
2200	440477	-2-20 60000 1111	CHEVITO	<u> </u>	200	000.44	
3288	1104U	55-59 STEP HANGER LH	CHEVY PU	2	B22	\$23.46	\$21.69
3289	1106AB	47-54 CAB FLOOR PAN RH	CHEVY PU	- 1	D105	\$32.83	\$41.02
			CHEVITU				
3289	1106AC	47-54 CAB FLOOR PAN LH	CHEVY PU	3	D105	\$98.43	\$133.14
3293	1106AY	67-72 CAB FLOOR LH	CHEVY PU	2	B101	\$33.60	\$51.39
2202	110CD A	60-66 OUTER CAB FLOOR/INNER			G21	#100 <b>2</b> 4	Ø115.50
3293	1106BA	ROCKER	CHEVY PU	3	C31	\$108.24	\$115.53

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-08-15	CEVA	ORGIN	2017-08-16

ITEM	DESCRIPTION	VPART NO.	SHID OTV	LOCATION	FOR	EXT
TIENI	DESCRIPTION	MAKE	Shir Q11	LUCATION	гов	COST
1106BC	67-72 OUTER CAB FLOOR/INNER		_ լ	C63	\$30.24	\$36.88
110000	ROCKER	CHEVY PU	1	003	\$30.24	φ30.00
1106DAWT	47-54 COWL OUTER LOWER			F111	\$86.24	\$108.70
HODAWI	PANEL LH	CHEVY PU	ļ , ,	12111	\$60.24	\$100.70
1109T	HOOD HINGE RH 55-57 W/SPRING	CHEVY PU	2	A106	\$54.06	\$55.09
1109U	HOOD HINGE LH 55-57 W/SPRING	CHEVY PU	2	A106	\$54.18	\$55.21
11147	67.72 EOOT WELL DANIEL LIL	,	,	D02	\$15.00	\$16.40
11142	07-72 FOOT WELL FANEL LH	CHEVY PU	2	D93	\$13.92	\$10.40
1115H	HEAD LAMP BEZEL 69-72 PAIR		_ 2	C42	\$43.30	\$46.03
	CHEVY	CHEVY PU		J	,	,
1115HA	HEAD LAMP BEZEL 69-72 PAIR		_ 2	B34	\$151.20	\$152.46
	GMC	CHEVY PU				
1115I	HEADLAMP BEZEL 47-55 PAIR	CHEVY PU	1	A63	\$11.84	\$12.28
1115I	HEADLAMP BEZEL 47-55 PAIR	CHEVY PU	1	A63	\$11.84	\$12.28
1115L	WINDOW REGULATOR RH 72	CHEVY PU	3	A114	\$46.11	\$48.51
	54-59 FRONT RED PANEL					
1119B	STEPSIDE	CHEVY PU	3	M91	\$151.20	\$162.81
	47-72 RECTANGULAR	,	_			
1151E	STAINLESS MIRROR	CHEVY PU	6	F164	\$38.82	\$39.81
44515	47-72 RECTANGULAR			TI4 C 4	<b>42.7</b> 0.7	A
1151E	STAINLESS MIRROR	CHEVY PU	7 4	F164	\$25.88	\$26.54
11521	60-66 EXTERIOR MIRROR ARM			F1.62	#20.24	ф20. c2
11531	LH	CHEVY PU	7 2	F162	\$30.24	\$30.63
1155 A	47-53 INTERIOR REAR VIEW			E1.64	¢10.00	¢10.00
1155A	MIRROR BKT	CHEVY PU	¬ ,	F104	\$10.08	\$10.08
	1109U 1114Z 1115H 1115HA 1115I 1115I	1106BC         67-72 OUTER CAB FLOOR/INNER ROCKER           1106DAWT         47-54 COWL OUTER LOWER PANEL LH           1109T         HOOD HINGE RH 55-57 W/SPRING           1109U         HOOD HINGE LH 55-57 W/SPRING           1114Z         67-72 FOOT WELL PANEL LH           1115H         HEAD LAMP BEZEL 69-72 PAIR CHEVY           1115HA         HEAD LAMP BEZEL 69-72 PAIR GMC           1115I         HEADLAMP BEZEL 47-55 PAIR           1115I         HEADLAMP BEZEL 47-55 PAIR           1115L         WINDOW REGULATOR RH 72           1119B         54-59 FRONT BED PANEL STEPSIDE           1151E         47-72 RECTANGULAR STAINLESS MIRROR           1151E         47-72 RECTANGULAR STAINLESS MIRROR           1153I         60-66 EXTERIOR MIRROR ARM LH           1153A         47-53 INTERIOR REAR VIEW	1106BC	1106BC	TTEM	TIEM

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-08-15	CEVA	ORGIN	2017-08-16

PO#	ITEM	DESCRIPTION	VPART NO.	CHID OTV	LOCATION	FOB	EXT
PO#	IIEM	DESCRIPTION	MAKE	SHIP Q11	LUCATION	ГUБ	COST
3282	1155D	60-71 INTERIOR REAR VIEW			F164	\$28.11	\$28.29
3282	1155D	MIRROR BKT	CHEVY PU	3	F 104	\$28.11	\$28.29
3289	1412	70 REAR BUMPER BRACKET	CHEVELLE	_ 2	G104	\$108.66	\$113.27
		69-72 ROOF RAIL WEATHER	CHEVELLE				
3287	1418E	STRIP PR	CHEVELLE	2	C61	\$37.86	\$39.01
		66-67 DOOR FRAME WEATHER	CHEVELLE				
3287	1418F	STRIP PR	CHEVELLE	3	C61	\$55.53	\$56.41
			CHEVELLE				
3285	1452J	68-72 A/C CENTER VENT	CHEVELLE	3	A85	\$26.79	\$26.84
3285	1452K	68-72 A/C CENTER VENT	CHEVELLE	4	A85	\$25.20	\$25.26
	1 10 222	00 /212 0 021 (1211 ) 22 (1	CHEVELLE		1200	Ψ20.20	Ψ20.20
3285	1457	FRONT BUMPER 64	CHEVELLE	2	F132	\$258.90	\$281.50
2202	14600	TRUNK FLOOR RH 68-72 A			G1 <b>5</b> 0	407.05	Φ122.45
3293	1462D	BODY**	CHEVELLE	5	G172	\$97.05	\$123.45
2202	14600	TRUNK FLOOR CENTER 68-72 A			G102	#20.c2	<b>#45.01</b>
3293	1462E	BODY	CHEVELLE	_ 2	G182	\$38.62	\$45.31
3293	1462F	TRUNK FLOOR LH 68-72 A BODY		4	G182	\$77.48	\$98.60
3273	14021	TROTAL LOOK EIT 00-72 M BOD I	CHEVELLE	<b></b>	0102	Ψ77.40	Ψ70.00
3287	1462G	71-72 COMPLETE TRUNK FLOOR	CHEVELLE	2	J111	\$515.76	\$581.34
	11/222	64-67 HUMP PANEL			74.	<b></b>	<b></b>
3287	1462WC	WO/CONSOLE	CHEVELLE	_ 2	F174	\$40.14	\$41.46
2205	4.464775447	68-72 PACKAGE SHELF PANEL *			C124	<b>#140.14</b>	Φ126.4 <b>5</b>
3287	1462ZDWT	WTP *	CHEVELLE	1	C126	\$148.14	\$136.47
2202	1166	110 0D 110 10T D11 50 52	3976676		4.02	Φ <b>.</b> 7.2.3.1	Φ.Ε.Α
3293	1466	HOOD HINGE RH 70-72	CHEVELLE	3	A93	\$53.31	\$54.61
3293	1467	HOOD HINGE LH 70-72	a	2	A93	\$35.54	\$36.41
3273	1407	1100D IIII(OL EII 70-72	CHEVELLE		A)3	ψ55.54	ψ50.41

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-08-15	CEVA	ORGIN	2017-08-16

DO#	TOTAL A	DESCRIPTION	VPART NO.	CHID O'EX	T OCATION	EOD	EXT
PO#	ITEM	DESCRIPTION	MAKE	SHIPQIY	LOCATION	FOB	COST
2207	1472	EDON'T INNED EENDED DIJ CC	3872138	2	1171	¢02.50	¢124.00
3287	14/2	FRONT INNER FENDER RH 66	CHEVELLE	2	J171	\$92.50	\$134.08
3285	1472D	FRONT INNER FENDER RH 68-72	F92604	6	J141	\$297.90	\$407.82
3263	14/20	TRONT INNER PENDER RIT 08-72	CHEVELLE	•	J141	\$271.70	Φ407.62
3285	1472E	FRONT INNER FENDER LH 68-72	6264843	5	J151	\$248.25	\$339.85
3203	14/26	TROTT INVERTENDER EIT 00-72	CHEVELLE		3131	Ψ2-10.23	Ψ337.03
3285	1472F	REAR OUTER WHEELHOUSE RH	9815030		G178	\$55.88	\$73.72
3263	17/21	70-72	CHEVELLE		G176	ψ33.66	ψ13.12
3285	1472G	REAR OUTER WHEELHOUSE LH	9815031		G156	\$55.88	\$74.12
3263	14720	70-72	CHEVELLE		0130	ψ33.66	ψ/4.12
3285	1472H	REAR OUTER WHEELHOUSE RH			G178	\$62.80	\$80.17
3263	14/211	66-67	CHEVELLE		G176	Ψ02.00	ψ00.17
3285	1472J	REAR OUTER WHEELHOUSE LH			G175	\$61.82	\$79.11
3203	17/20	66-67	CHEVELLE		G173	Ψ01.02	Ψ77.11
3287	1488D	71-72 RADIATOR SUPPORT	CHEVELLE	3	F148	\$216.24	\$244.05
3285	1488F	70-72 HOOD CATCH & SPRING	CHEVELLE	2	A76	\$33.30	\$33.66
3285	1491A	FRONT BUMPER FILLER 66	CHEVELLE	1	C22	\$25.25	\$27.77
			CHEVELLE				
3285	1494A	64-72 BRAKE PEDAL PAD	CHEVELLE	2	C82	\$2.74	\$2.63
3285	1495	69 EMERGENCY BRAKE ASSY	CHEVELLE	2	C81	\$73.54	\$74.14
3285	1495J	64-72 CONTROL ARM LOWER RH	CHEVELLE	3	A91	\$230.19	\$107.07
3285	1495K	64-72 CONTROL ARM LOWER LH	CHEVELLE	3	A91	\$234.42	\$107.07
3288	14B53131	68-72 CARPET BLACK 80/20 LOOP	CHEVELLE	4	F183	\$405.64	\$420.94

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-08-15	CEVA	ORGIN	2017-08-16

PO#	ITEM	DESCRIPTION	VPART NO.	SHIP OTV	LOCATION	FOB	EXT
10"		DESCRIPTION	MAKE	Sim Q11		100	COST
3293	1506AWT	66-67 WHEELHOUSE COMPLETE		1	F52	\$118.51	\$133.63
3273	1300A W 1	RH	GTO		152	\$110.51	Φ133.03
3293	1506BWT	66-67 WHEELHOUSE COMPLETE		1	F62	\$109.94	\$125.06
3273	13000 11 1	LH	GTO		102	\$107.74	\$125.00
3293	1506CWT	66-67 WHEELHOUSE INNER RH	GTO	1	G156	\$47.88	\$57.38
3293	1506DWT	66-67 WHEELHOUSE INNER LH	GTO	1	G156	\$48.48	\$57.97
2200	15004	68-70 RADIATOR SUPPORT			E1.40	ф2 <b>7.</b> 2.6	ф20. <b>21</b>
3289	1509A	UPPER	GTO	2	F142	\$37.26	\$39.21
2200	1500C	68-72 RADIATOR TO CORE		2	414	¢1.6.7.4	¢17.04
3289	1509C	SUPPORT	GTO	3	A14	\$16.74	\$17.04
3293	1527A	66 HEADER PANEL	CTO	1	F125	\$116.87	\$122.11
			GTO				
3293	1536	66-67 HEATER BOX	GTO	1	A134	\$115.20	\$118.84
3289	1556T	68-72 LOWER DOOR HINGE LH	GTO	- 3	B23	\$72.84	\$73.47
			GIO			,	
3289	1556X	LOWER DOOR HINGE LH	GTO	6	A104	\$144.48	\$145.02
3289	1556Y	UPPER DOOR HINGE RH	GTO	3	A104	\$59.88	\$60.53
3289	1556Z	UPPER DOOR HINGE LH		5	A104	\$100.60	\$101.08
3289	1550Z	UPPER DOOR HINGE LH	GTO	5	A104	\$100.60	\$101.08
3288	1560	SEAT TRACK RH 68-72 2PC/SET	GTO	3	A142	\$93.78	\$95.49
3288	1561	SEAT TRACK LH 68-72 2PC/SET	GTO	1	A142	\$31.60	\$31.93
3285	1608A	FRONT BUMPER 65		2	F93	\$115.60	\$127.97
3403	1000/1	1 KOWI DOWII EK 05	NOVA		173	φ115.00	Ψ121.71

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-08-15	CEVA	ORGIN	2017-08-16

PO#	ITEM	DESCRIPTION	VPART NO.	CHID OTY	LOCATION	FOB	EXT
PO#	HEM	DESCRIPTION	MAKE	SHIPQIY	LUCATION	rob	COST
3285	1645WT	66-67 FIREWALL	NOVA	1	G162	\$159.43	\$171.61
3285	1647	66-67 GLOVE BOX DOOR	NOVA	2	D101	\$104.00	\$102.25
3285	1660	66-67 COMPLETE ROCKER PANEL RH	NOVA	1	E91	\$123.97	\$127.24
3285	1671A	66-67 ROOF HEADLINER RETAINER	NOVA	2	D93	\$116.00	\$118.16
3285	1751D	62-64 VENT WINDOW ACTUATOR LH	IMPALA	1	C42	\$30.59	\$30.62
3285	1753	63 DOOR LATCH LH	IMPALA	3	A134	\$105.00	\$103.17
3285	1757	63-64 DOOR LATCH ASSEMBLY PR	IMPALA	3	1C12	\$117.00	\$114.36
3285	1786WT	65-70 ROCKER PANEL INNER RH	IMPALA	1	E91	\$33.12	\$33.88
3285	1787WT	65-70 ROCKER PANEL INNER LH	IMPALA	1	E91	\$33.12	\$33.88
3285	1790	63-64 WINDOW REGULATOR RH	IMPALA	1	A111	\$32.38	\$33.15
3293	20030351	71-81 DOME LIGHT BASE	CAMARO	2	A26	\$9.98	\$10.01
3288	337	69-78 IGNITION,DOOR,GLOVE & TRUNK	NOVA	3	4-2	\$113.85	\$100.78
3288	3410	64-65 HOOD	FALCON	1	E81	\$290.00	\$287.24
3288	3415	64-65 RADIATOR SUPPORT	FALCON	1	F127	\$150.00	\$153.42
3288	3430	64-65 COMPLETE FLOOR PANEL	FALCON	1	J81	\$270.00	\$286.95

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-08-15	CEVA	ORGIN	2017-08-16

DO#	TTEN	DESCRIPTION	VPART NO.	CHID O'TY	LOCATION	EOD	EXT
PO#	ITEM	DESCRIPTION	MAKE	SHIPQIY	LOCATION	FOB	COST
2200	26254	FRONT BUMPER GUARD 67/8	C7ZZ17996B	2	172	¢22.20	¢22.04
3289	3637A	PAIR CHROME	MUSTANG	_ 2	A73	\$32.28	\$32.84
3276	3640A	REAR BUMPER 69-70	C9ZZ17906A		F91	\$188.22	\$192.78
3270	3040A	REAR BUMPER 09-70	MUSTANG	3	F 91	\$100.22	\$192.70
3283	3641M	DOOR SHELL RH 65-66	C5ZZ6520124B	1	G12	\$128.00	\$165.14
3203	3041141	DOOK SHELL KII 03-00	MUSTANG		G12	ψ120.00	Ψ105.14
3283	3641N	DOOR SHELL LH 65-66	C5ZZ6520125B	_ 2	G12	\$256.00	\$333.10
3203	304111	DOOK SHELL LII 03-00	MUSTANG		G12	Ψ230.00	Ψ555.10
3275	3647LDWT	67-70 ROCKER PANEL OUTER RH	MUSTANG	2	E91	\$135.92	\$144.47
3275	3647MDWT	67-70 ROCKER PANEL OUTER LH	MUSTANG	1	E91	\$67.96	\$72.23
3282	3647R	FULL FLOOR PANEL RH 65-68	MUSTANG	3	G172	\$85.02	\$103.47
3282	3647S	FULL FLOOR PANEL LH 65-68	MUSTANG	2	G144	\$56.68	\$68.96
3285	4012A	56 HOOD LATCH	CHEVY PU	3	B44	\$83.43	\$85.28
2205	4054	56 FRONT BUMPER 1 PIECE		1	E124	¢210.00	¢220.41
3285	4054	STYLE	CHEVROLET	1	F124	\$210.00	\$220.41
3289	5961568	TAIL LAMP LENS RH 69	5961568	2	A134	\$71.24	\$68.77
3289	5901508	STANDARD	CAMARO		A134	\$/1.24	\$08.7
3289	8732777	70-81 DOME LIGHT LENS	CAMARO	10	A26	\$13.10	\$11.50
2200	EN 52 (52	68 FENDER EMBLEM		1		Φ1.C.CΩ	ф1 <b>7</b> О
3289	EM3652	"MUSTANG" SCRIPT	MUSTANG	4		\$16.60	\$17.02
3289	EM3653	69-73 FENDER & TRUNK SCRIPT	MUSTANG	6		\$29.94	\$30.57
2200	EM2655	67 HOOD LETTER SET "FORD"				¢22.20	¢22.50
3288	EM3655	4PCS	MUSTANG	5		\$22.30	\$22.68

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-08-15	CEVA	ORGIN	2017-08-16

PO#	ITEM	DESCRIPTION	VPART NO.	SHIP OTY	LOCATION	FOB	EXT
			MAKE				COST
3288	G06	47-49 DASH GAUGES	CHEVY PU	2	CUP3	\$75.60	\$75.69
3287	G15	50-53 DASH GAUGES	CHEVY PU	2	CUP3	\$75.60	\$72.18
3285	K892	HEADLAMP MOUNTING BUCKET RH 67-69	CAMARO	3	1A12	\$34.20	\$34.80
		HEADLAMP MOUNTING	CAMARO				
3285	K893	BUCKET LH 67-69	CAMARO	3	2C1	\$36.00	\$36.60
3285	K902	PILLAR POST MOLDING 67 CPE		1	B23	\$54.59	\$54.97
3263	K902	CHROM PR	CAMARO	1	D23	\$34.37	φ34.97
3288	L3606	69-70 BACK UP LAMP ASSY RH	MUSTANG	1	A16	\$19.47	\$19.57
3288	L3661A	69 FRONT SIDE MARKER LENS		_ 5	A12	\$32.75	\$32.77
3200	LS001A	ASSY	MUSTANG	3	A12	\$32.13	φ32.11
3288	L3661B	69 FRONT/REAR SIDE MARKER		1	A13	\$9.15	\$9.27
		BEZEL PR	MUSTANG			7	77
3285	L4603	56 LICENSE PLATE LIGHT	CHEVROLET	3	A43	\$38.16	\$38.34
3287	LH11	55-57 HEADLAMP BUCKET		10	C51	\$225.10	\$226.55
3207	Liiii	RH/LH	CHEVY PU	10	CSI	Ψ223.10	Ψ220.33
3279	LH41	64-66 WINDSHIELD WIPER			B11	\$54.60	\$54.63
		SWITCH	GTO			7	7.0.00
3290	LH70	79-81 HEAD LAMP BUCKET SET		2		\$110.00	\$110.00
		4PCS	TRANS AM				
3289	LP18	40-53 TAIL LAMP ASSY BLACK	CHELIN DV	10	A16	\$193.20	\$194.55
		W/CHROME	CHEVY PU				
3287	M1029H	75-81 REAR WINDOW MOLDING KIT	CAMARO	2	A23	\$138.12	\$145.31
			CAMARO				
3287	M1029J	78-81 REAR WINDOW MOLDING KIT BLACK	CAMARO	2	A22	\$142.26	\$146.11
		KII DLACK	CAMARO				

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-08-15	CEVA	ORGIN	2017-08-16

PO#	ITEM	DESCRIPTION	VPART NO. MAKE	SHIP QTY	LOCATION	FOB	EXT COST
3289	M1058	70-73 HEADLAMP BEZEL RH	G.13.6.1.D.0	2	A45	\$33.04	\$33.55
3207	111030		CAMARO		A43	Ψ33.04	Ψ33.33
3285	M1100	328844 FR WHEEL OPEN MLDG	328844	8	A51	\$31.52	\$55.88
		RH 73-80	CHEVY PU			·	
3285	M1101	328843 FR WHEEL OPEN MLDG	328843	<b>-</b>   8	A51	\$31.60	\$55.88
		LH 73-80	CHEVY PU			,	
3285	M1102	14022806 FR WHEEL OPEN MLG	14022806	15	A51	\$58.50	\$115.28
	1,11102	RH 81-87	CHEVY PU		1202	ΨΕ Ο ΙΕ Ο	Ψ110.20
3285	M1103	14022805 FR WHEEL OPEN MLG	14022805	14	A51	\$54.60	\$107.73
3203	WIIIOS	LH 81-87	CHEVY PU	17	ASI	Ψ24.00	Φ107.73
3285	M1104	6273600 RR WHEEL OPEN MLDG	6273600		A51	\$85.80	\$169.29
3283	W11104	RH 73-87	CHEVY PU	22	ASI	\$65.60	\$109.29
2205	3.51105	6273599 RR WHEEL OPEN MLDG	6273599	21	4.51	ф0 <b>2</b> 7.4	Φ1.CQ 4.4
3285	M1105	LH 73-87	CHEVY PU	21	A51	\$82.74	\$162.44
2200	3/110/	FFONT WHEEL MOULDING 88-91	15616312	1	A122 \$5.	Φ <b>7</b> .01	ф0. <b>22</b>
3288	M1106	RH BLZER	CHEVY PU	1	A122	\$5.91	\$8.22
•••	3.5140.	FRONT WHEEL MOLDING LH	15616313			<b>4.7.</b> 00	40.00
3288	M1107	1988-91	CHEVY PU	1	A122	\$5.90	\$8.29
		REAR WHEEL MOLDING RH	15616291	_			
3288	M1108	1988-91	CPU/BLAZER	2	A122	\$11.80	\$15.15
			15616292	_			
3288	M1109	RR WHL MLDG 88-91 LH BLZER	CHEVY PU	2	A122	\$11.82	\$15.53
		69-72 GMC FRONT FENDER					
3287	M1136C	MOLDING RH	GMC	<b>-</b>   4	A126	\$99.92	\$101.06
		69-72 GMC FRONT FENDER	- CIVIC		A126		
3287	M1136D	MOLDING LH	GMC	3		\$74.46	\$75.28
		FENDER SIDE MOLDING 69-72	OMC				
3289	M1210	RH/LH	CHEVY PU	6	A81	\$126.96	\$130.59
			CHEVIIO				
3289	M1215	UPPER CAB CORNER MOLDING LH 69-72	CHEVY PU	2	A122	\$17.32	\$17.38
		Li1 07-12	DACE:14				

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-08-15	CEVA	ORGIN	2017-08-16

DO#	TOTAL A	DESCRIPTION	VPART NO.	CHID OTY	I OCLUTION	EOD	EXT
PO#	ITEM	DESCRIPTION	MAKE	SHIPQTY	LOCATION	FOB	COST
3289	M1216	UPPER BEDSIDE MOLDING 69-72		2	B62	\$35.38	\$37.65
3289	N11210	SHORT	CHEVY PU		B02	\$33.38	\$37.03
3289	M1217	UPPER BEDSIDE MOLDING 69-72		4	B63	\$88.52	\$93.98
3209	W11217	LONG	CHEVY PU	4	D03	\$66.32	\$93.90
3289	M1220	LOWER FRONT FENDER	CV01-M11		A122	\$16.56	\$16.81
3209	W1122U	MOLDING RH 69-72	CHEVY PU		A122	\$10.50	\$10.61
3289	M1221	LOWER FRONT FENDER	CV01-M12	_ 1	A122	\$8.26	\$8.38
3209	W11221	MOLDING LH 69-72	CHEVY PU	1	A122	\$6.20	φο.30
3289	M1244	LOWER FRONT BED MOLDING	CV01-M21		B15	\$25.14	\$26.28
3209	W11244	RH 69-72	CHEVY PU		Б13	\$23.14	\$20.26
3289	M1245	LOWER FRONT BED MOLDING	CV01-M22		B15	\$25.32	\$26.02
3209	W11243	LH 69-72	CHEVY PU		Б13	\$23.32	\$20.02
3285	M1350	HOOD MOULDING 64	3838493		B72	\$56.64	\$58.75
3203	W11330	HOOD MOULDING 04	CHEVELLE		D/2	\$30.04	φ36.73
3285	M1359B	INSTRUMENT BEZEL 66-67**	CHEVELLE	3	A102	\$55.05	\$56.78
3288	M1379	HOOD LOUVER 69 PAIR	CHEVELLE	1	A125	\$61.16	\$61.32
2205	M1400	CA DE AD HOW MOLDING			422	¢20.22	¢20.44
3285	M1480	64 REAR "C" MOLDING	CHEVELLE	1	A33	\$29.23	\$29.44
3285	M1530	67 TRUNK LID MOLDING	GTO	1	A83	\$30.60	\$30.73
2205	N/1521	67 TRUNK LID EXTENSION		2	162	¢ (2.70	¢<5.05
3285	M1531	MOLDING PR	GTO	2	A63	\$63.78	\$65.95
3287	M1609	BODY BUSHING KIT 68-74 NOVA	CAMARO	15	C51	\$219.15	\$221.40
3293	M1630B	73-74 HOOD MOLDING	NOVA	1	A111	\$30.33	\$30.60
3285	M1719B	1964 GRILLE	IMPALA	2		\$347.10	\$358.42

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-08-15	CEVA	ORGIN	2017-08-16

PO#	ITEM	DESCRIPTION	VPART NO.	SHIP OTV	LOCATION	FOB	EXT
10"	1112111	DESCRIPTION	MAKE	51111 Q11	LOCATION	ГОВ	COST
3290	M1719P	66 GRILLE SUPPORT LOWER		1		\$89.00	\$89.00
3270	W117171	APRON 3PCS	IMPALA			\$67.00	ψ62.00
3275	M1726G	64-67 ACCELERATOR PEDAL			A76	\$29.40	\$29.85
3213	W11720G	PAD	CHEVELLE	3	Ait	\$27.40	\$27.03
3288	M3572	FRONT BUMPER OUTER ARM	]7ZZ 17754A	8	G121	\$51.76	\$54.44
3200	1413372	RH 67-68	MUSTANG	•	G121	ψ51.70	Ψ,74.44
3288	M3658C	69-70 MOLDING CLIPS			G102	\$10.23	\$10.32
3200	W13030C	WINDSHIELD	MUSTANG		G102	\$10.23	\$10.52
3289	M6075	70 QUARTER EXTENSION			A135	\$22.86	\$22.92
3209	1/10073	MOLDING LH	CHALLENGER	3	AISS	\$22.60	\$22.92
3292	T05	FUEL SENDING UNIT 70	DOWY 9275A	_ 2	B82	\$22.62	\$23.88
3292	103	FOEL SENDING UNIT 70	MUSTANG		D02	\$22.02	\$23.00
3292	T06	FUEL SENDING UNIT 71-73	D1ZZ 9275A	_ 2	B82	\$22.78	\$23.08
3292	100	FUEL SENDING UNIT 71-73	MUSTANG	2	D02	\$22.70	\$23.06
3292	T10	GAS TANK 67-68	T10	3	P13	\$113.52	\$135.08
3292	110	CAMARO/FIREBIRD18 GAL	CAMARO	3	113	\$113.32	\$133.06
3292	T13B	78-81 GAS TANK W/NECK	CAMARO	_ 2	P33	\$102.90	\$144.18
			CAMARO	<del>-</del>		7-0-12-0	7
3292	T13F	67-69 GAS TANK STRAPS STAINLESS PR	CAMARO	2	F181	\$30.62	\$31.07
		STAINLESS PR	CAMARO				
3292	T13K	76-81 GAS TANK STRAPS PR	CAMARO	3	F181	\$27.90	\$28.98
		SENDING UNIT 68-69 6 CLY 5/16"	428844				
3292	T15	LINE(M22) CAMARO / 70-71	,	1	B81	\$20.90	\$22.10
		NOVA	CAMARO				
		76-81 3/8" FUEL SENDING					
3292	T18E	UNITSTAINLESS 76-79 NOVA 1/4		2	B85	\$38.22	\$44.46
		RETURN	CAMARO				
		68-70 FUEL SENDING UNIT 3/8"					
3292	T202	&	CITA D CIMODA D	1	B85	\$13.76	\$14.29
	1/4"COR	NET/BELEVDERE/ROADRUNNER/	CHAKGMOFAK				
3292	T206	71-72 FUEL SENDING UNIT	NED	1	B85	\$13.44	\$14.32
-	5/10	"CORONET/ROADRUNNER/CHAR	GER MOPAR				

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-08-15	CEVA	ORGIN	2017-08-16

PO#	ITEM	DESCRIPTION	VPART NO.	CHID OTV	LOCATION	FOB	EXT
PO#	TIENI	DESCRIPTION	MAKE		LUCATION	гOВ	COST
3292	T24	1970 22 GALLON GALVANIZED TANKW/O DRAIN PLUG	MUSTANG	2	P42	\$77.46	\$96.60
3292	T25	GAS TANK 64/7 CHEVELLE, 65/6 IMPALA31"X38.5"X7.5"	CHEVELLE	4	P22	\$221.56	\$274.06
3292	T25B	GAS TANK STRAPS 65-70 2PC WO/BOLTS	IMPALA	3	A133	\$23.25	\$24.15
3292	T25D	59-60 GAS TANK STRAPS PR	LC IMPALA	1	F181	\$10.97	\$11.29
3292	T28D	68-72 GAS TANK BRACE RH	NOVA	1	F146	\$30.38	\$32.36
3292	T28E	68-72 GAS TANK BRACE LH	NOVA	1	F146	\$29.50	\$31.48
3292	Т29С	69-70 GAS TANK W/O NECK24 GALLON, HOSE INCLUDED	IMPALA	_ 2	P43	\$201.62	\$226.61
3292	T32A	GAS CAP 64-72 NON-VENTED	CHEVELLE	7	B71	\$21.28	\$21.39
3292	Т37	55-57 FUEL SENDING UNIT 5/16" LINE	CHEVROLET	3	B82	\$63.00	\$63.95
3292	T37A	55-57 FUEL SENDING UNIT 3/8" LINE	CHEVROLET	_ 2	B83	\$42.00	\$26.47
3292	Т38	58-60 FUEL SENDING UNIT 5/16" LINE	CHEVROLET	1	B82	\$15.21	\$15.60
3292	T40	FUEL SENDING UNIT 61-645/16" FUEL LINE	IMPALA	5	B84	\$80.80	\$82.52
3292	T42	GAS CAP 67-68 "SS 350"	CAMARO	1	B82	\$18.15	\$18.21
3276	T54	GAS TANK 70-72 W/E.E.C	CHEVY PU	2	P44	\$181.46	\$206.84
3292	T61	FUEL SENDING UNIT 60-66	CHEVY PU	2	B82	\$24.16	\$25.33

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-08-15	CEVA	ORGIN	2017-08-16

PO#	ITEM	DESCRIPTION	VPART NO. MAKE	SHIP QTY	LOCATION	FOB	EXT COST
3276	T65	72 FUEL SENDER STD TRAN	CHEVY PU	2	B83	\$26.26	\$27.43
3292	T66	72 FUEL SENDER AUTO TRANSDUAL LINE	CHEVY PU	2	B83	\$26.26	\$27.43
3292	T72	FUEL SENDING UNIT 68-70 4BLL & A/C350,400,454,396 3/8"	6428035 CHEVELLE	5	B83	\$61.95	\$64.12
3292	T86D	68-70 FUEL TANK W/4 VENT PIPE 19 GACHARGER	MOPAR	1	P93	\$52.62	\$61.27
3292	<b>T86F</b> GA	68-70 FUEL TANK W/O VENT 18 LLONBARRACUDA/DART/VALLA	NT MOPAR	2	P93	\$79.18	\$94.30
3292	Т88	70-74 FUEL SENDING UNIT 3/8" & 1/4"	CHALLENGER	3	B82	\$54.96	\$57.13
3285	TU64AN	64 BACK UP LAMP LENS	CHEVELLE	2	A14	\$43.90	\$44.14
3289	X3670	67-68 WINDSHIELD GLASS FB	MUSTANG	3	N101/E	\$200.82	\$224.26
					TOTAL	\$22414.77	\$24626.98