VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-08-28	CEVA	ORGIN	2017-08-31

## **CONTAINER 70830 DETAILS**

PO#	ITEM	DESCRIPTION	VPART NO.	SHIP OTY	LOCATION	FOB	EXT
	1123,1		MAKE	SIII VII			COST
3297	1099G	INNER FENDER RH 67-72	CHEVY PU	4	J161	\$109.24	\$109.24
3297	1099Н	INNER FENDER LH 67-72	CHEVY PU	4	J161	\$109.40	\$109.40
3294	1099Z	RADIATOR SUPPORT 69-72	CHEVY PU	2	F135	\$235.28	\$235.28
3297	1100E	BATTERY HOLD DOWN 55-57	CHEVY PU	2	F151	\$8.86	\$8.86
3294	1101U	DOOR HINGE 55-59 LOWER RH=LHN / SPRING	CHEVY PU	6	A124	\$126.18	\$126.18
3294	1101W	60-66 DOOR HINGE LH UP=LOW	CHEVY PU	1	A124	\$37.80	\$37.80
3294	1101Y	DOOR SKIN, PARTIAL LOWER RH 67-729"	CHEVY PU	1	D102	\$9.30	\$9.30
3294	1101Z	DOOR SKIN, PARTIAL LOWER LH 67-729"	CHEVY PU	1	D102	\$9.42	\$9.42
3297	1102AH	60-66 DOOR SKIN RH	CHEVY PU	2	C113	\$129.54	\$129.54
3297	1102AJ	60-66 DOOR SKIN LH	CHEVY PU	1	C113	\$64.77	\$64.77
3294	1102AN	47-55 DOOR INNER BOTTOM LH	CHEVY PU	2	B45	\$36.54	\$36.54
3296	1102AY	60-66 DOOR SKIN LOWER PANELRH=LH	CHEVY PU	4	A145	\$49.92	\$49.92
3296	1102BF	47-54 FRONT LOWER DOOR PILLAR LH	CHEVY PU	2	C42	\$31.30	\$31.30
3294	1102SB	47-54 DOOR INNER PANEL RH	CHEVY PU	2	A103	\$28.82	\$28.82
3298	1103IB	60-63 DOOR RELAY LH	CHEVY PU	2	В93	\$21.00	\$21.00

PAGE:3