| VENDOR | SHIP DATE | SHIP VIA | F.O.B | ONSHIP ETA |
|--------|------------|----------|-------|------------|
| DII | 2017-12-13 | CEVA | ORGIN | 2017-12-15 |

CONTAINER 71215 DETAILS

| PO# | ITEM | DESCRIPTION | VPART NO. | SHIP QTY | LOCATION |
|------|--------|---|-----------|----------|----------|
| | | | MAKE | | |
| 3344 | 1114A | CAB CORNER RH 55-59 | CHEVY PU | 5 | C122 |
| 3344 | 1114B | CAB CORNER LH 55-59 | CHEVY PU | 3 | C122 |
| 3346 | 1114C | CAB CORNER RH 60-66 | CHEVY PU | 5 | C122 |
| 3341 | 1114FA | 47-55 CAB CORNER INNER RH | CHEVY PU | 2 | D94 |
| 3341 | 1114FB | 47-55 CAB CORNER INNER LH | CHEVY PU | 1 | D94 |
| 3344 | 1115E | HEAD LAMP BEZEL 58-59 PAIR | CHEVY PU | 1 | C43 |
| 3342 | 1115HA | HEAD LAMP BEZEL 69-72 PAIR GMC | CHEVY PU | 1 | B34 |
| 3346 | 1116B | REAR BUMPER CHROME 67-72 FLEETSIDE | CHEVY PU | 3 | F124 |
| 3341 | 1119A | 47-53 FRONT BED PANEL | CHEVY PU | 3 | M91 |
| 3346 | 1119B | 54-59 FRONT BED PANEL STEPSIDE | CHEVY PU | 3 | M91 |
| 3342 | 1119E | 67-72 FRONT BED PANEL FLEETSIDESTEEL FLOOR | CHEVY PU | 2 | M91 |
| 3344 | 1130G | 60-67 VENT WINDOW HANDLE PR | CHEVY PU | 2 | A124 |
| 3341 | 1131 | WINDOW REGULATOR CRANK HANDLE 47- 66 | CHEVY PU | 30 | A125 |
| 3342 | 1136 | 58-59 HOOD LATCH GMC ONLY | CHEVY PU | 1 | A35 |
| 3341 | 1136 | 58-59 HOOD LATCH GMC ONLY | CHEVY PU | 1 | A35 |

PAGE:10