VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-26	1	ORGIN	2017-09-26

## **CONTAINER 3318 DETAILS**

PO# ITEM	DECCRIPTION	VPART NO.	CHID OTY	LOCATION	EOD	EXT	
	HEN	DESCRIPTION	MAKE	SHIPQIY	LOCATION	FOB	COST
3318 <b>1611A</b>	REAR BUMPER BRACKET 66-67		1	F156	\$14.39	\$14.39	
3310	3316 <b>1011A</b>	RH	NOVA	1	1130	\$14.35	\$14.57
3318 <b>1611B</b>	REAR BUMPER BRACKET 66-67		_ 1	F156	\$14.48	\$14.48	
		LH	NOVA		-		
3318	1612	FRONT BUMPER CHROME 68-69	NOVA	1	F101	\$89.18	\$89.18
3318	1613	FRONT BUMPER CHROME 70-72	NOVA	2	F101	\$184.54	\$184.54
2210	3318 <b>1614</b>	REAR BUMPER 68-72 NOVA71 /		2	F91 / F101	\$182.86	\$182.86
3318		72 VENTURA	NOVA	2			
3318	3318 <b>1614A</b>	FRONT BUMPER BRACKET RH		1	B22	\$17.81	\$17.81
3310	1014/1	68-72 2PC	NOVA				
3318	3318 <b>1614C</b>	68-72 REAR BUMPER BRACKET		_ 1	G122	\$21.53	\$21.53
		RH	NOVA				
3318	3318 <b>1614D</b>	68-72 REAR BUMPER BRACKET LH	NOVA	1	G122	\$21.53	\$21.53
			NOVA				
3318	1615B	FRONT BUMPER FILLER 66-67 **	NOVA	2	E113	\$55.92	\$55.92
3318	3318 <b>1615</b> C	FRONT BUMPER FILLER METAL		1	E113	\$30.18	\$30.18
3316		68-72**	NOVA				
3318	3318 <b>1615WT</b>	DECK LID FILLER PANEL 66-		1	C23	\$41.79	\$41.79
		67*WTP*	NOVA				,
3318	1616	FENDER RH 68-69	NOVA	2	D32	\$342.48	\$342.48
3318	1617	FENDER LH 68-69	NOVA	1	D32	\$176.79	\$176.79
3318	1617A	FENDER RH 70-74	NOVA	2	D13	\$340.00	\$340.00
3318	1617B	FENDER LH 70-74	NOVA	2	D13	\$358.74	\$358.74

PAGE:54