VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
B0018	2018-01-30	DEL	ORGIN	2018-01-30

CONTAINER 3364 DETAILS

PO# ITEM	DESCRIPTION	VPART NO.	CHID OTY	LOCATION	FOB	EXT	
		MAKE SHIP Q1 Y	LOCATION	FOB	COST		
3364	GL10-	64-72 CLUTCH ROD HOLE		4		\$44.00	\$44.00
3304	0504-CC	COVER W/HARDWARE	CHEVY PU				
	GL12-422-	C12-422- S 60-63 DOOR CHECK SUPPORT ON A PILLAR W/ROLL PIN AND HARDWARE		4			\$70.00
3364	S		CHEVY PU			\$70.00	
3364	GL14-	63-66 REAR CAB TO FRAME				\$64.00	\$64.00
3304	4141-R	SUPPORT	CHEVY PU	2		\$04.00	
3364	GL14-525-	67-72 CAB SUPPORT REPAIR		6	\$26.0	\$36.00	\$36.00
3304	CFP	PLATE	CHEVY PU	•		\$30.00	
3364	GL14-525-	67-72 REAR CAB TO FRAME		4		\$132.00	\$132.00
3304	CR	SUPPORT W/HARDWARE	CHEVY PU				
3364	GL16-	60-72 SEAT REAR COIL SPRING		2		\$52.00	\$52.00
3304	0510-S	UPPER W/HARDWARE	CHEVY PU				
3364	3364 GL17-0519	66-72 PARK CABLE BUSHING IN FRAME CROSS MEMBER OE	17-0519	10		\$44.80	\$44.80
3304		NYLON PR	CHEVY PU				
3364	GL19-405-	60-61 PARKING LAMP LEN		4	\$10	\$104.00	\$104.00
3304	60C	CLEAR W/GASKET GMC	CHEVY PU			\$104.00	
3364	GL19-505-	67-72 PARK LAMP HOUSING		10)	\$55.00	\$55.00
3304	S	SUPPORT W/HARDWARE GMC	CHEVY PU	10			
3364	GL20-510-	67-72 INNER FENDER TO CAB		_ 4	\$23.88	\$23.88	
3301	СВ	BOLT W/WASHER	CHEVY PU	<u> </u>		Ψ23.00	Ψ23.00
3364	GL23-202-	2- 47-55 FIRST SERIES GMC 100 EMBLEM W/HARDWARE		4		\$120.00	\$120.00
	G1		CHEVY PU			Ψ120.00	Ψ120.00
3364	3364 GL3-206	47-55 FILLER PANELS AT FIREWALL/FENDER W/SCREWS		4		\$32.00	\$32.00
			CHEVY PU			\$2 2. 00	
3364	GL3-320- HS-S	55-59 HOOD ADJUSTER BOLT	CHEVY PU	10		\$55.00	\$55.00
3364	GL30-2724	47-53 BED BLOCK W/PAD KIT	CHEVY PU	5		\$60.00	\$60.00
3364	GL31-	54-72 BED PAD SET 10 PCS	31-0201-P	10		\$50.00	\$50.00
3301	0201-P	RUBBER SET	CHEVY PU			\$20.00	Ψ50.00

PAGE:1

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
B0018	2018-01-30	DEL	ORGIN	2018-01-30

CONTAINER 3364 DETAILS

PO#	ITEM	DESCRIPTION	VPART NO.	SHID OTV	LOCATION	FOB	EXT COST
	IIEM		MAKE	Shir Q11			
2264	3364 GL33-316- CP	55-59 INNER CAB CORNER FLOOR PANEL EACH		10		¢00.00	¢00.00
3304			CHEVY PU	10		\$80.00	\$80.00
3364	GL36-	67-72 CLUTCH Z BAR BRACKET- BOLT ON BLOCK V8		1		\$28.95	\$28.95
3304	5126-V		CHEVY PU	1			
3364	GL39-315-	55-59 UPPER SHOCK FRAME BRACKET		4		Ф.СО. ОО	\$68.00
3304	FU		CHEVY PU	7 4		\$68.00	
2264	GL39-316-	55-59 FRONT SPRING U-BOLT 2"		10		\$80.00	\$80.00
3364	F	SPRING W/ NUTS	CHEVY PU	10			
2264	GL39-316-	55-59 REAR AXLE U-BOLT 7 1/2		10	10	\$80.00	\$80.00
3364	R	X 2 W/NUTS	CHEVY PU	7 10			
2264	GL40-310-	58-59 RADIATOR SUPPORT				\$64.00	\$64.00
3364	58K	MOUNT KIT	CHEVY PU	4			
2264	GL5-413-	60-66 GLOVE BOX DOOR HINGE SPRING		6		\$42.00	\$42.00
3364	GS		CHEVY PU				
2264	GL6-405-	60-66 WASHER NOZZLES PR		10		\$100.00	\$100.00
3364	W		CHEVY PU				
2264	GL6-505-	CZ ZO WA GUED MOZZI EG DD		10		Φ100 00	\$100.00
3364	W	67-72 WASHER NOZZLES PR	CHEVY PU			\$100.00	
2264	CT 0.550 A	67-72 SEAT ADJUSTER SPRING & LOCK 2 PCS		10		\$70.00	\$70.00
3364	GL8-570-A		CHEVY PU				
2264	GL8-570-	- 67-72 SEAT ADJUST LOCK BAR W/HARDWARE LH	8-570-LB-L	4		\$44.00	\$44.00
3364	LB-L		CHEVY PU				
2264	GL8-570-	- 67-72 SEAT ADJUST LOCK BAR		4		\$44.00	\$44.00
3364	LB-R	W/HARDWARE RH	CHEVY PU				
2264	GL9-201- 47T	47-49 GLOVE BOX LINER		3	2	¢20.00	#20.00
3364		RETAINER W/SCREWS	CHEVY PU			\$30.00	\$30.00
	•			•	TOTAL	\$1773.63	\$1773.63

PAGE:2