VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-26	1	ORGIN	2017-09-26

3312 106M 77-81 FRONT DISC BRAKE BRACKET PR CAMARO 4 D83 S83.72 S83.73 S83.73 S83.72 S83.73 S83.	PO#	ITEM	DESCRIPTION	VPART NO.	CHID OTV	LOCATION	FOB	EXT
3312 1049W 67-73 BUMPER BOLT BULK PACKSO PCS(3 /8" X 1") CAMARO 8 D91 \$164.00 \$164.00 \$312 1067QA 70-81 CROSS MEMBER TRANNY SUPPORTTURBO 400 TRAN. CAMARO 4 G143 \$110.68 \$110.	PO#	IIEMI	DESCRIPTION	MAKE		LUCATION	гов	COST
3312 1068G	3312 1006M		77-81 FRONT DISC BRAKE			D03	¢02.70	¢02.70
3312 1067QA 70-81 CROSS MEMBER TRANNY SUPPORTTURBO 400 TRAN. CAMARO	3312	1000101	BRACKET PR	CAMARO	4	роз	\$63.72	\$65.72
3312 1068Q TO-81 CROSS MEMBER TRANNY SUPPORTTURBO 400 TRAN. CAMARO	2212	1040337	67-73 BUMPER BOLT BULK		Q	D01	\$164.00	\$164.00
3312 1068G	3312	1049 W	PACK50 PCS(3 / 8" X 1")	CAMARO	o	D91	\$104.00	\$104.00
3312 1068Q	2212	106701	70-81 CROSS MEMBER TRANNY		」	C1/12	\$110.69	¢110.69
1068G	3312	1007QA	SUPPORTTURBO 400 TRAN.	CAMARO	4	G143	\$110.06	\$110.00
3312 1068H HOOD HINGE LH 67 / 9 CAMARO	2212	10680	HOOD HINGE RH 67 / 9			A 0.1	\$442.20	\$442.20
3312 1068H CAMARO,65 / 7 IMPA CAMARO 20 A91 \$442.20 \$442.20 \$442.21 \$442.20 \$442.21 \$442.22	3312	1000G	CAMARO,65 / 7 IMPA	CAMARO	20	A91	\$442.20	\$442.20
1068Q 67-73 HOOD SAFETY LATCH BLACK CAMARO 6 A133 \$71.28 \$71.29	3312	106811	HOOD HINGE LH 67 / 9			A 01	\$442.20	\$442.20
3312 1071 HOOD COWL VENT GRILLE70-73 CAMARO CAM	3312	100011	CAMARO,65 / 7 IMPA	CAMARO	20	A91	\$442.20	\$442.20
3312 1071 HOOD COWL VENT GRILLE70-73 CAMARO 4 E105 \$266.44 \$266.44 \$266.44 \$312 1096 47-54 GMC BUMPER FILLERGMC ONLY CHEVY PU 6 F135 \$284.52 \$284.53 \$312 1096E GRILLE UPPER BAR 57 CHEVY ONLY CHEVY PU 2 A65 \$52.66 \$52.66 \$52.66 \$52.66 \$312 1097G 68-72 REAR FENDER STEPSIDE RH CHEVY PU 6 N33 \$1,738.80 \$1,738.80 \$1,738.80 \$312 1097H 68-72 REAR FENDER STEPSIDE LH CHEVY PU 6 N32 \$1,750.02 \$1,750.03 \$1312 1099G INNER FENDER RH 67-72 CHEVY PU 8 J161 \$218.48 \$218.44 \$312 1099H INNER FENDER LH 67-72 CHEVY PU 4 J161 \$109.40 \$109.40 \$312 1103DJ 55-59 ROOF FRONT FILLER BRACE CHEVY PU 12 C74 \$281.76	2212	10690	67-73 HOOD SAFETY LATCH			A 122	¢71.20	¢71.00
3312 1096 47-54 GMC BUMPER FILLERGMC ONLY CHEVY PU 6 F135 \$284.52 \$284.52 \$284.52 \$3312 1096E GRILLE UPPER BAR 57 CHEVY ONLY CHEVY PU 2 A65 \$52.66 \$52.66 \$52.66 \$52.66 \$3312 1097G 68-72 REAR FENDER STEPSIDE RH CHEVY PU 6 N33 \$1,738.80 \$1,738.80 \$1,738.80 \$3312 1097H 68-72 REAR FENDER STEPSIDE LH CHEVY PU 6 N32 \$1,750.02 \$1,750.02 \$1,750.02 \$3312 1099G INNER FENDER RH 67-72 CHEVY PU 8 J161 \$218.48 \$218.49 \$3312 1099H INNER FENDER LH 67-72 CHEVY PU 4 J161 \$109.40 \$109.40 \$3312 1103DJ 55-59 ROOF FRONT FILLER BRACE CHEVY PU 12 C74 \$281.76 \$28	3312	1000Q	BLACK	CAMARO	O	A133	\$/1.20	\$/1.28
3312 1096 47-54 GMC BUMPER FILLERGMC ONLY CHEVY PU 6 F135 \$284.52 \$284.52 \$284.52 \$3312 1096E GRILLE UPPER BAR 57 CHEVY ONLY CHEVY PU 2 A65 \$52.66 \$52.66 \$52.66 \$52.66 \$3312 1097G 68-72 REAR FENDER STEPSIDE RH CHEVY PU 6 N33 \$1,738.80 \$1,738.80 \$1,738.80 \$3312 1097H 68-72 REAR FENDER STEPSIDE LH CHEVY PU 6 N32 \$1,750.02 \$1,750.02 \$1,750.02 \$3312 1099G INNER FENDER RH 67-72 CHEVY PU 8 J161 \$218.48 \$218.48 \$3312 1099H INNER FENDER LH 67-72 CHEVY PU 4 J161 \$109.40 \$109.40 \$3312 1103DJ 55-59 ROOF FRONT FILLER BRACE CHEVY PU 12 C74 \$281.76 \$28	3312	1071	HOOD COWL VENT GRILLE70-73	CAMARO	4	E105	\$266.44	\$266.44
3312 1096 ONLY CHEVY PU 6 F135 \$284.52 \$284.52 \$284.52 \$3312 1097G 68-72 REAR FENDER STEPSIDE RH CHEVY PU 6 N33 \$1,738.80 \$1,738.80 \$1,738.80 \$1,738.80 \$1,750.00 \$3312 1097H 68-72 REAR FENDER STEPSIDE LH CHEVY PU 6 N32 \$1,750.00				CAMARO			7-00111	+
3312 1096E GRILLE UPPER BAR 57 CHEVY ONLY CHEVY PU 2 A65 \$52.66 \$52.66 3312 1097G 68-72 REAR FENDER STEPSIDE RH CHEVY PU 6 N33 \$1,738.80 \$1,738.80 3312 1097H 68-72 REAR FENDER STEPSIDE LH CHEVY PU 6 N32 \$1,750.02 \$1,750.02 3312 1099G INNER FENDER RH 67-72 CHEVY PU 8 J161 \$218.48 \$218.49 3312 1099H INNER FENDER LH 67-72 CHEVY PU 4 J161 \$109.40 \$109.40 3312 1103DJ 55-59 ROOF FRONT FILLER BRACE CHEVY PU 12 C74 \$281.76 \$281.76 3313 3314 3315 CHEVY PU C74 \$281.76	3312	1096	I :	CHEVY DII	6	F135	\$284.52	\$284.52
3312 1097G 68-72 REAR FENDER STEPSIDE RH CHEVY PU 6 N33 \$1,738.80 \$1,738.80 \$1,738.80 \$1,738.80 \$1,738.80 \$1,738.80 \$1,750.02 \$1,750.0				CHEVYPU				
3312 1097G 68-72 REAR FENDER STEPSIDE RH CHEVY PU 6 N33 \$1,738.80 \$1,738.80 \$1,738.80 \$1,738.80 \$1,738.80 \$1,738.80 \$1,738.80 \$1,738.80 \$1,750.02 \$1,750.0	3312	1096E	I -	CHEVY DI	_ 2	A65	\$52.66	\$52.66
3312 1097G RH CHEVY PU 6 N33 \$1,738.80				CHEVYPU				
3312 1097H 68-72 REAR FENDER STEPSIDE CHEVY PU 6 N32 \$1,750.02	3312	1097G	I	CHEVY DI	6	N33	\$1,738.80	\$1,738.80
3312 1099G INNER FENDER RH 67-72 CHEVY PU 8 J161 \$218.48 \$218.44 \$3312 1099H INNER FENDER LH 67-72 CHEVY PU 4 J161 \$109.40 \$109.40 \$3312 1103DJ 55-59 ROOF FRONT FILLER BRACE CHEVY PU 12 C74 \$281.76 \$281.76 \$281.76 \$281.76				CHEVYPU				
3312 1099G INNER FENDER RH 67-72 CHEVY PU 8 J161 \$218.48 \$218.44 3312 1099H INNER FENDER LH 67-72 CHEVY PU 4 J161 \$109.40 \$109.40 3312 1103DJ 55-59 ROOF FRONT FILLER BRACE CHEVY PU 12 C74 \$281.76 \$281.76	3312	1097H	I	CHEVY DII	6	N32	\$1,750.02	\$1,750.02
3312 1099H INNER FENDER LH 67-72 CHEVY PU 4 J161 \$109.40 \$109.40 3312 1103DJ 55-59 ROOF FRONT FILLER BRACE CHEVY PU 12 C74 \$281.76 \$281.76			LII	CHEVYPU				
3312 1103DJ 55-59 ROOF FRONT FILLER BRACE CHEVY PU 12 C74 \$281.76 \$281.76	3312	1099G	INNER FENDER RH 67-72	CHEVY PU	8	J161	\$218.48	\$218.48
3312 1103DJ 55-59 ROOF FRONT FILLER BRACE CHEVY PU 12 C74 \$281.76 \$281.76	3312	1099Н	INNER FENDER LH 67-72	CHEVY DI	4	J161	\$109.40	\$109.40
3312 1103DJ BRACE CHEVY PU 12 C74 \$281.76 \$281.76				CHEVYPU				,
2212 1103M DOOD I ATCH I I 47 51 4 D22 600 44 600 4	3312	1103DJ	I ====================================	CHEAN DIT	12	C74	\$281.76	\$281.76
3312 1103M DOOR LATCH I H 47-51 4 R32 \$88.44 \$88.45			BRACE	CHEVY PU				
5512 110511 DOOK LATCH LIT 47-51 CHEVY PU 4 D32 \$600.44 \$600.44	3312	1103M	DOOR LATCH LH 47-51	CHEVY PU	4	B32	\$88.44	\$88.44

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-26	1	ORGIN	2017-09-26

PO#	ITEM	DESCRIPTION	VPART NO. MAKE	SHIP QTY	LOCATION	FOB	EXT COST
3312	1104LE	67-72 BED STEP FOR SHORTBED,PAINTEDRH	CHEVY PU	2	C125	\$105.00	\$105.00
3312	1104P	68-72 VENT WINDOW ASSY RHCLEAR GLASS-WILL FIT 67- SEE NOTE	CHEVY PU	2	B102	\$258.44	\$258.44
3312	1106W	67-72 WIPER TRANSMISSION ARMSPR	CHEVY PU	4	B102	\$163.44	\$163.44
3312	1107W	47-50 BED REAR CROSS BRACE9 BOARD FLOOR	CHEVY PU	2	F34	\$109.20	\$109.20
3312	1109JD	60-66 LOWER FENDER BRACE REAR RH	CHEVY PU	4	B92	\$71.72	\$71.72
3312	1109KD	60-66 LOWER FENDER BRACE REAR LH	CHEVY PU	_ 2	B92	\$35.82	\$35.82
3312	1109R	HOOD HINGE RH 47-55	CHEVY PU	4	A95	\$72.00	\$72.00
3312	1114E	CAB CORNER RH 67-72	CHEVY PU	14	C122 / C123	\$87.64	\$87.64
3312	1114F	CAB CORNER LH 67-72	CHEVY PU	- 8	C122 / C123	\$49.28	\$49.28
3312	1114I	47-53 DASH SPEAKER GRILLECHEVY W / ASH TRAY	CHEVY PU	4	A133	\$255.36	\$255.36
3312	1115I	HEADLAMP BEZEL 47-55 PAIR	CHEVY PU	8	A63	\$94.72	\$94.72
3312	1135	55-57 HOOD LATCH	CHEVY PU	14	A35	\$337.12	\$337.12
3312	1151C	47-72 ROUND MIRROR STAINLESS 5-5 / 8"SMOOTH	CHEVY PU	14	F164	\$117.60	\$117.60
3312	1153B	47-55 EXTERIOR MIRROR ARM BLACK RH	CHEVY PU	4	F174	\$40.32	\$40.32
3312	1402EWT	64-72 SEAT MOUNTING RAIL 4PCS SET* WTP *	CHEVELLE	- 6	A104	\$103.68	\$103.68

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-26	1	ORGIN	2017-09-26

PO#	ITEM	DESCRIPTION	VPART NO.	CHID OTV	LOCATION	FOB	EXT
ro#	IIEMI	DESCRIPTION	MAKE	Shir Q11	LOCATION	гов	COST
3312	1485J	66-67 WINDOW ASSEMBLY VENT RHCHEVELLE / GTO CLEAR	CHEVELLE	4	B125	\$747.92	\$747.92
3312	1485K	66-67 WINDOW ASSEMBLY VENT LHCHEVELLE / GTO CLEAR	CHEVELLE	2	B104	\$377.90	\$377.90
3312	1488E	RADIATOR SUPPORT 70	CHEVELLE	4	F148	\$299.76	\$299.76
3312	1490DWT	WINDSHIELD CHANNEL 64- 67*** WTP *	CHEVELLE	4	F132	\$83.96	\$83.96
3312	1496	SHIFTER 68-72 (W / 0 ROD)	CHEVELLE	2	A65	\$76.68	\$76.68
3312	1615D	FRONT BUMPER FILLER 68-72 PLASTIC	NOVA	10	E95	\$176.70	\$176.70
3312	1636B	64-67 FLOOR TRANSMISSION COVERMANUAL	NOVA	4	F177	\$60.52	\$60.52
3312	1643C	68-72 HOOD LATCH ASSY	NOVA	4	A104	\$139.28	\$139.28
3312	1644WT	66-67 COWL VENT GRILLE* WTP	NOVA	_ 2	F137	\$212.44	\$212.44
3312	1705L	62 REAR BUMPER	IMPALA	4	F113	\$773.84	\$773.84
3312	1705M	65 FRONT BUMPER	IMPALA	2	F93	\$380.56	\$380.56
3312	1710G	63 PARKING LAMP LENS AMBER PR	IMPALA	4	A12	\$47.64	\$47.64
3312	1737RWT	65-66 TRUNK FLOOR DROP OFF RH*WTP*	IMPALA	4	E112	\$105.40	\$105.40
3312	3631MWT	OUTER WHEEL HOUSE RH 65- 66* WELD THROUGH PRIMER *	MUSTANG	10	G168	\$220.90	\$220.90
3312	3631NWT	OUTER WHEEL HOUSE LH 65- 66* WELD THROUGH PRIMER *	MUSTANG	6	G168	\$120.00	\$120.00

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-26	1	ORGIN	2017-09-26

PO#	TTPEN 4	DESCRIPTION	VPART NO.	SHIP QTY	LOCATION	FOB	EXT
ro#	ITEM	DESCRIPTION	DESCRIPTION MAKE		LUCATION	гов	COST
2212	2(20D	64-66 REAR BUMPER GUARD		4	CO2	¢24.40	¢24.40
3312	3639B	BRACKET PR	MUSTANG	4	G92	\$34.40	\$34.40
3312	2642NG	70 TAIL LAMP HOUSING TO		4	A37	\$57.52	\$57.52
3312	3643NC	BODY SEALRH=LH	MUSTANG	4	A3/	\$37.32	\$37.32
3312	3643WA	69 TAIL LAMP LENSALL BODY		8	A45	\$206.48	\$206.48
3312	3043 WA	STYLE	MUSTANG	0	A45	\$200.46	\$200.46
3312	3647LDWT	67-70 ROCKER PANEL OUTER		8	E91	\$543.68	\$543.68
3312	304/LDW1	RH*WTP*	MUSTANG	•	E91	\$343.00	φ343.06
3312	3647MDWT	67-70 ROCKER PANEL OUTER		10	E91	\$679.60	\$679.60
3312	3047NID W 1	LH* WTP *	MUSTANG	10	E91	\$079.00	\$079.00
3312	3649E	TRUNK FLOOR RH 65-70	MUSTANG	10	G116	\$110.00	\$110.00
3312	3649F	TRUNK FLOOR LH 65-70	MUSTANG	10	G116	\$110.00	\$110.00
3312	3649PWT	65-68 SEAT SUPPORT		4	G95	\$99.16	\$99.16
3312	30471 11 1	PLATFORMRH *WTP *	MUSTANG		G73	φ99.10	φ99.10
3312	3649QWT	65-68 SEAT SUPPORT		4	G95	\$98.36	\$98.36
3312	3047Q111	PLATFORMLH *WTP *	MUSTANG		973	Ψ/0.50	Ψ70.30
3312	3652WT	65-66 TORQUE BOX RH CONVT		4	A97	\$149.56	\$149.56
3312	3032 11 1	*WTP*67-68 AS WELL	MUSTANG		A)	\$147.50	Ψ147.50
3312	3661	67-68 TRAP DOOR BEHIND REAR			G143	\$187.96	\$187.96
3312	3001	SEAT FB	MUSTANG		0143	\$107.90	\$107.90
3312	EM4755	71-72 "SS" REAR BUMPER		4		\$96.12	\$96.12
3312	EN14733	EMBLEM	CHEVELLE			\$70.12	\$70.12
3312	G1130	67-72 DOOR GLASS RH=LH		4	N131 / G2	\$75.36	\$75.36
3312	G1130	CLEAR	CHEVY PU	4	1131 / G2	\$15.50	\$15.50
3312	LH10	47-54 HEADLAMP BUCKET RH /		20	C84	\$406.80	\$406.80
3312	LHIU	LH	CHEVY PU	20	C04	\$ 4 00.80	φ 4 00.80
3312	LP53	60-72 DOME LAMP ASSY WHITE		6	A15	\$47.88	\$47.88
3312	LF55	BASE	CHEVY PU	U	A15	\$47.88	\$47.88

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-26	1	ORGIN	2017-09-26

PO#	ITEM	DESCRIPTION	VPART NO.	CHID OTY	LOCATION	FOB	EXT
PO#	HEM	DESCRIPTION	MAKE		LOCATION	FUB	COST
3312	M3506A	67-70 FOLD DOWN SEAT ASSY		2	A131	\$885.02	\$885.02
3312	WISSUUA	FB	MUSTANG	2	AISI	\$665.02	\$665.02
		FOLD DOWN SEAT MOULDING					
3312	M3507	65-68 F / B14PCS SET*W / O	MUCTANG	− 4	A34	\$418.12	\$418.12
		RECESSED STRIKE AREA*	MUSTANG				
3312	M3509A	67-70 FOLDDOWN LATCH FB RH) HIGH LIIG	- 4	B23	\$77.24	\$77.24
3312	1,100,0311	or rorozada viri zarreni a idi	MUSTANG	<u> </u>	D-20	Ψ, γ, 2, 1	Ψ, γ, 2.
3312	M3509B	67-70 FOLDDOWN LATCH FB LH	MUSTANG	4	B23	\$76.84	\$76.84
			MUSTANO	+		•	
3312	M3547	HOOD LATCH SUPPORT 65-66	MUSTANG	4	A94	\$19.52	\$19.52
			MUSTANO	+			
3312	SW29	47-66 HORN CONTACT PIN /		4	C42	\$6.60	\$6.60
3312	51129	SWITCH	CHEVY PU	•		Ψ0.00	Ψ0.00
	TOTAL						\$16215.66