VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-26	1	ORGIN	2017-09-26

CONTAINER 3318 DETAILS

PO# ITEM	TOTAL	DESCRIPTION	VPART NO.	CHID OTY	LOCATION	FOB	EXT COST
	HEN	DESCRIPTION	MAKE	SHIP QTY			
3318	1099K	FENDER LH 60-66	CHEVY PU	1	N14	\$99.95	\$99.95
3318	1099KB	60-66 CAB CORNER MUD		1	B102	\$8.89	\$8.89
3310	1077111	GUARD LH	CHEVY PU				
3318	1099KD	60-66 REAR FENDER LOWER		_ 1	C74	\$17.93	\$17.93
3310	1077112	BRACE LH	CHEVY PU	•			
3318	1099L	HOOD 69-72 STANDARD	CHEVY PU	2	E31	\$421.28	\$421.28
3318	1099MC	73-80 HOOD	CHELIN DI	1	D51	\$87.69	\$87.69
	10771120		CHEVY PU	-		ψο/.ο>	Ψ07.05
3318	1099N	HOOD CENTER MOLDING 47-54 CHEVROLET		2	B114	\$54.12	\$54.12
			CHEVY PU				
3318	1099P	HOOD 67-68 STANDARD	CHEVY PU	1	E41	\$276.36	\$276.36
3318	1099TA	47-52 HOOD 1PC W / EMBLEM		1	E71	\$238.20	\$238.20
3316	10991A	HOLES	CHEVY PU				
3318	1099V	62-66 HOODWILL FIT 60-61 AS		2		#0.00	\$0.00
3318	1099 V	WELL	CHEVY PU			\$0.00	\$0.00
2210	100011	60-66 HOOD LAMP PANEL (FACE		1	F64	\$95.54	\$95.54
3318	3318 1099W	PANEL)	CHEVY PU				
3318	1099YA	67-68 GMC RADIATOR SUPPORT	CHEVY PU	1	F72	\$132.01	\$132.01
3318	3318 1099Z	RADIATOR SUPPORT 69-72		1	F135	\$117.64	\$117.64
3310	10))2		CHEVY PU		1133	ψ117.04	ψ117.04
3318	3318 1099ZA	69-72 GMC RADICATOR		1	F135	\$136.79	\$136.79
	10000	SUPPORT	CHEVY PU			Ψ100.77	4100.77
3318	10B53140	67-69 CARPET BLACK 80 / 20		_ 1	F186	\$99.12	\$99.12
3310	10000170	LOOP 1PC	CAMARO		1100	Ψ>>.12	Ψ22.12
3318	10B53140-2	67-69 CARPET BLACK 80 / 20		1	F186	\$101.41	\$101.41
3310	10033140-2	LOOP 2PC	CAMARO				

PAGE:3