VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-09-26	1	ORGIN	2017-09-26

## **CONTAINER 3318 DETAILS**

PO# ITEM	ITEM	DESCRIPTION	VPART NO.	CHID OTV	LOCATION	FOB	EXT COST
	TIENI	DESCRIPTION	MAKE				
3318 <b>1104I</b> C	1104IC	55-59 BEDSTEP RH LONGBED		1	C125	\$0.00	\$0.00
3318	3318 11041C	CHROME	CHEVY PU	1			
3318	1104JC	55-59 BEDSTEP LH LONGBED		1	C125	\$0.00	\$0.00
3316	110430	CHROME	CHEVY PU				
3318	1104X	47-54 RUNNING BOARD LH	CHEVY PU	1	F107	\$97.73	\$97.73
2210	1104VC	47-54 RUNNING BOARD		1	E126	¢127.00	¢127.00
3318	3318 <b>1104XC</b>	CHROME LH	CHEVY PU	1	F126	\$137.08	\$137.08
3318	3318 <b>1105</b>	68-72 SHIFT LEVER W / TILT	CHEVY DI	1	A14	\$0.00	\$0.00
			CHEVY PU			,	
3318	1105Z	55-59 COWL OUTER PANEL LH	CHEVY PU	3	E116	\$71.01	\$71.01
2210	110644	67-72 TRUNK BED PANEL BOLT		1	D111	¢4.75	¢4.75
3318	3318 <b>1106AA</b>	KIT	CHEVY PU	1	D111	\$4.75	\$4.75
3318	3318 <b>1106AB</b>	47-54 CAB FLOOR PAN RH	CHEVA DI	2	D105	\$65.66	\$65.66
		.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	CHEVY PU			7	+
3318	1106AC	47-54 CAB FLOOR PAN LH	CHEVY PU	2	D105	\$65.62	\$65.62
2210	3318 <b>1106AD</b>	47-55 CAB FLOOR FRONT			D104	<b>#24.70</b>	¢24.70
3318		SUPPORT RH	CHEVY PU	2	D104	\$24.70	\$24.70
3318 <b>1106AE</b>	47-55 CAB FLOOR FRONT		1	D104	¢12.50	\$12.58	
	HUOAE	SUPPORT LH	CHEVY PU	1	D104	\$12.58	\$12.38
3318	3318 <b>1106AG</b>	47-55 CAB FLOOR REAR		1	D103	\$12.87	\$12.87
3318 1100AG	SUPPORT LH CHEVY PU		1	D103	\$12.07	\$12.07	
3318 <b>1106AK</b>	60-66 FRONT CAB FLOOR		2	B75	\$20.16	\$20.16	
	HUUAK	SUPPORTRH=LH * 1.60 MM *	CHEVY PU		Віз	φ20.10	φ20.10
3318	1106AL	67-72 FRONT CAB FLOOR		4	B75	\$23.52	\$23.52
	HUUAL	SUPPORT MOUNTRH=LH	CHEVY PU	ļ <sup>-</sup>	<b>D</b> /3	ΨΔ3.3Δ	ΨΔ3.32
3318 <b>1106</b> A		60-72 CAB FLOOR REAR					
	1106AM	SUPPORT RH**PATCH PANEL**	CHEVY PU	1	C33	\$3.79	\$3.79
		OVERLAYS SUPPORT**	DACE:10				

PAGE:10