VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-10-11	CEVA	ORGIN	2017-10-12

PO#	ITEM	DESCRIPTION	VPART NO.	CHID OTY	LOCATION	FOB	EXT
PO#	HEN	DESCRIPTION	MAKE	SHIPQIY	LOCATION	гов	COST
3309	1000B	67-69 CONVT. TOP BOLT &		_ 1	C52	\$16.35	\$16.37
		PIVOT KIT68-72 CHEVELLE	CAMARO				
2200	10000	67-69ANTENNA MAST*FIXED			D54	ф <b>д</b> .г.с	Φ <b>7. 6</b> 2
3309	1000C	WHIP STYLE** REPLACEMENT - MAST ONLY*	CAMARO	1	B74	\$7.56	\$7.63
3314	1006M	77-81 FRONT DISC BRAKE			D83	\$41.86	\$41.86
3314	1000101	BRACKET PR	CAMARO		D63	φ41.60	φ41.60
3309	1039W	FRONT INNER FENDER RH 67-68	CAMARO	8	J171	\$372.80	\$471.12
2211	1041110	75-81 OUTER WHEELHOUSE		1	C155	<b>\$50.03</b>	¢55.40
3311	1041HC	LHFIREBIRD / TRANS AM	FIREBIRD	1	G157	\$50.83	\$55.48
3288	1041J	WHEELHOUSE OUTER LH 70-81	CAMARO	1	G147	\$27.72	\$34.21
3311	1041JC	75-81 OUTER WHEELHOUSE		1	G157	\$50.79	\$55.47
3311	104130	RHFIREBIRD / TRANS AM	FIREBIRD	1	G157	\$30.79	\$33.47
2211	10.4177	67-76 HEATER BLOWER			4142	0.66.54	0.67.1.4
3311	1041W	MOTORW / O AC NOVA 64-74, CHEVELLE 64-72	CAMARO	3	A143	\$66.54	\$67.14
2216	40450	ED ONE A DROM CO DG	3938601		Gaa	Φ.5.1.00	ф.c2.20
3316	1047B	FRONT APRON 68 RS	CAMARO	2	C23	\$51.90	\$62.20
2211	10.451	RADIATOR SUPPORT 67-		10	C14	Ø512.10	Φ5.65.10
3311	1047L	69CAMARO AND FIREBIRD	CAMARO	10	C14	\$512.10	\$565.10
3316	1048N	FRONT BUMPER OUTER			G132	\$12.70	\$12.28
3310	104011	BRACKET LH 67	CAMARO		0132	Ψ12.70	Ψ12.20
3302	1048QB	69 FRONT BUMPER BRACKET			A55	\$135.00	\$151.26
	10.0Q2	4PCS SET	FIREBIRD		1100	Ψ123.00	Ψ131.20
3309	1048X	TRUNK FLOOR DROP OFF RH 69	CAMARO	5	G153	\$68.10	\$77.05
3309	1048Y	TRUNK FLOOR DROP OFF LH 69	CAMARO	5	G153	\$69.00	\$76.20
2206	10.40P	DEAD DUMMED (7.69	3886603	4	E05	<b>#2</b> 66.00	<b>#272</b> 00
3306	3306 <b>1049B</b>	REAR BUMPER 67-68	CAMARO	<b>4 F95</b> \$266	\$266.08	\$272.88	

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-10-11	CEVA	ORGIN	2017-10-12

PO#	ITEM	DESCRIPTION	VPART NO.	SHID OTV	LOCATION	FOB	EXT
ro#	TIENI	DESCRIPTION	MAKE	Silir Q11	LUCATION	гов	COST
3316	1049C	REAR BUMPER 69	3927424	3	F111	\$199.53	\$204.33
3310	10490	REAR BUNIFER 09	CAMARO	3	FIII	\$199.55	\$204.33
3297	1049J	REAR CHROME BUMPER 70-73	CAMARO	3	F92	\$270.03	\$275.85
3316	1049LG	67-69 TRUNK WEATHERSTRIP			C13	\$35.14	\$35.60
3310	1047LG	CHANNEL PR	CAMARO		CIS	φ33.14	\$33.00
3314	1049W	67-73 BUMPER BOLT BULK		4	D91	\$88.52	\$88.52
3314	1049 11	PACK50 PCS(3 / 8" X 1")	CAMARO	4	D91	\$00.32	\$00.32
3309	1064B	GRILLE 67 STANDARD	3891693		C65	\$46.94	\$41.18
3309	1004D	GRILLE 07 STANDARD	CAMARO	2	C05	\$40.94	<b>\$41.10</b>
3309	1064E	GRILLE 67 / 8 RS W / CHROME			C65	\$76.14	\$68.56
3309	1004E	NO HEADLAMPCOVER	CAMARO	2	Cos	\$70.14	\$06.50
3311	1066KA	75-81 QUARTER PANEL		1	K63	\$209.39	\$216.61
3311	1000KA	RHFIREBIRD / TRANS AM	FIREBIRD	1	Kus	\$209.39	\$210.01
3297	1066KB	75-81 QUARTER PANEL			K63	\$460.32	\$506.48
3291	1000KD	LHFIREBIRD / TRANS AM	FIREBIRD	2	Kus	\$400.32	Ψ500.40
3316	1067G	ROCKER PANEL RH 67-69 H / T	7741310		E111	\$176.15	\$188.25
3310	100/G	ROCKER FAINEL KH 07-09 H / 1	CAMARO	3	EIII	\$170.13	\$100.23
3311	1067Q	69 REAR CROSS RAIL	CAMARO	5	F126	\$115.00	\$126.35
3310	1067QB	1970-73 SHIFTER POD 4 SPEED	CANTARO	_ 2		\$33.00	\$33.00
	1007 Q2		CAMARO			Ψ22.00	455.00
3316	1067R	67-69 ROCKER PANEL INNER	G.13.6.17.0	5	E95	\$183.50	\$208.80
		RH** COUPE **	CAMARO				
3316	1067S	67-69 ROCKER PANEL INNER	G115170	5	E94	\$182.60	\$207.10
		LH** COUPE **	CAMARO				
3311	1067Y	INNER TAIL LAMP PANEL67-68	CAMARO	5	C32	\$138.70	\$146.10
3316	1068EE	69 DASH UPPER PANEL(STEEL)		1	C22	\$28.17	\$29.65
3310	TOOLE	CUSTOM	CAMARO	•		Ψ20.17	Ψ27.03

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-10-11	CEVA	ORGIN	2017-10-12

PO#	ITEM	DESCRIPTION	VPART NO. MAKE	SHIP QTY	LOCATION	FOB	EXT COST
	10.10.01	HOOD HINGE RH 67 / 9	1068G	1.0			
3314	1068G	CAMARO,65 / 7 IMPA	CAMARO	10	A91	\$220.50	\$220.50
2214	1068H	HOOD HINGE LH 67 / 9	1068H	10	4.01	¢221 10	¢221 10
3314	1009H	CAMARO,65 / 7 IMPA	CAMARO	10	A91	\$221.10	\$221.10
3311	1068RXWT	68-69 FLOOR PAN FRAME RAIL RH6" WIDER WHEELHOUSE		2	E101	\$181.60	\$190.46
		*WTP *	CAMARO				
3316	1069CWT	67-69 COWL TOP VENT GRILLE			A117	\$184.02	\$192.99
3310	1009€ W 1	PANEL* WTP *	CAMARO	3	AIII	\$104.02	\$192.99
3296	1069J	69 TRANS AM HOODFIT ON 67-68	FIREBIRD	2	D21	\$533.52	\$560.40
3314	1071	HOOD COWL VENT GRILLE70-73	CAMARO	2	E105	\$133.40	\$133.40
3309	1072C	67-68 WIPER MOTOR TRANSMISSION ARM	CAMARO	2	F157	\$91.96	\$92.32
3316	1073L	67-69 OUTER COWL SIDE LH	CAMARO	4	A86	\$145.56	\$153.56
3316	1073R	67-69 OUTER COWL SIDE RH	CAMARO	4	A86	\$145.68	\$153.68
3316	1076L	67-69 QUARTER VENT WINDOW		1	B103	\$91.68	\$91.69
		RH CPE	CAMARO				
3305	1077A	OUTER DOOR HANDLE RH 73-81 *CHROME*	CAMARO	10	A32	\$22.10	\$22.10
		47-54 GMC BUMPER FILLERGMC	C/ HVI/ HCO				
3314	1096	ONLY	CHEVY PU	3	F135	\$142.23	\$142.23
	100 =	GRILLE UPPER BAR 57 CHEVY	<del>-</del>				
3314	1096E	ONLY	CHEVY PU	1	A65	\$26.32	\$26.32
3311	1097D	REAR STEPSIDE FENDER LH 55-		2	N13	\$363.84	\$402.88
3311	עויפטו	66CHEVY / GMC	CHEVY PU	<u> </u>	N13	\$303.84	\$402.88
3311	1097E	47-55 REAR FENDER STEPSIDE			N123	\$552.84	\$615.06
3311	107/15	RH	CHEVY PU		11123	ψυυΔ.04	φ015.00

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-10-11	CEVA	ORGIN	2017-10-12

PO#	TOTAL	DESCRIPTION	VPART NO.	CHID OTY	LOCATION	FOB	EXT
ro#	ITEM	DESCRIPTION	MAKE		LOCATION	гов	COST
3314	1097G	68-72 REAR FENDER STEPSIDE		3	N33	\$869.40	\$869.40
3314	109/G	RH	CHEVY PU	3	NSS	\$609.40	\$809.40
3314	1097H	68-72 REAR FENDER STEPSIDE			N32	\$875.01	\$875.01
3314	109/11	LH	CHEVY PU	3	1432	\$675.01	φ673.01
3314	1099G	INNER FENDER RH 67-72	CHEVY PU	4	J161	\$109.24	\$109.24
3314	1099Н	INNER FENDER LH 67-72	CHEVY PU	2	J161	\$54.70	\$54.70
3282	1099V	62-66 HOODWILL FIT 60-61 AS		2		\$1,008.00	¢1 009 00
3282	1099 V	WELL	CHEVY PU			\$1,008.00	\$1,008.00
3282	1099W	60-66 HOOD LAMP PANEL (FACE	TP	1	F64	\$95.54	¢100.00
3282	1099 W	PANEL)	CHEVY PU	1	F 04	\$95.54	\$100.08
3309	1100E	BATTERY HOLD DOWN 55-57	CHEVY PU	2	F151	\$8.86	\$9.08
3311	1101Y	DOOR SKIN, PARTIAL LOWER		1	D102	\$9.30	\$9.30
3311	1101 1	RH 67-729"	CHEVY PU	1	D102	\$9.50	\$9.50
3316	1102	DOOR SHELL RH 67-7172 HAS		3	N31	\$463.20	\$495.63
3310	1102	HOLE FOR VENT WINDOW	CHEVY PU	¬ ,	N31	\$403.20	\$493.03
3316	1102BE	47-54 FRONT LOWER DOOR		3	C42	\$44.79	\$45.06
3310	1102BE	PILLAR RH	CHEVY PU	3	C42	\$44.79	\$45.00
3316	1102BF	47-54 FRONT LOWER DOOR		1	C42	\$15.65	\$15.74
3310	1102DF	PILLAR LH	CHEVY PU	1	C42	\$15.05	\$13.74
3316	1102BS	67-72 FRONT LOWER DOOR		2	C74	\$10.38	\$11.80
3310	110203	PILLAR RH	CHEVY PU		C/4	\$10.56	\$11.60
3316	1102BT	67-72 FRONT LOWER DOOR		2	C74	\$10.36	\$11.02
3310	110201	PILLAR LH	CHEVY PU		C/ <b>-1</b>	\$10.30	φ11.02
3309	1102H	47-55 DOOR ARM REST BLACK		4	B92	\$77.28	\$77.76
3307	110211	RH=LH1 ST SERIES	CHEVY PU	<b>_</b>	10/2	ψ11.20	ψ11.10
3309	1102K	64-67 DOOR ARM REST BLACK			B92	\$21.84	\$22.04
3307	11021	RH=LH	CHEVY PU		10/2	Ψ21.04	Ψ22.04

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-10-11	CEVA	ORGIN	2017-10-12

PO#	ITEM	DESCRIPTION	VPART NO.	CHID OTV	LOCATION	FOB	EXT
PO#	HEN	DESCRIPTION	MAKE	SHIPQIY	LUCATION	гов	COST
3316	1103	DOOR SHELL LH 67-7172 HAS		3	031	\$467.46	¢501.60
3310	1103	HOLE FOR VENT WINDOW	CHEVY PU	3	031	\$467.46	\$501.60
3311	1103D	DOOR SHELL LH 55-59	CHEVY PU	4	N11	\$780.00	\$1,014.96
2214	1102D I	55-59 ROOF FRONT FILLER			074	Ф120 44	ф120 44
3314	1103DJ	BRACE	CHEVY PU	6	C74	\$139.44	\$139.44
3306	1103DK	55-59 EXTERIOR WINDSHIELD		1	E102	\$84.00	\$86.72
3300	HUSDK	SUNVISOR	CHEVY PU	1	12102	\$64.00	\$60.72
3303	1103DL	47-53 WINDSHIELD SUNVISOR		1	B92	\$8.82	\$8.92
3303	1103DL	BRACKETRH	CHEVY PU		10/2	ψ6.62	ψ0.72
3306	1103DN	54-55 WINDSHIELD SUNVISOR		1	B92	\$8.82	\$8.92
	1103211	BRACKETRH 1ST SERIES	CHEVY PU		D)2	ψ0.02	Ψ0.72
3314	1103M	DOOR LATCH LH 47-51	CHEVY PU	2	В32	\$44.22	\$44.22
3306	1103WD	51-54 VENT WINDOW ASSY W /		1	B94	\$123.08	\$124.29
3300	1103WD	GLASS RHPAINTED	CHEVY PU	1	D94	\$123.08	\$124.29
3306	1103WE	51-54 VENT WINDOW ASSY W /		1	B94	\$123.56	\$124.77
3300	11034412	GLASS LHPAINTED	CHEVY PU	1	D74	\$123.30	Φ124.77
3287	1103XL	64-66 VENT WINDOW RH		1	B121	\$178.50	\$180.01
3207	1103211	CHROME	CHEVY PU		D121	Ψ170.50	Ψ100.01
3306	1103Y	DOOR LATCH RH 52-54	CHEVY PU	1	В32	\$14.74	\$14.80
3306	1103Z	DOOR LATCH LH 52-54	CHEVY PU	3	B32	\$43.02	\$44.40
3309	1104A	ROCKER PANEL RH 60-66	CHEVY PU	2	C124	\$38.72	\$36.26
			CHEVIPU			·	· ·
3309	1104B	ROCKER PANEL LH 60-66	CHEVY PU	4	C124	\$75.04	\$70.44
3306	1104DA	73-87 ROCKER PANEL RH OE	TP		E101	\$25.26	\$28.26
3300	IIVIDA	STYLE	CHEVY PU		17101	Ψ2.20	Ψ20.20

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-10-11	CEVA	ORGIN	2017-10-12

PO#	ITEM	DESCRIPTION	VPART NO.	CHID OTV	LOCATION	FOB	EXT
ro#	11EW	DESCRIPTION	MAKE	SHIP QI I	LUCATION	ГUБ	COST
3306	1104DB	73-87 ROCKER PANEL LH OE	TP	1	E101	\$11.52	\$14.13
3300	1104DB	STYLE	CHEVY PU	1	EIUI	\$11.32	\$14.13
3314	1104LE	67-72 BED STEP FOR		1	C125	\$52.50	\$52.50
3314	1104LE	SHORTBED,PAINTEDRH	CHEVY PU	1	C123	\$32.30	φ32.30
3306	1105Z	55-59 COWL OUTER PANEL LH	CHEVY PU	3	E116	\$71.01	\$75.60
2216	110CDD	47-55 LOWER OUTER COWL		1		# <b>2</b> 0.40	ф <b>20.71</b>
3316	1106DB	PATCH RH	CHEVY PU	1		\$29.40	\$29.71
3316	1106DC	47-55 LOWER OUTER COWL		2		\$75.CO	\$76.22
3310	1100DC	PATCH LH	CHEVY PU	2		\$75.60	\$70.22
3316	1106DD	47-55 LOWER INNER TO OUTER		4		\$120.96	\$121.96
3310	110000	COWL PATCH RH	CHEVY PU	4		\$120.90	\$121.90
3316	1106DE	47-55 LOWER INNER TO OUTER		4		\$120.96	\$121.96
3310	1100DE	COWL PATCH LH	CHVEY PU	4		\$120.90	\$121.90
3302	1106DWT	47-54 COWL OUTER LOWER		1	E102	\$21.61	\$23.21
3302	11000 111	PANEL RH* NON WTP *	CHEVY PU	<u> </u>	12102	\$21.01	Ψ23.21
3309	1106EWT	47-53 DASH PANEL* WTP *	CHEVY PU	<b>-</b>   1	E115	\$170.50	\$152.21
		47-55 TRANS SHIFT COVEWR 4	TP				
3309	1106GA	SPEED	CHEVY PU	1	G74	\$32.63	\$34.61
		67-72 WIPER TRANSMISSION	CHEVITO				
3314	1106W	ARMSPR	CHEVY PU	2	B102	\$81.72	\$81.72
		68-72 CAB FLOOR PANEL					
3309	1107E	COMPLETEW / BRACE-	CHEVY PU	2	J111	\$543.84	\$567.66
		68-72 CAB FLOOR PANEL					
3309	1107H	COMPLETE 8FTWO / BRACE,FIT		_ 2	N61	\$415.28	\$462.96
		PANEL TRUCK,SUBURBAN	CHEVY PU				
3288	1107S	47-54 WOODEN FLOOR BED		2	D92	\$176.40	\$177.84
3200	110/5	STRIPSSTAINLESS 8PCS	CHEVY PU		D92	\$170.40	\$177.84
3314	1109JD	60-66 LOWER FENDER BRACE		2	B92	\$42.68	\$42.68
3314	110511	REAR RH	CHEVY PU	4	D94	φ <del>4</del> 2.08	Φ42.08

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-10-11	CEVA	ORGIN	2017-10-12

ITEM	DESCRIPTION	VPART NO.	SHIP QTY	LOCATION	FOB	EXT COST
	CO CC LOWER FENDER RRACE	WIAKE				
1109KD	REAR LH	CHEVY PU	1	B92	\$18.15	\$18.15
1109R	HOOD HINGE RH 47-55	CHEVY PU	2	A95	\$37.32	\$37.32
1109T	HOOD HINGE RH 55-57 W/SPRING	CHEVY PU	1	A106	\$27.03	\$27.37
1109V	58-59 HOOD HINGE W/SPRING RH	CHEVY PU	1	A106	\$30.12	\$30.48
4440		3911705			0 - 7 - 7 - 7	<b></b>
1110	HOOD HINGE LH 67-72	CHEVY PU	7 3	A95	\$65.52	\$68.94
1111	HOOD HINGE BUILT TO	3911706	2	4.05	04416	ф.4.7. O.2
1111	HOOD HINGE RH 67-72	CHEVY PU	7 2	A95	\$44.16	\$45.92
444487	FRONT BUMPER BRACKET RH		2	D02	#10.0 <b>2</b>	¢20.24
111114	60-66	CHEVY PU	7 2	B92	\$19.92	\$20.24
111177	FRONT BUMPER BRACKET LH		2	D02	<b>#10.70</b>	Φ <b>2</b> 0.04
1111Z	60-66	CHEVY PU	7 2	B92	\$19.70	\$20.04
11101 11/10	47-54 ROOF PANEL BRACE		2	D02	<b>0.40.7</b> 6	Φ <b>57</b> 00
1112LW1	FRONT* BLACK EDP *	CHEVY PU	7 2	D83	\$49.76	\$55.88
1112P	55-59 ROOF PANEL	CHEVY PII	1	F82	\$147.36	\$152.06
1113B	BED STEP LH 73-87 STEPSIDE		<b>-</b>   4	C122	\$91.56	\$79.20
	BED STEP HANGER RH 73-87					
1113C	STEPSIDE		5	B92	\$47.95	\$48.25
				C122 /		
1114E	CAB CORNER RH 67-72	CHEVY PU	1	C123	\$6.27	\$6.27
				C122 /		
1114F	CAB CORNER LH 67-72	CHEVY PU	7 10	C123	\$61.60	\$62.70
44445	GAR GORNER LIL G	,		C122 /	004 51	<b>#20</b> * *
1114F	CAB CORNER LH 67-72	CHEVY PU	4	C123	\$24.64	\$30.44
	1109KD  1109R  1109T  1109V  1110  1111  1111Y  1111Z  1111Z	1109KD         60-66 LOWER FENDER BRACE REAR LH           1109R         HOOD HINGE RH 47-55           1109T         HOOD HINGE RH 55-57 W/SPRING           1109V         58-59 HOOD HINGE W/SPRING RH           1110         HOOD HINGE LH 67-72           1111         HOOD HINGE RH 67-72           1111Y         FRONT BUMPER BRACKET RH 60-66           1111Z         FRONT BUMPER BRACKET LH 60-66           1112LWT         47-54 ROOF PANEL BRACE FRONT* BLACK EDP *           1112P         55-59 ROOF PANEL           1113B         BED STEP LH 73-87 STEPSIDE           1113C         BED STEP HANGER RH 73-87 STEPSIDE           1114E         CAB CORNER RH 67-72           1114F         CAB CORNER LH 67-72	1109KD	TTEM	TTEM	TTEM

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-10-11	CEVA	ORGIN	2017-10-12

PO#	ITEM	DESCRIPTION	VPART NO. MAKE	SHIP QTY	LOCATION	FOB	EXT COST
3311	1114K	55-59 CAB FLOOR TRANSMISSION COVER3SP / AUTO)	CHEVY PU	3	C122	\$73.50	\$78.24
3316	1114Y	67-72 FOOT WALL PANEL RH	CHEVY PU	2	D93	\$15.92	\$16.26
3316	1114Z	67-72 FOOT WELL PANEL LH	CHEVY PU	2	D93	\$15.92	\$16.26
3308	1115C	WINDOW REGULATOR RH 55-59	CHEVY PU	3	A114	\$77.58	\$85.56
3308	1115D	WINDOW REGULATOR LH 55-59	CHEVY PU	1	A114	\$27.93	\$28.77
3308	1115E	HEAD LAMP BEZEL 58-59 PAIR	CHEVY PU	1	C43	\$27.90	\$28.19
3308	1119J	55-59 BEDSIDE PANEL RH SHORTBED	CHEVY PU	1	S51	\$178.84	\$200.95
3309	1123	HOOD LATCH PANEL 58-59 CHEVY	CHEVY PU	2	A56	\$40.30	\$42.00
3306	112A	67 TRUNK LOCK ORIGINAL 64- 66 CHEVL63-65&68 GTO,64-66 MONTE,60-68 CHET	CAMARO	4	3-4	\$36.00	\$34.32
3311	1130F	55-59 VENT WINDOW HANDLE PR	CHEVY PU	3	A124	\$27.27	\$27.36
3306	1132	EXTERIOR DOOR HANDLE 47- 51PR	CHEVY PU	4	A32	\$105.44	\$105.96
3306	1133	EXTERIOR DOOR HANDLE 52-59 PR	CHEVY PU	2	A125	\$44.60	\$44.84
3306	1134	60-66 EXTERIOR DOOR HANDLE PR	CHEVY PU	2	C63	\$58.80	\$44.78
3314	1135	55-57 HOOD LATCH	CHEVY PU	7	A35	\$168.98	\$168.98
3311	1143M	FRNT DOOR GLASS CHANEL RUN LH 81-91	CHEVY PU	3	C13	\$18.57	\$19.20

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-10-11	CEVA	ORGIN	2017-10-12

PO#	ITEM	DESCRIPTION	VPART NO.	CHID OTY	LOCATION	EOD	EXT
PO#	IIEWI	DESCRIPTION	MAKE		LOCATION	FOB	COST
3316	1143P	FRONT INNER BELT RH 81-92	15569072	3	A125	\$18.54	\$18.84
3310	1145P	FRONT INNER BELT RH 81-92	CHEVY PU	<u> </u>	A125	\$18.54	\$18.84
3306	1146Н	69-72 DASH BEZEL		2	CUP4/	\$14.28	\$14.54
3300	114011	APPLIQUEWOODGRAIN	CHEVY PU		CUP4	\$14.26	\$14.34
3314	1153B	47-55 EXTERIOR MIRROR ARM		2	F174	\$17.80	\$17.80
3314	1155B	BLACK RH	CHEVY PU	2	F1/4	\$17.00	\$17.00
3311	1153I	60-66 EXTERIOR MIRROR ARM		1	F162	\$15.12	\$15.25
3311	11331	LHSTAINLESS	CHEVY PU	1	F 102	\$13.12	\$13.23
		70-81 CAMARO DAY / NIGHT					
3306	1154F	MIRROR72-92 CHEVY PU DAY /	CAMARO	6	F164	\$151.20	\$152.04
		NIGHT	CAMARO				
3311	1160S	67-72 BEDSIDE FOR STEPSIDE		1	S51	\$189.00	\$200.67
		LHSHORTBED	CHEVY PU				
3282	1170	TAILGATE 55-87 STEPSIDE W /			M91	\$366.45	\$690.95
		CHEVROLET	CHEVY PU			7000.00	+
3294	1190F	67-72 ANTENNA	CHEVY PU	2	B112	\$58.80	\$59.20
2202	10000	47-55 BRAKE OR CLUTCH			D102	Ф2.25	Ф2.20
3282	1220B	PEDAL PAD	CHEVY PU	_ 2	B102	\$3.36	\$3.38
2200	1220D	47-55 BRAKE OR CLUTCH			D102	Ф2.26	Ф2 20
3299	1220B	PEDAL PAD	CHEVY PU	_ 2	B102	\$3.36	\$3.38
2211	1001	CT TO CAR MOUNTE WITH DO	UNITED C677204	_	D02	Φ <b>2</b> 0.7.20	# <b>207</b> 00
3311	1221	67-72 CAB MOUNT KIT38 PCS	CHEVY PU	5	B92	\$205.30	\$205.80
3309	1400L	68-72 STEERING CLOUMN		1	A91	\$16.60	\$16.69
3309	1400L	CLAMP PLATE	CHEVELLE	<b>1</b>	A91	\$10.00	\$10.09
		68-72 WINDSHIELD GLASS	·				
3309	1400P	CLEARUPPER TINT STRIP / NO		1	1 N91/A	\$79.80	\$101.50
		ANTENNA COUPE	CHEVELLE				
3314	1402EWT	64-72 SEAT MOUNTING RAIL		3	A104	\$50.04	\$50.04
3317	170212771	4PCS SET* WTP *	CHEVELLE		AIVT	Ψ50.04	Ψ50.04
		WINDSHIELD WASHER BOTTLE					
3311	1425	BRACKET64 / 9 CHEVELLE / 67 /	CAMARO	2	2 F154	\$13.38	\$13.84
		9 CAMARO,64 / 9 NOVA	DACE:0				

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-10-11	CEVA	ORGIN	2017-10-12

PO#	ITEM	DESCRIPTION	VPART NO.	CHID OTV	LOCATION	FOB	EXT	
PO#	I I E IVI	DESCRIPTION	MAKE	SHIP QI I	LUCATION	гов	COST	
3316	1460D	REAR BUMPER 67PREMIUM	3895146	3	F134	\$387.06	\$404.85	
3310	14000	QUALITY	CHEVELLE	3	F134	\$367.00	\$404.63	
3306	1468F	64-66 HOOD BUMPER / 2PCS		30	C43	\$65.70	\$66.00	
3300	14001	SETGTO	CHEVELLE	30	C43	\$05.70	\$00.00	
3311	1472G	REAR OUTER WHEELHOUSE LH	9815031	1	G156	\$27.94	\$33.82	
3311	14/20	70-72	CHEVELLE	1	G130	\$27.54	φ33.62	
3311	1472H	REAR OUTER WHEELHOUSE RH			G178	\$62.80	\$74.38	
3311	14/211	66-67	CHEVELLE	2	G1/6	\$02.60	\$74.36	
3311	1472J	REAR OUTER WHEELHOUSE LH			G175	\$61.82	\$73.40	
3311	14/23	66-67	CHEVELLE	2	G1/5	\$01.62	\$73.40	
3306	1474A	70-72 QUARTER PANEL WO		1	R63	\$198.88	\$198.88	
3300	14/4A	LAMP HOLE RH	CHEVELLE	1	Kos	\$190.00	\$190.00	
3306	1474B	70-72 QUARTER PANEL WO		1	R63	\$197.92	\$197.92	
3300	14/40	LAMP HOLE LH	CHEVELLE	1	K03	\$197.92	\$197.92	
		66-67 WINDOW ASSEMBLY						
3314	1485K	VENT LHCHEVELLE / GTO	CHEVELLE	1	B104	\$188.95	\$188.95	
		CLEAR	CHEVELLE					
3306	1486	DOOR SKIN 70-72 RH	8809736		B124	\$128.66	\$140.66	
	1.00	Doord Similary 12 Inc.	CHEVELLE		D12.	Ψ120.00	Ψ110.00	
3306	1487	DOOR SKIN 70-72 LH	9867778	1	B124	\$64.21	\$70.22	
3300	1407	DOOK SIKII VO 72 EII	CHEVELLE		D124	ψ04.21	Ψ70.22	
3314	1488E	RADIATOR SUPPORT 70	3957351		F148	\$147.96	\$147.96	
3314	140012	KADIITOK SCIT OKT 70	CHEVELLE		1140	Ψ1+7.70	Ψ1+7.70	
3306	1489WWT	64-67 ROCKER PANEL INNER		1	E91	\$23.45	\$23.86	
3300	140211111	RH* WTP *	CHEVELLE		E	\$23.43	Ψ25.00	
3306	1489XWT	64-67 ROCKER PANEL INNER			E92	\$70.38	\$76.08	
3300	170/4 11 1	LH* WTP *	CHEVELLE		12/2	Ψ10.36	ψ/0.06	
3316	1492A	FRONT BUMPER FILLER 69	CHEVELLE	3	G91	\$80.91	\$85.68	
3311	1495Z	68-72 CLUTCH ROD BOOT	CHEVELLE	2	B44	\$10.08	\$10.08	

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-10-11	CEVA	ORGIN	2017-10-12

PO#	ITEM	DESCRIPTION	VPART NO.	SHIP OTY	LOCATION	FOB	EXT
10"	112.11	DESCRIPTION	MAKE	SIII QII		100	COST
3293	1508WT	RADIATOR SUPPORT 66-67* WTP		1	F125	\$141.78	\$150.29
3273	1300 11 1	*	GTO		F 123	ψ141.76	\$150.27
3293	1509FWT	68-69 FIREWALL BRACE PR*		1	D93	\$58.55	\$59.88
3293	13071 11 1	WTP *	GTO	1	D33	\$30.33	φ39.00
3309	1528	GRILLE 69 RH / LH SET	GTO	2	C56	\$171.50	\$173.54
3309	1529	FRONT VALANCE 69	GTO	2	F116	\$120.00	\$156.90
220.4	4505	60 72 D 4 TTTTT 1 4 14			F4.54	<b>#16.60</b>	Φ17.10
3304	1535	68-72 BATTERY TRAY	GTO	2	F154	\$16.68	\$17.12
		65 IGNITION OCTAGON62-65					
3309	158	GTO,65 MONTE / CHEVT / NOVA	CHEVELLE	4	1-5	\$17.28	\$20.88
		/ PU	CHEVELLE				
3314	1615D	FRONT BUMPER FILLER 68-72	3919083		E95	\$89.85	\$89.85
	10102	PLASTIC	NOVA		250	Ψ07.02	407.02
3311	1618	FENDER RH 62-65**	NOVA	3	D64	\$250.62	\$250.62
2211	1619	EENDED LIL CO (5**		1	D32	¢1.67.00	\$1.67.00
3311	1019	FENDER LH 62-65**	NOVA	2	D32	\$167.08	\$167.08
3296	1623A	FULL QUARTER PANEL RH 70-			J53	\$512.01	\$558.30
3270	1023/1	72**W / SAIL PANEL	NOVA		955	ψ312.01	ψ550.50
3296	1623B	FULL QUARTER PANEL LH 70-			J73	\$344.12	\$374.96
3270	10231	72**W / SAIL PANEL	NOVA		373	ψ344.12	Ψ374.70
3309	1623C	DOOR SKIN RH 68-72**		2	B123	\$127.48	\$138.86
3307	10230	NOVAVENTURA 2 71 / 72	NOVA		D123	Ψ127.40	Ψ130.00
3309	1623D	DOOR SKIN LH 68-72**		2	B124	\$128.22	\$138.48
3307	10231	NOVAVENTURA 2 71 / 72	NOVA		D144	Φ120.22	φ130.40
3309	1623E	DOOR HINGE ROLLER 68-72		3	B12	\$10.56	\$10.32
3307	102315	PAIRCAMARO 67-69	NOVA	3	D12	\$10.50	φ10.32
3309	1623G	QUARTER PANEL SKIN LH 68-69	NOVA	1	J44	\$94.63	\$106.78
			NOVA				

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-10-11	CEVA	ORGIN	2017-10-12

PO#	ITEM	DESCRIPTION	VPART NO.	SHID OTV	LOCATION	FOB	EXT
ro#	IIEM	DESCRIPTION	MAKE	Silir Q11	LOCATION	FOB	COST
3309	1623M	65-67 GAS CAP CHROME	NOVA	2	B83	\$15.58	\$15.64
3306	1635	FULL FLOOR PAN LH 68-74	NOVA	4	G171	\$113.04	\$123.72
3314	1636B	64-67 FLOOR TRANSMISSION COVERMANUAL	NOVA	2	F177	\$29.14	\$29.14
3314	1643C	68-72 HOOD LATCH ASSY	NOVA	2	A104	\$70.52	\$70.52
3309	1700C	FRONT BUMPER FILLER 64**	IMPALA	2	E103	\$83.98	\$87.62
3299	1700Ј	RADIATOR SUPPORT 64**	IMPALA	1	E106	\$76.15	\$81.95
3310	1701E	62 HOOD	IMPALA	2		\$520.00	\$520.00
3316	1702Z	62 FENDER LH	IMPALA	2	F72	\$398.50	\$415.70
3314	1705L	62 REAR BUMPER	IMPALA	2	F113	\$390.42	\$390.42
3314	1705M	65 FRONT BUMPER	IMPALA	1	F93	\$194.81	\$194.81
3314	1710G	63 PARKING LAMP LENS AMBER PR	IMPALA	2	A12	\$24.54	\$24.54
3276	1714G	65 TAIL / BACK UP LAMP BEZEL RH	IMPALA	3	A12	\$22.68	\$25.41
3304	1735R	64 TRUNK FLOOR DROP OFF RH** HAVE 1 UNDER RWT **	IMPALA	1	A82	\$20.00	\$17.16
3314	1737RWT	65-66 TRUNK FLOOR DROP OFF RH*WTP*	IMPALA	2	E112	\$52.74	\$52.74
3309	1748553	DOOR LATCH RH 70-81	CAMARO	1	C73	\$26.66	\$26.81

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-10-11	CEVA	ORGIN	2017-10-12

PO#	ITEM	DESCRIPTION	VPART NO. MAKE	SHIP QTY	LOCATION	FOB	EXT COST
3309	1748554	DOOR LATCH LH 70-81	CAMARO	2	С73	\$54.68	\$54.98
3306	1783RWT	65-70 FULL FLOOR PAN RH*WTP*	IMPALA	1	G172	\$65.81	\$76.42
3309	1860	70 FRONT BUMPER	CUTLASS		F102	\$393.70	\$412.44
3305	3630FWT	65-66 FENDER APRON FRONT LEFT LHWTP	MUSTANG	2	G104	\$33.42	\$36.90
3311	3630J	OUTER SHOCK TOWER BRACKET RH,67-70	MUSTANG	4	A103	\$78.92	\$81.00
3311	3630K	OUTER SHOCK TOWER BRACKET LH,67-70	MUSTANG	4	A103	\$79.60	\$81.68
3311	3630W	65-70 FRAME RAIL FRONT RHFITS COUGAR	MUSTANG	3	C126	\$194.58	\$203.19
3311	3631B	1965-73 LEAF SPRING SHACKLE KITPER 1 SIDE	MUSTANG	20	A103	\$134.20	\$136.00
3314	3631MWT	OUTER WHEEL HOUSE RH 65- 66* WELD THROUGH PRIMER *	MUSTANG	5	G168	\$128.50	\$128.50
3314	3631NWT	OUTER WHEEL HOUSE LH 65- 66* WELD THROUGH PRIMER *	MUSTANG	3	G168	\$66.72	\$66.72
3306	3631ZWT	65-66 FIRE WALL CPE / FBTRIM FOR CONVT -WELD THROUGH PRIMER	MUSTANG	3	G162	\$352.17	\$378.84
3306	3635R	67-68 MONTE CARLO BAR CURVED CHROME	MUSTANG	3	A95	\$57.81	\$66.27
3275	3639	REAR BUMPER 64-66	C5ZZ17906A MUSTANG	2	F103	\$121.80	\$125.24
3314	3639B	64-66 REAR BUMPER GUARD BRACKET PR	MUSTANG	2	G92	\$17.52	\$17.52
3305	3641A	DOOR SKIN RH 69-70	MUSTANG	3	C112	\$177.09	\$185.79

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-10-11	CEVA	ORGIN	2017-10-12

DO#	ITEM	DESCRIPTION	VPART NO.	CHID OTY	LOCATION	FOB	EXT
PO#	HEN	DESCRIPTION	MAKE	SHIPQIY	LOCATION	FUB	COST
3305	3641B	DOOR SKIN LH 69-70	MUSTANG	2	C112	\$114.82	\$120.62
2200	3642D	VALANCE REAR 65-66 W / LIGHT	SFA03-2	_	E94	00.00	¢00.40
3309	3042D	HOLE	MUSTANG	5	F84	\$90.90	\$99.40
3314	3643NC	70 TAIL LAMP HOUSING TO			A37	\$28.74	\$28.74
3314	3043110	BODY SEALRH=LH	MUSTANG		AST	Ψ20.74	Ψ20.74
3314	3643WA	69 TAIL LAMP LENSALL BODY		4	A45	\$103.24	\$103.24
3314	30431111	STYLE	MUSTANG	ļ ·	7140	Ψ103.24	Ψ103.24
3311	3643WWT	69-70 TAIL LAMP MOUNTING		_ 2	E112	\$39.88	\$43.64
5511	201211111	LH* WTP *	MUSTANG		2112	Ψ37.00	Ψ 15.0 1
3311	3643XJWT	65-66 ROOF DRIP RAIL FB PR	MUSTANG	2	A121	\$177.28	\$179.54
3316	3647YZWT	65-66 DECK LID FILLER PANEL		3	E105	\$120.00	\$157.74
3310	304/12//1	FB*WELD THROUGH PRIMER *	MUSTANG	3	E103	\$120.00	Φ137.74
3306	3648YWT	65-66 PILLAR PANEL RH* WTP *	MUSTANG	3	C124	\$57.69	\$59.82
3306	3648ZWT	65-66 PILLAR PANEL LH* WTP *	MUSTANG	3	C124	\$57.75	\$59.82
3314	3649E	TRUNK FLOOR RH 65-70	MUSTANG	5	G116	\$74.60	\$74.60
3314	3649F	TRUNK FLOOR LH 65-70	MUSTANG	5	G116	\$67.25	\$67.25
		65-68 SEAT SUPPORT	110011110				
3314	3649PWT	PLATFORMRH *WTP *	MUSTANG	2	G95	\$49.94	\$49.94
		65-68 SEAT SUPPORT			~~-		*
3314	3649QWT	PLATFORMLH *WTP *	MUSTANG	2	G95	\$49.16	\$49.16
		71-73 REAR INNER DECK LID,					
3310	3649VB	HINGES & TORTION RODS		_ 2		\$318.00	\$318.00
		INCLUDED	MUSTANG				
3314	3652WT	65-66 TORQUE BOX RH CONVT		2	A97	\$73.36	\$73.36
JJ1 <del>4</del>	3032 11 1	*WTP*67-68 AS WELL	MUSTANG		AJI	φ13.30	φ15.30

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-10-11	CEVA	ORGIN	2017-10-12

PO#	ITEM	DESCRIPTION	VPART NO. MAKE	SHIP QTY	LOCATION	FOB	EXT COST
3306	4001	57 PANEL LOWE FILLER ASSY	CHEVROLET	2	G101	\$108.60	\$130.46
3306	4002	55 VALANCE PANEL 3 PC SET	CHEVROLET	1	F168	\$59.27	\$62.94
3306	4004	55-57 WIPER ARM LH	CHEVROLET	1	F176	\$5.88	\$5.91
3311	4056	56 REAR BUMPER 1 PIECE STYLE	CHEVROLET	1	F124	\$210.00	\$214.50
3289	6030	70-74 BATTERY TRAY "E" BODY	CHALLENGER	8	F154	\$62.72	\$63.44
3311	6068AWT	70-74 REAR FRAME RAIL LH* WTP *	CHGRP01L CHALLENGER	2	F141	\$290.92	\$305.30
3311	6068WT	70-74 REAR FRAME RAIL RH* WTP *	CHGRP01R CHALLENGER	2	F141	\$292.62	\$307.00
3309	6082	70 TRUNK FLOOR PANEL*DIFFERENT SHOCK	CHGTF01	3	J81	\$385.56	\$412.92
		ACCESS HOLES 71-74	CHALLENGER		0 001	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
3311	6084	70-74 R.VALANCE W / DUAL	CHGVR01	2	F34	\$135.60	\$143.98
3311	0004	EXHAUST HOLE	CHALLENGER		154	Ψ133.00	Ψ1+3.76
3309	6086	70-74 WHEELHOUSE OUTER	CHGWH02R	1	G178	\$29.60	\$34.11
		PANEL RH	CHALLENGER		92.0	7-7.00	7
3309	6086A	70-74 WHEELHOUSE OUTER	CHGWH02L	2	G165	\$59.84	\$68.84
		PANEL LH	CHALLENGER				
3294	CTL6066SR	60-66 LED TAILLAMP,STAINLESS HOUSIN	CHEWA DI	2		\$47.36	\$47.38
		,	CHEVY PU				
3316	CTL6701LEI	0 67 LED TAIL LAMP ASSYEACH	CHEVELLE	2		\$46.64	\$47.00
3311	EM1732	64 HOOD EMBLEM. INSERT		1		\$16.80	\$16.84
3311	EN11/32	ONLY	IMPALA	1		\$10.80	\$10.84
3309	EM3601	65-66 FENDER EMBLEM		6		\$20.46	\$20.64
3307	22/12/01	LHRUNNING HORSE	MUSTANG			Ψ20.40	Ψ20.04

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-10-11	CEVA	ORGIN	2017-10-12

PO#	ITEM	DESCRIPTION	VPART NO.	CHID OTY	LOCATION	FOB	EXT
PO#	IIEM	DESCRIPTION	MAKE	SHIPQIY	LOCATION	гов	COST
3309	EM3602	67-68 FENDER EMBLEM RH"289"		2		\$10.40	\$10.46
3307	EN13002	W / RUNNING HORSE	MUSTANG			ψ10. <del>4</del> 0	ψ10. <del>4</del> 0
3309	EM3603	67-68 FENDER EMBLEM LH"289"		_ 2		\$10.40	\$10.46
	Zivicooc	W / RUNNING HORSE	MUSTANG			Ψ10.10	Ψ10.10
3309	EM3604	68 FENDER EMBLEM RH"302" W				\$12.50	\$12.56
		/ RUNNING HORSE	MUSTANG			7	
3309	EM3605	68 FENDER EMBLEM LH"302" W		_ 2		\$10.40	\$10.46
		/ RUNNING HORSE	MUSTANG			7	
3306	EM3657	65-72 STICK ON LETTER		_ 2		\$16.70	\$16.76
		SET"MUSTANG" 7PCS	MUSTANG			,	
3314	EM4755	71-72 "SS" REAR BUMPER		_ 2		\$48.06	\$48.06
		EMBLEM	CHEVELLE				
3314	G1130	67-72 DOOR GLASS RH=LH	TP	_ 2	N131 / G2	\$37.68	\$37.68
		CLEAR	CHEVY PU				
3285	G40	57 FUEL GAUGE	CHEVROLET	1	CUP3	\$50.40	\$50.43
2206	17.550	67-69 WOOD WHEEL MOUNTING		2	1.5	0.47.16	ф.47.0 <b>7</b> .
3306	K579	KIT	CAMARO	3	1A7	\$47.16	\$47.25
		62-66 QUARTER LIGHT ASSY.67					
3300	L1700	CAMARO DELUXE INTERIOR 2	CANTARO	2	C53	\$33.60	\$35.36
		PER CAR	CAMARO				
3306	L3661B	69 FRONT / REAR SIDE MARKER		_ 2	A13	\$18.30	\$18.46
	LCOOID	BEZEL PR	MUSTANG		1110	Ψ10.50	Ψ10.10
3306	L4600	55 BACK UP LAMP LENEA	CHEVROLET	4	B14	\$7.44	\$15.12
		64-66 WINDSHIELD WIPER	CHEVROLLI				
3311	LH41	SWITCH2 SPEED 63 / 64 NOVA.	GTO	1	B11	\$27.30	\$27.31
		67-68 WINDSHIELD WIPER		+			
3295	LH47	SWITCH 2SPD	CAMARO	1	B11	\$18.48	\$18.50
		69-70 PARKING LAMP	<u> </u>	1			
3303	LP13B	ASSEMBLY LHCLEAR	CHEVY PU	_ 2	C83	\$63.00	\$63.00
			DAGE 16	_			

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-10-11	CEVA	ORGIN	2017-10-12

PO#	ITEM	DESCRIPTION -	VPART NO. MAKE	SHIP QTY	LOCATION	FOB	EXT COST
		67-72 TAIL LAMP BLACK	Wiriti				
3306	LP31	STEPSIDE	CHEVY PU	4	A15	\$100.80	\$101.36
220.6	1 D25	67-72 BACKUP LAMP ASSY				ф <b>25.2</b> 0	<b>#27.24</b>
3306	LP35	FLEETSIDE RH	CHEVY PU	2	A15	\$25.20	\$25.34
3306	LP36	67-72 BACKUP LAMP ASSY		2	A15	\$25.20	\$25.34
3300	LF30	FLEETSIDE LH	CHEVY PU	2	A15	\$23.20	\$23.34
3297	LP48	69-72 TAIL LAMP BEZEL		5	A64	\$46.20	\$46.65
3271	L1 40	FLEETSIDE LH	CHEVY PU	3	AUT	Φ+0.20	Ψ+0.03
3314	LP53	60-72 DOME LAMP ASSY WHITE		6	A15	\$47.88	\$48.30
3314	LI 55	BASE	CHEVY PU	•	AIS	Ψ+7.00	Ψ+0.50
		OUTER MIRROR ROND BOWTIE	3909197				
3311	M1032	67 CAMARO66-72 NOVA,66-67	CAMARO	20	F163	\$206.00	\$208.60
		CHEVELLE,CHEVY II	CAMARO				
2211	M1024	OUTER DOOR MIRRORCHEVELLE / MONTE	9717592/3	20	F163	¢257.20	¢2<0.00
3311	M1034	CARLO 70-72 NOTE	CHEVELLE	20	F 103	\$257.20	\$260.00
2207	N#1020E	67 TAIL LAMP LENS RALLY			. 15	<b>#10.04</b>	¢10.10
3297	M1039E	SPORT	CAMARO	2	A17	\$10.04	\$10.18
2200	M1167	GRILLE SIDE MLDG LH 83-870N	15593227	1	4.52	¢	¢c.c7
3309	M1167	FENDER	CHEVY PU	1	A52	\$6.57	\$6.67
3309	M1194	BED LO MLG RR RH 73-80 6.5 F	475582	2	A71	¢10.20	\$11.02
3309	W11194	BED LO MLG RR RH /3-80 6.5 F	CHEVY PU		A/I	\$10.28	\$11.02
3309	M1195	BED LO MLG RR LH 73-80 6.5'	475581	2	A71	\$10.46	\$11.00
3309	W11193	BED LO MLG RR LH 75-80 0.3	CHEVY PU	2	A/I	\$10.40	\$11.00
3309	M1262	UPPER TAILGATE MOLDING LH		_ 2	A143	\$8.44	\$8.58
3309	111202	69-72	CHEVY PU	2	A143	<b>9</b> 6.44	φο.3ο
3309	M1280	69-70 WINDSHIELD MOLDING		3	B114	\$94.50	\$100.86
3307	1411200	SET	CHEVY PU	,	7117	Ψ/4.30	ψ100.00
3309	M1282	67-72 REAR WINDSHIELD		4	B114	\$126.00	\$135.60
3307	1111202	MOLDING SET	CHEVY PU	<b>_</b>	D117	Ψ120.00	Ψ155.00
		69 GRILL OUTER			2B12		
3311	M1362G	MOLDING(BETWEEN	CHEVELLE	4		\$20.44	\$20.40
		HEADLAMP)	CHEVELLE				

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-10-11	CEVA	ORGIN	2017-10-12

PO#	ITEM	DESCRIPTION	VPART NO. MAKE	SHIP QTY	LOCATION	FOB	EXT COST
3311	M1383Q	68-72 REAR CORNER EXT. MOLDINGPR	EL CAMINO	2	C73	\$24.04	\$24.22
3311	M1390WB	1964-67 DOOR HANDLE KIT PRW / PUSH BUTTONS	CHEVELLE	1	C62	\$15.05	\$14.99
3306	M1392R	64-72 WINDOW CRANK GASKET 4PCS / KIT	CHEVELLE	10	1C10	\$18.30	\$16.80
3309	M1460A	68-72 FRONT HEADLINER MOLDING	CHEVELLE	3	A66	\$41.61	\$34.20
3309	M1460D	70-72 HEADLINER MOLDING SIDE PR	CHEVELLE	3	A66	\$82.59	\$82.98
3309	M1460E	64-67 FRONT HEADLINER MOLDING H / TCHEVELLE / EL CAMINO	CHEVELLE	2	A66	\$7.70	\$8.28
3309	M1501	DRIP RAIL MOLDING SET 68-69 6PC GTO	GTO	3	A65	\$126.90	\$127.53
3309	M1512	ROCKER MOLDING RH 1970-72 GTO	GTO	3	B52	\$72.60	\$75.15
3309	M1513	ROCKER MOLDING LH 1970-72 GTO	GTO	3	B52	\$72.93	\$75.27
3309	M1514	66-67 ROCKER MOLDING RH66 GTO, 67 LEMANS	GTO	2	B52	\$54.44	\$56.64
3309	M1515	66-67 ROCKER MOLDING LH66 GTO, 67 LEMANS	GTO	3	B52	\$81.21	\$84.63
3306	M1561	66-67 WHEEL OPENING MOLDING SET	GTO	1	A67	\$70.97	\$72.59
3306	M1562	68-69 WHEEL OPENING MOLDING SET	GTO	2	A67	\$140.84	\$145.38
3306	M1563	70-72 WHEEL OPENING MOLDING SET	GTO	1	A67	\$70.27	\$72.19
3316	M1611	GRILLE 1967	NOVA	1	C76	\$54.11	\$55.61

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-10-11	CEVA	ORGIN	2017-10-12

PO#	ITEM	DESCRIPTION	VPART NO. MAKE	SHIP QTY	LOCATION	FOB	EXT COST
3306	M1673	68-74 ROCKER PANEL MOLDING PRW / O CLIPS	NOVA	3	B62	\$153.15	\$154.83
3306	M1675	66 VALANCE PANEL MOLDING	NOVA	2	B62	\$49.84	\$50.28
3306	M1721J	57-58 BATTERY HOLD DOWN	CHEVROLET	2	F156	\$8.40	\$9.02
3309	M1722	BATTERY CLAMP (HOLD DOWN) 1962-63	IMPALA	- 5	F152	\$16.40	\$16.95
3309	M1723	64 BATTERY CLAMP HOLDDOWN 64-5 CHEVCHEVELLE / EL CAMINO	IMPALA	3	F152	\$10.08	\$10.26
3309	M1724W	LOWER GRILL MOLDING 64	IMPALA	2	B53	\$45.96	\$46.76
3309	M1727F	63-64 VENT WINDOW STOPPER2PCS / CONVT	IMPALA	2	A116	\$17.44	\$17.44
3306	M1771	DOOR LOCK KNOB CHROME PR61-66 GM, 64-66 GTO	IMPALA	20	C73	\$22.20	\$22.00
3314	M3507	FOLD DOWN SEAT MOULDING 65-68 F / B14PCS SET*W / O RECESSED STRIKE AREA*	MUSTANG	2	A34	\$208.26	\$208.26
3309	M3514	QUARTER PANEL ORNAMENT 66 PAIR	C6ZZ65290A76/7A MUSTANG	2	В33	\$43.06	\$43.38
3309	M3516	HEATER BOX 65-66 W / GASKETS & CLIPSWITH RESISTOR CUT-OUT**	MUSTANG	- 1	C53	\$77.90	\$81.49
3309	M3570A	FRONT BUMPER TO FENDER BRACKET RH64-66**	C5ZZ 17A869B MUSTANG	4	C43	\$4.40	\$4.40
3309	M3570B	FRONT BUMPER TO FENDER BRACKET LH64-66**	C5ZZ 17A870B MUSTANG	3	C43	\$3.30	\$3.30
3295	M3643Q	70 FENDER EXTENSION MOLDING LH	MUSTANG	3	B41	\$173.10	\$173.97
3309	M3651	SCUFF PLATE 65-68 CONV	C5ZZ 7613208C MUSTANG	10	A43	\$55.50	\$58.80

VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-10-11	CEVA	ORGIN	2017-10-12

PO# ITEM	DESCRIPTION	VPART NO.	CHID OTX	I OCATION	EOD	EXT	
	HEM	DESCRIPTION	MAKE	SHIPQTY	LOCATION	FOB	COST
2200	3309 <b>M3652</b>	COLUEE DI ATTE CO 70	C9ZZ 6513208A	15	A54	¢07.15	¢01.90
3309 <b>N1303</b> 2	SCUFF PLATE 69-70	MUSTANG		A54	\$87.15	\$91.80	
2200	3309 <b>M3653</b>	SCUFF PLATE 71-73	D4DZ 6213208A	5	B31	\$25.50	¢27.45
3309			MUSTANG	3	B31	\$35.50	\$37.45
3314	SW29	47-66 HORN CONTACT PIN / SWITCH		_ 2	C42	\$3.34	\$3.34
3314	3 11 29		CHEVY PU				
3316	Т04	FUEL SENDING UNIT 69	MUSTANG	5	B82	\$57.90	\$58.60
3309	T200	66-67 FUEL SENDING UNIT 3 /		1	B85	\$13.44	\$13.79
3309	309 1200	8"CHARGER / BELEVDERE	MOPAR	ı	D03	\$15.44	\$13.79 
3316	3316 <b>T23</b>	20 GALLON GALVANIZED TANK 69W / O DRAIN PLUG		3	P53	\$127.53	\$150.33
3310	123		MUSTANG		1 33	Ψ121.33	φ150.55
3316	T24	1970 22 GALLON GALVANIZED TANKW / O DRAIN PLUG		2	P42	\$77.46	\$94.98
3310	127		MUSTANG		1 72	Ψ77.40	Ψ/Τ./Ο
3306	T43	GAS CAP "SS" 67-68	UNITED	4	B82	\$72.48	\$72.60
3300	3300 143		CAMARO		102	\$72.40	Ψ12.00
3306	T45	GAS CAP 67-68 STD	CAMARO	2	B82	\$12.78	\$13.04
			CAMAKO				
3311	T61	FUEL SENDING UNIT 60-66	CHEVY PU	2	B82	\$24.16	\$24.16
3311	T62	FUEL SENDING UNIT 69-72	CHEVY PU	3	B82	\$45.36	\$46.14
2200	3309 <b>T79</b>	71 GAS TANK W / NECK, 3 VENT PIPE15" NECK		_ 2	P43	\$93.64	\$113.54
3309			GTO		F43	\$93.04	φ115.54 
3316	X3674	64-66 REAR WINDOW FB TINTED	MUSTANG	1	J162	\$136.36	\$144.45
	•	-		-	TOTAL	\$32828.81	\$34801