VENDOR	SHIP DATE	SHIP VIA	F.O.B	ONSHIP ETA
DII	2017-08-15	CEVA	ORGIN	2017-08-16

## **CONTAINER 70816 DETAILS**

PO# ITEM	ITEM	DESCRIPTION	VPART NO.	SHID OTV	LOCATION	FOB	EXT COST
	11121/1	DESCRII IION	MAKE	SHIP QIY			
3287	1104B	ROCKER PANEL LH 60-66	CHEVY PU	1	C124	\$18.76	\$20.52
3293 <b>1104DA</b>	73-87 ROCKER PANEL RH OE	TP	3	E101	\$27.90	\$44.64	
	1104DA	STYLE	CHEVY PU	3	E101	\$37.89	\$44.64
3293	1104E	ROCKER PANEL RH 47-55		1	E103	\$21.53	\$23.12
3293	5295 1104E	W/RUNNING NOA	CHEVY PU	1	E103	φ21.33	\$43.12
3293	3293 <b>1104F</b>	ROCKER PANEL LH 47-55		_ 2	E103	\$43.78	\$46.96
3293	11041	W/RUNNING BOA	CHEVY PU	2	E103	Ф43./8	\$40.90
3293	3293 <b>1104G</b>	INNER DOOR STEP WITH		_ 2	C91	\$79.20	\$90.30
3293 11 <b>04G</b>	ROCKER RH	CHEVY PU		(91	\$19.20	\$90.30	
3203	3293 1104Н	INNER DOOR STEP WITH			С92	\$119.88	\$136.53
3273		ROCKER LH	CHEVY PU	3			
3289	1104K	55-66 SHORT BED STEP RH	CHEVY PU	4	C124	\$144.00	\$169.08
3289	1104L	55-66 SHORT BED STEP LH	CHEVY PU	3	C124	\$108.42	\$122.07
3293	1104M	68-72 VENT WINDOW ASSY RH	CHEVY PU	3	B122	\$388.71	\$394.11
3293	1104S	55-59 ROCKER PANEL LH	CHEVY PU	2	E101	\$31.92	\$32.52
3288	1104U	55-59 STEP HANGER LH	CHEVY PU	2	B22	\$23.46	\$21.69
			CHEVITO				
3289	1106AB	47-54 CAB FLOOR PAN RH	CHEVY PU	1	D105	\$32.83	\$41.02
3289	1106AC	47-54 CAB FLOOR PAN LH	CHEVY PU	3	D105	\$98.43	\$133.14
3293	1106AY	67-72 CAB FLOOR LH	CHEVY PU	2	B101	\$33.60	\$51.39
3293 <b>1106BA</b>	110CD 4	60-66 OUTER CAB FLOOR/INNER			C21	¢100.24	¢115.52
	ROCKER	CHEVY PU	3	C31	\$108.24	\$115.53	

PAGE:6