GOLDEN LEAF AUTOMOTIVE

GOLDEN LEAF AUTOMOTIVE

170 ZENWAY BLVD UNIT#2 WOODBRIDGE, ONTARIO L4H 2Y7 TELEPHONE 905/850-3433

 $\label{thm:corn} \textbf{VENDOR: } \textbf{DYNACORN INTERNATIONAL INC.}$

4030 VIA PESCADOR CAMARILLO CA 93012 PERMIT: 805/987-8818

PURCHASE ORDER 3335

PURCHASE ORDER DATE 2017-11-13

PAGE: 4

SHIP TO: GOLDEN LEAF AUTOMOTIVE 170 ZENWAY BLVD UNIT#2 WOODBRIDGE, ONTARIO L4H 2Y7

*** PURCHASE ORDER ***

VENDOR		ENDOR FAX NO	VENDOR TELEPHONE NO	SHIP VIA	F.O.B	TERMS
DII	80:	5/388-0786 SALES	805/987-8818 REMARKS	CEVA FREIGHT	TAX	120
BUYER	C	ONFIRMING TO				
					N	
QTY.ORD	QTY.OPEN	YOUR ITEM #	ITEM DESCRIPTION		UNIT PRICE EXT DDIA	EVE DDIGE
		OUR ITEM#	ITEM DESCRIPTION		REQ.DATE	EXT.PRICE
10	10		ROCKER PANEL LH 67-72		\$ 9.16	\$ 91.60
		1104D			2017-11-13	
2	2	TP	-73-87 ROCKER PANEL RH OE STYLE		\$ 12.63	\$ 25.26
		1104DA			2017-11-13	
2	2	TP	73-87 ROCKER PANEL LH OE STYLE		\$ 11.52	\$ 23.04
		1104DB			2017-11-13	
1	1		│ ─DOOR SKIN, PARTIAL LOWER LH 67-72	O"	\$ 9.41	\$ 9.41
		1101Z	DOOK SKIN, I AKTIAL LOWER LIT 07-72)		2017-11-13	Ψ 7.41
10	10		67-72 EXT. DOOR HANDLEPR		\$ 22.31	\$ 223.10
		1134A			2017-11-13	
1	1		67-72 REAR ROLL PAN FOR FLEETSIDEW / LICENSE BOX(NO LICENSE LAMP HOLE)		\$ 63.00	\$ 63.00
		1159B			2017-11-13	
3	3		REAR BUMPER BRACKET 67-72		\$ 25.93	\$ 77.79
		1109K			2017-11-13	
3	3		REAR LICENSE PLATE BRACKET 60-66		\$ 13.37	\$ 40.11
		1109Q	ALL IN EIGH ISE TEITE BRITEINET 60 00		2017-11-13	ψ 13.11
3	3		73-80 BATTERY TRAY		\$ 4.90	\$ 14.70
		1100Q			2017-11-13	¥ 170
1	1		 -BATTERY TRY ASSEMBLY 67-72 W / AG		\$ 19.51	\$ 19.51
		1100G			2017-11-13	
3	3		 - 47-54 COWL OUTER LOWER PANEL LH	* NON WTP *	\$ 23.67	\$ 71.01
		1106DAWT			2017-11-13	
						CONTINUE

VENDOR ORIGINAL